



**Countries:** CANADA, UNITED STATES, MEXICO  
**Availability:** ISIS, NotSIR  
**Major System:** COOLING  
**Current Language:** English  
**Other Languages:** NONE  
**Viewed:** 162

**Document ID:** IK0900143  
**Revision:** 0  
**Created:** 6/1/2021  
**Last Modified:** 8/13/2021  
**Author:** Allan Hertko

[Less Info](#)

Hide Details

Coding Information

<b>Copy Link</b> 	<b>Copy Relative Link</b> 	<b>Bookmark</b>  <a href="#">View My Bookmarks</a>	<b>Add to Favorites</b> 	<b>Print</b> 	<b>Provide Feedback</b> 	<b>Helpful</b>  3	<b>Not Helpful</b>  1
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	-------------------------	-----------------------------

**Title:** CV Heater Core Outlet Tube

**Applies To:** CV

## CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

08/10/2021 - Initial Article Release

## DESCRIPTION

A coolant leak can develop from a cracked heater core outlet tube along the lower engine bracket weld. A redesigned tube, bracket and clamp has been released to resolve this concern.

## SYMPTOM(s)

Coolant leak from front or passenger side of vehicle.

### Diagnostic Trouble Code(s) & Dashboard Indicator Light(s):

DTC/Light	Description
N/A	N/A

## SPECIAL TOOL(s) / SOFTWARE

Tool Description	Tool Number	Comments	Instructions
Coolant Recovery Tool	KL5007NAV-U		

---

## **SERVICE PARTS INFORMATION**

Kit Description	Part Number	Quantity Required	Notes
Pipe, Heater, Return Aluminum	2523133C1	1	
Support, Lower, Heater Return Non-AC	4282049C1	1	
Clamp 5/8 Cushioned	7095515C1	1	
Bolt, Flange Head M8 x 25	31055R1	1	
Nut, Hexagon Flange	40050R1	1	

---

## **DIAGNOSTIC STEP(s)**

Refer to [Cooling System Leak Test](#) per (2018-2020 International CV Technician Manual (Service and Diagnostic) 0001111853.


Yes, coolant is leaking from the heater outlet pipe, proceed with article.

No, refer to [Engine Cooling Operational Checkout Procedure](#) to find the source of the coolant leak.

---

## **REPAIR STEP(s)**

### **Current Welded Design**



Step 1: Open hood assembly.

Step 2: Drain cooling system.

Step 3: Remove right front inner fender.


Step 4: Remove intake air box top and lower box.

Step 5: Unlatch the heater hose from the outlet tube.

Step 6: Remove the lower hose and clamp.

Step 7: Remove both bolts and tube from engine compartment. Do not discard bolts save for reuse.

### **Updated Non-Welded Clamp Design**



Step 8: Install support (4282049C1) into the original bracket location. Torque support bolt to (62-84 ft-lb) or (85-115 Nm).

Step 9: Position outlet heater tube (2523133C1) into the engine compartment.

Step 10: Install upper outlet heater tube bolt and lower clamp, bolt and nut until the tube is properly positioned, (7095515C1, 31055R1, 40050R1).

Step 11: Torque lower clamp bolt and nut to (20-26 ft-lb) or (27.8-34.8 Nm).

Step 12: Torque upper bracket bolt to (10-13 ft-lb) or (14.1-17.6 Nm).

Step 13: Reinstall heater hoses and clamps.

Step 14: Vacuum test and refill cooling system. If no leaks are found proceed with the final steps.

Step 15: Reinstall inner fender, lower and top air intake box components.

Step 16: Close hood and road-test vehicle to recheck engine operation.

---

## **WARRANTY INFORMATION**

### **Warranty Claim Coding:**

<b>SRT:</b>	CV12-3761A
<b>Noun:</b>	Cooling System

[Hide Details](#)

#### Feedback Information

Viewed: 161

Helpful: 3

Not Helpful: 1

No Feedback Found