

Technical Service Bulletin

94 Tail lamp warning, DTC B16D4F4, B16D5F4, B16D6F4, B16D7F4 is stored - Repair Authorization

94 21 46 2064418/1 September 7, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2019 - 2020	All	Not Applicable

Condition

Customer states:

• A turn signal or tail lamp warning displayed in the instrument cluster however, the lamps work normally.

Workshop findings:

One or more of the following DTCs may be stored in the comfort control module, J393 (address word 0046):

- DTC B16D4F4 (left tail lamp 1 Turn signal light defective).
- DTC B16D5F4 (left tail lamp 2 Turn signal light).
- DTC B16D6F4 (Right rear tail lamp 1 Turn signal).
- DTC B16D7F4 (Right rear tail lamp 2 Turn signal light defective).

Technical Background

Various parts have been replaced under warranty for the condition noted above, but no issues were identified with these parts. In an effort to gain information on the DTC codes for the vehicles listed above, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.

Production Solution

No changes to production have been made, as no issue has been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

- 1. Verify the condition.
- 2. Fill out the attached questionnaire



Technical Service Bulletin

3. If the vehicle is within the New Vehicle Limited Warranty, contact a TAC consultant before proceeding. Please attach the completed questionnaire and diagnostic log to the TAC ticket/TAC Web Ticket.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2064418) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.