



Service Update

SU2103 Shaw J1939 DEF Sensor Troubleshooting Guide

Models Affected: Vision (BBCV), All American, and TX4 (T3FE, T3RE), with EPA/CARB certified on highway Cummins® Diesel Engine Features Built After 01/18/2016

Subject: The intent of Service Update SU2103 is to announce a “New Shaw Development® Technical Bulletin”. The Technical Bulletin is intended to guide Shaw Development® customers in troubleshooting fault codes related to the DEF tank assembly on Cummins® engine equipment. This document is intended to be a “living document”, and the details and processes within can/will change as system designs evolve, or other new information comes to light. Access to this Shaw Development® Technical Bulletin is also available on the Blue Bird Vantage website noted below.

WARNING:
Always follow all Federal, State, Local and Shop safety standards and use proper safety equipment, and thoroughly read and understand all instructions before performing these procedures.
Park bus on level surface, apply parking brake, turn off ignition key, and chock wheels.

Information:
Shaw Development® manufactures and supplies the diesel exhaust fluid (DEF) tank assemblies installed on Blue Bird buses powered with Cummins® Diesel engines. Technical Bulletin Document No: 0000297252 (attached) is intended to supplement existing Shaw Development® service documents that are currently available. As noted this document is intended to be a “living document”, therefore to ensure you always have the latest revision it is highly recommended that the document be downloaded from the Blue Bird Vantage website by clicking here. <https://vantage.blue-bird.com/Portal/supplier-documentation-P-and-S.aspx>

Shaw Development® Bulletin Tools And Equipment:

Item Number	Part Number	Description	Quantity
1	BB# 10058812	Shaw Scan Gauge diagnostic tool	1
2	Cummins®	Cummins ECM diagnostics application (Insite)	1
3	Cummins®/Industry Suppliers	RP1210 Communication Adapter (Inline/DPA5/Nexiq)	1
4	Cummins®	Refractometer calibrated for measuring DEF	1
5	Industry Suppliers	Digital Multimeter	1
6	Industry Suppliers	Temperature measurement device	1
7	Industry Suppliers	Infrared temperature measurement device	1
8	Cummins® QuickServe®	Cummins® field support portal for service information	1

DIGITAL SENSOR FIELD TROUBLESHOOTING GUIDE

DOCUMENT NO: 0000297252

Version: B

Status: Approved

VERSION HISTORY

Version	Implemented By	Revision Date	Reason
A	Christian Braun	1/31/2021	Initial draft
B	Christian Braun	2/16/2021	Removed watermark

TABLE OF CONTENTS

1	INTRODUCTION	3
1.1	Purpose of Technical Bulletin	3
1.2	Applicable Part Numbers, Assemblies and/or Applications.....	3
1.3	Required Tools and Equipment	3
1.4	Definitions/Acronyms.....	4
2	HEADER/SENSOR GENERATION IDENTIFICATION.....	5
2.1	Gen4 Header With Analog Sensor	5
2.2	Gen4 Header with Digital Sensor	7
2.3	Gen5 Header with Analog Sensor	9
2.4	Gen5 Header with Digital Sensor	11
2.5	Gen6 and Gen7 Header (MSU Sensor)	13
3	FAULT CODES	15
3.1	Discussion.....	15
3.2	DEF System Fault Code Details	15
4	PROCEDURES.....	18
4.1	Read ECM Fault Codes	18
4.2	Obtaining a Cummins Insite Job Image.....	18

4.3	Abnormal Update Rate Fault Codes (3868, 4572, 4677)	19
4.3.1	Discussion	19
4.3.2	Troubleshooting Procedure	19
4.4	Level Sensor Abnormal Rate of Change (4769)	20
4.4.1	Discussion	20
4.4.2	Troubleshooting Procedure	20
4.5	Quality Sensor Abnormal Rate of Change (4277)	21
4.5.1	Discussion	21
4.5.2	Troubleshooting Procedure	21
4.6	Sensor Element Open/Short Circuit (FMI3 and FMI4 in Table 3)	24
4.6.1	Discussion	24
4.6.2	Troubleshooting Procedure	24
4.7	DEF Tank Temperature Evaluation	24
4.7.1	Discussion	24
4.7.2	Procedure	24
4.8	DEF Tank Coolant Loop Evaluation	25
4.8.1	Discussion	25
4.8.2	Procedure	25

NOTICE OF CONFIDENTIAL INFORMATION AND PROPRIETARY RIGHTS

THIS DOCUMENT MAY NOT BE DISCLOSED TO OTHERS EXCEPT BY EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. THIS DOCUMENT CONTAINS CONFIDENTIAL COMMERCIAL AND TECHNICAL DATA, CONCEPTS AND OTHER INFORMATION, ALL OF WHICH ARE PROPRIETARY AND OF ECONOMIC VALUE TO SHAW DEVELOPMENT, LLC. THIS DOCUMENT MAY NOT BE USED FOR MANUFACTURE OR PROCESSING USES ABSENT EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. ANY USE OTHER THAN CONFIDENTIAL EVALUATION IS STRICTLY PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF SHAW DEVELOPMENT, LLC.

© 2017 Shaw Development, LLC. All rights reserved.

1 INTRODUCTION

1.1 Purpose of Technical Bulletin

The Technical Bulletin is intended to guide Shaw Development customers in troubleshooting fault codes related to the DEF tank assembly on Cummins engine equipment.

This document is intended to be a "living document", and the details and processes within can/will change as system designs evolve, or other new information comes to light.

1.2 Applicable Part Numbers, Assemblies and/or Applications

Table 1

	Source	Document No.	Title/Description
1	Shaw	DMCXX-XXXXXXXX	Gen4 headers with digital sensor
2	Shaw	DRCXX-XXXXXXXX	Gen4 tank assemblies with digital sensor
3	Shaw	DM5XX-XXXXXXXX	Gen5 headers
4	Shaw	DR5XX-XXXXXXXX	Gen5 tank assemblies
5	Shaw	DM6XX-XXXXXXXX	Gen6 headers
6	Shaw	DR6XX-XXXXXXXXXX	Gen6 tank assemblies
7	Shaw	DM7XX-XXXXXXXX	Gen7 headers
8	Shaw	DR7XX-XXXXXXXXXX	Gen7 tank assemblies

1.3 Required Tools and Equipment

Table 2

	Source	Equipment Name/PN	Description
1	Shaw	960-0232-01-K	Shaw Scan Gauge diagnostic tool
2	Cummins	Insight	Cummins ECM diagnostics application
3	Cummins	Inline 6/7	Cummins J1939 service tool
4	Cummins	DEF Refractometer	Refractometer calibrated for measuring DEF
5	Cummins	Quickserve Portal	Cummins field support portal
6		Digital Multimeter	
7		Thermocouple	Temperature measurement device
8		IR Thermometer	Infrared temperature measurement device

1.4 Definitions/Acronyms

- CCV
Coolant Control Valve
- DEF
Diesel Exhaust Fluid
- ECM
Engine Control Module
- FMI
Failure Mode Indicator
- J1939
SAE CAN Communication Protocol
- MFHU
Multi-Function Head Unit
- MSU
Multi-parametric Sensor Unit
- SAE
Society of Automotive Engineers
- SPN
Suspect Parameter Number

NOTICE OF CONFIDENTIAL INFORMATION AND PROPRIETARY RIGHTS

THIS DOCUMENT MAY NOT BE DISCLOSED TO OTHERS EXCEPT BY EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. THIS DOCUMENT CONTAINS CONFIDENTIAL COMMERCIAL AND TECHNICAL DATA, CONCEPTS AND OTHER INFORMATION, ALL OF WHICH ARE PROPRIETARY AND OF ECONOMIC VALUE TO SHAW DEVELOPMENT, LLC. THIS DOCUMENT MAY NOT BE USED FOR MANUFACTURE OR PROCESSING USES ABSENT EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. ANY USE OTHER THAN CONFIDENTIAL EVALUATION IS STRICTLY PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF SHAW DEVELOPMENT, LLC.

© 2017 Shaw Development, LLC. All rights reserved.

2 HEADER/SENSOR GENERATION IDENTIFICATION

Depending on the equipment vintage, there are multiple generations of DEF headers/sensors which could be encountered in the field. In order to assist personnel in troubleshooting, distinguishing features which can be used to identify which generation of Shaw products is being worked on are detailed below. Gen4 and Gen5 headers were produced with both the digital sensor, as well as analog sensors. Gen6 and Gen7 headers are only available with MSU sensors.

2.1 Gen4 Header With Analog Sensor

The Gen4 header with analog sensor is shown below. The contents of this document are typically not relevant to this product. From the exterior of the tank, this generation can be distinguished by a round, black sensor mounted into the DEF header, offset from center. Sensor part and serial numbers are present on the body of the sensor. Internally to the tank, a white plastic "focus tube" can be observed.




Figure 1: Gen4 Header with Analog Sensor




Figure 2: Gen4 Header with Analog Sensor Exterior Closeup

NOTICE OF CONFIDENTIAL INFORMATION AND PROPRIETARY RIGHTS

THIS DOCUMENT MAY NOT BE DISCLOSED TO OTHERS EXCEPT BY EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. THIS DOCUMENT CONTAINS CONFIDENTIAL COMMERCIAL AND TECHNICAL DATA, CONCEPTS AND OTHER INFORMATION, ALL OF WHICH ARE PROPRIETARY AND OF ECONOMIC VALUE TO SHAW DEVELOPMENT, LLC. THIS DOCUMENT MAY NOT BE USED FOR MANUFACTURE OR PROCESSING USES ABSENT EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. ANY USE OTHER THAN CONFIDENTIAL EVALUATION IS STRICTLY PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF SHAW DEVELOPMENT, LLC.

© 2017 Shaw Development, LLC. All rights reserved.

2.2 Gen4 Header with Digital Sensor

The Gen4 header with digital sensor is shown below. From the exterior of the tank, this generation can be distinguished by a laser etched bent stainless steel plate offset from center in the header, which is marked with a 11-digit serial number, a part number of the format 'XXXX-XX' or 'XXXX-XXXX', and a revision code of the format 'XX_X XXXXXX'. Additionally, the wire harness on this generation comes out of the sensor at a 90° angle. Gen4 digital sensors went through two iterations of design. Internally to the tank, the earlier iteration did not include the aeration shroud (see Figure 3), while the later generation did (see Figure 4).



Figure 3: Gen4 Header with Digital Sensor (Without Shroud)



Figure 4: Gen4 Header with Digital Sensor (With Shroud)

NOTICE OF CONFIDENTIAL INFORMATION AND PROPRIETARY RIGHTS

THIS DOCUMENT MAY NOT BE DISCLOSED TO OTHERS EXCEPT BY EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. THIS DOCUMENT CONTAINS CONFIDENTIAL COMMERCIAL AND TECHNICAL DATA, CONCEPTS AND OTHER INFORMATION, ALL OF WHICH ARE PROPRIETARY AND OF ECONOMIC VALUE TO SHAW DEVELOPMENT, LLC. THIS DOCUMENT MAY NOT BE USED FOR MANUFACTURE OR PROCESSING USES ABSENT EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. ANY USE OTHER THAN CONFIDENTIAL EVALUATION IS STRICTLY PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF SHAW DEVELOPMENT, LLC.

© 2017 Shaw Development, LLC. All rights reserved.



Figure 5: Gen4 Header with Digital Sensor Exterior Closeup

NOTICE OF CONFIDENTIAL INFORMATION AND PROPRIETARY RIGHTS

THIS DOCUMENT MAY NOT BE DISCLOSED TO OTHERS EXCEPT BY EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. THIS DOCUMENT CONTAINS CONFIDENTIAL COMMERCIAL AND TECHNICAL DATA, CONCEPTS AND OTHER INFORMATION, ALL OF WHICH ARE PROPRIETARY AND OF ECONOMIC VALUE TO SHAW DEVELOPMENT, LLC. THIS DOCUMENT MAY NOT BE USED FOR MANUFACTURE OR PROCESSING USES ABSENT EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. ANY USE OTHER THAN CONFIDENTIAL EVALUATION IS STRICTLY PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF SHAW DEVELOPMENT, LLC.

© 2017 Shaw Development, LLC. All rights reserved.

2.3 Gen5 Header with Analog Sensor

The Gen5 header with analog (reed switch) sensor is shown below. From the exterior of the tank, this generation can be distinguished by a laser etched stainless steel plate centered in the header, which is marked with a part number of the format 'XXXX-XX', and a 6-digit serial number below the part number. Additionally, the sensor harness is typically connected to the vehicle harness by a short jumper harness with a Deutsch DT06-4S on one end and OEM specific connectors on the other. Internally to the tank, a black magnetic float can be observed centered in the coolant coil.




Figure 6: Gen5 Header with Analog Sensor




Figure 7: Gen5 Header with Analog Sensor Exterior Closeup

NOTICE OF CONFIDENTIAL INFORMATION AND PROPRIETARY RIGHTS

THIS DOCUMENT MAY NOT BE DISCLOSED TO OTHERS EXCEPT BY EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. THIS DOCUMENT CONTAINS CONFIDENTIAL COMMERCIAL AND TECHNICAL DATA, CONCEPTS AND OTHER INFORMATION, ALL OF WHICH ARE PROPRIETARY AND OF ECONOMIC VALUE TO SHAW DEVELOPMENT, LLC. THIS DOCUMENT MAY NOT BE USED FOR MANUFACTURE OR PROCESSING USES ABSENT EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. ANY USE OTHER THAN CONFIDENTIAL EVALUATION IS STRICTLY PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF SHAW DEVELOPMENT, LLC.

© 2017 Shaw Development, LLC. All rights reserved.

2.4 Gen5 Header with Digital Sensor

The Gen5 header with Digital sensor is shown below. From the exterior of the tank, this generation can be distinguished by a laser etched stainless steel plate centered in the header, which is marked with a 11-digit serial number, a part number of the format 'XXXX-XX' or 'XXXX-XXXX', and a revision code of the format 'XX_X XXXXXX'. Internally to the tank, the sensor is black and has a L-shape; and the bottom of the sensor is covered with a plastic shroud.



Figure 8: Gen5 Header with Digital Sensor



Figure 9: Gen5 Header with Digital Sensor Exterior Closeup

NOTICE OF CONFIDENTIAL INFORMATION AND PROPRIETARY RIGHTS

THIS DOCUMENT MAY NOT BE DISCLOSED TO OTHERS EXCEPT BY EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. THIS DOCUMENT CONTAINS CONFIDENTIAL COMMERCIAL AND TECHNICAL DATA, CONCEPTS AND OTHER INFORMATION, ALL OF WHICH ARE PROPRIETARY AND OF ECONOMIC VALUE TO SHAW DEVELOPMENT, LLC. THIS DOCUMENT MAY NOT BE USED FOR MANUFACTURE OR PROCESSING USES ABSENT EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. ANY USE OTHER THAN CONFIDENTIAL EVALUATION IS STRICTLY PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF SHAW DEVELOPMENT, LLC.

© 2017 Shaw Development, LLC. All rights reserved.

2.5 Gen6 and Gen7 Header (MSU Sensor)

The Gen6 and Gen7 headers are shown below. The headers are the same between Gen6 and Gen7. The MSU Sensor is also a digital sensor, and is backwards compatible to Gen5 Digital applications. Externally to the tank, these generations can be distinguished by a blank stainless steel plate centered in the header, and part markings on the backshell of the Deutsch DT04-4P connector. The part marking consists of a QR code, a 10-digit serial number, a part number of the format 'XXXX-XX' or 'XXXX-XXXX', a single digit revision code, and a 6-digit firmware revision code (see Figure 12). Gen6 sensors went through two iterations of mechanical design. Internally to the tank, the earlier iteration can be identified by a trapezoidal shaped inlet with a white felt window, the latter can be identified by an oblong shaped inlet with a white felt window.



Figure 10: Gen6 Header with Early Model MSU Sensor



Figure 11: Gen6 Header with Current Model MSU Sensor



Figure 12: Gen6 and Gen7 Connector Markings

NOTICE OF CONFIDENTIAL INFORMATION AND PROPRIETARY RIGHTS

THIS DOCUMENT MAY NOT BE DISCLOSED TO OTHERS EXCEPT BY EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. THIS DOCUMENT CONTAINS CONFIDENTIAL COMMERCIAL AND TECHNICAL DATA, CONCEPTS AND OTHER INFORMATION, ALL OF WHICH ARE PROPRIETARY AND OF ECONOMIC VALUE TO SHAW DEVELOPMENT, LLC. THIS DOCUMENT MAY NOT BE USED FOR MANUFACTURE OR PROCESSING USES ABSENT EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. ANY USE OTHER THAN CONFIDENTIAL EVALUATION IS STRICTLY PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF SHAW DEVELOPMENT, LLC.

© 2017 Shaw Development, LLC. All rights reserved.

3 FAULT CODES

3.1 Discussion

Which fault codes are triggered by a given condition can depend on the engine/ECM model. In some instances, different fault codes can occur for the same fault, depending if the equipment is an on-road or off-road application. Application specific details of the fault codes can be researched in the Cummins Quickservice portal, using the equipment Engine Serial Number.

3.2 DEF System Fault Code Details

Table 3: Cummins Fault Codes

Fault Code	SPN	FMI	Cummins Verbiage	Cause	Section/Page
4677	1761	9	SAE J1939 Multiplexing PGN Timeout Error - Abnormal Update Rate.	ECM did not receive level message communication from sensor for 5 seconds	4.3/19
4572	3031	9	Aftertreatment Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate.	ECM did not receive level message communication from sensor for 5 seconds	4.3/19
3868	3364	9	Aftertreatment Diesel Exhaust Fluid Quality - Abnormal Update Rate.	ECM did not receive concentration message communication from sensor for 5 seconds	4.3/19
1669	1761	3	Aftertreatment Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source.	Sensor detects internal failure of level sensing circuit	4.6/24
1686	3364	3	Aftertreatment Diesel Exhaust Fluid Quality Sensor Circuit - Voltage above normal, or shorted to high source	Sensor detects internal failure of concentration sensing circuit	4.6/24
1678	3031	3	Aftertreatment Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Above Normal or Shorted to High Source.	Sensor detects internal failure of temperature sensing circuit	4.6/24
1677	3031	4	Aftertreatment Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Below Normal or Shorted to Low Source.	Sensor detects internal failure of temperature sensing circuit	4.6/24

NOTICE OF CONFIDENTIAL INFORMATION AND PROPRIETARY RIGHTS

THIS DOCUMENT MAY NOT BE DISCLOSED TO OTHERS EXCEPT BY EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. THIS DOCUMENT CONTAINS CONFIDENTIAL COMMERCIAL AND TECHNICAL DATA, CONCEPTS AND OTHER INFORMATION, ALL OF WHICH ARE PROPRIETARY AND OF ECONOMIC VALUE TO SHAW DEVELOPMENT, LLC. THIS DOCUMENT MAY NOT BE USED FOR MANUFACTURE OR PROCESSING USES ABSENT EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. ANY USE OTHER THAN CONFIDENTIAL EVALUATION IS STRICTLY PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF SHAW DEVELOPMENT, LLC.

© 2017 Shaw Development, LLC. All rights reserved.

Fault Code	SPN	FMI	Cummins Verbiage	Cause	Section/Page
4233	3515	3	Aftertreatment Diesel Exhaust Fluid Temperature Sensor - Voltage Above Normal or Shorted to High Source.	Sensor detects internal failure of temperature sensing circuit	4.6/24
4234	3515	4	Aftertreatment Diesel Exhaust Fluid Temperature Sensor - Voltage Below Normal or Shorted to Low Source.	Sensor detects internal failure of temperature sensing circuit	4.6/24
4277	3364	10	Aftertreatment Diesel Exhaust Fluid Quality - Abnormal Rate of Change.	Sensor is not getting a concentration reading, but does not detect a circuit failure. Sensor output 62.75% for concentration for some time.	4.5/21
4769	1761	10	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor - Abnormal Rate of Change. A valid diesel exhaust fluid tank level reading has NOT been received.	Sensor is not getting a level reading, but does not detect a circuit failure. Sensor output 100.4% for level for more than 2 hours.	4.4/20
1673	1761	1	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Data Valid But Below Normal Operating Range - Most Severe Level	Measured DEF tank level is very low.	
1699	1761	2	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor - Data Erratic, Intermittent, or Incorrect		
1679	3031	2	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Data Erratic, Intermittent, or Incorrect		
3866	3364	1	Aftertreatment Diesel Exhaust Fluid Quality - Data Valid But Below Normal Operating Range - Most Severe Level	The concentration of the DEF reported by the sensor is below normal range	
3714	1569	31	Engine Protection Torque Derate - Condition Exists	A fault code indicating the vehicle has gone into torque derate. The code can be triggered by many emissions related faults.	
3712	5246	0	Aftertreatment SCR Operator Inducement - Data Valid But Above Normal Operating Range - Most Severe Level	A secondary code triggered if other SCR related codes are active for some period of time	

NOTICE OF CONFIDENTIAL INFORMATION AND PROPRIETARY RIGHTS

THIS DOCUMENT MAY NOT BE DISCLOSED TO OTHERS EXCEPT BY EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. THIS DOCUMENT CONTAINS CONFIDENTIAL COMMERCIAL AND TECHNICAL DATA, CONCEPTS AND OTHER INFORMATION, ALL OF WHICH ARE PROPRIETARY AND OF ECONOMIC VALUE TO SHAW DEVELOPMENT, LLC. THIS DOCUMENT MAY NOT BE USED FOR MANUFACTURE OR PROCESSING USES ABSENT EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. ANY USE OTHER THAN CONFIDENTIAL EVALUATION IS STRICTLY PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF SHAW DEVELOPMENT, LLC.

© 2017 Shaw Development, LLC. All rights reserved.

Fault Code	SPN	FMI	Cummins Verbiage	Cause	Section/Page
4863	1569	31	Aftertreatment SCR Operator Inducement Active - Condition Exists	A secondary code triggered if other SCR related codes are active for some period of time	

NOTICE OF CONFIDENTIAL INFORMATION AND PROPRIETARY RIGHTS

THIS DOCUMENT MAY NOT BE DISCLOSED TO OTHERS EXCEPT BY EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. THIS DOCUMENT CONTAINS CONFIDENTIAL COMMERCIAL AND TECHNICAL DATA, CONCEPTS AND OTHER INFORMATION, ALL OF WHICH ARE PROPRIETARY AND OF ECONOMIC VALUE TO SHAW DEVELOPMENT, LLC. THIS DOCUMENT MAY NOT BE USED FOR MANUFACTURE OR PROCESSING USES ABSENT EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. ANY USE OTHER THAN CONFIDENTIAL EVALUATION IS STRICTLY PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF SHAW DEVELOPMENT, LLC.

© 2017 Shaw Development, LLC. All rights reserved.

4 PROCEDURES

4.1 Read ECM Fault Codes

1. Turn keyswitch ON
2. Connect Cummins Inline diagnostic tool to J1939 connector on the equipment
3. Open the Cummins Insite application on your computer
4. Turn the equipment keyswitch to power on the equipment electronics (do not crank the engine)
5. In Cummins Insite, connect to the ECM
6. Open the "Fault Codes" page in Cummins Insite

4.2 Obtaining a Cummins Insite Job Image

1. Connect the Cummins Inline diagnostic tool to the J1939 connector on the equipment.
2. Open the Cummins Insite application on your computer
3. Turn the equipment keyswitch to power on the equipment electronics (do not crank the engine)
4. In Cummins Insite, connect to the ECM
5. When prompted, set up the work order details as instructed by your organization
6. Export the Work Order/ECM Image as follows
 - i. Select the "Work Orders ECM Images ECM Templates" option on the left-hand side of the Insite application
 - ii. Right click on the Work Order/ECM Image you just created
 - iii. Select "Export Image(s) to External File"
 - iv. Complete the Save File dialog, and save the file to your preferred location




Figure 13: Cummins Insite Export Image

4.3 Abnormal Update Rate Fault Codes (3868, 4572, 4677)

4.3.1 Discussion

The Abnormal Update Rate codes are triggered when the ECM does not detect the 1Hz periodic messages transmitted by the DEF sensor for some period of time (typically 5 seconds). Depending on the ECM calibration, a subset of the three codes or all three have been observed to be present if this occurs. Information from Cummins Insite such as if the codes are active/inactive, how many counts of the codes are present, and whether Abnormal Update Rate codes for other Aftertreatment devices are present will factor into determining the root cause for these fault codes.

Occurrence of these codes due to a sensor failure has been associated with extended exposure to elevated DEF tank temperatures. If a fleetwide high failure rate, or reoccurring failures on a specific piece of equipment are observed, it is recommended to perform the DEF tank temperature evaluation in Section 4.7.

Note: The distinction between verbiage for these codes ("Abnormal Update Rate") and verbiage for other codes ("Abnormal Rate of Change"). These codes are caused by different phenomena and must be distinguished from each other.

4.3.2 Troubleshooting Procedure

1. Perform steps in Section 4.1
 - i. If the codes are inactive, monitor vehicle for reoccurrence and proceed with troubleshooting when they go active
 - ii. If "Abnormal Update Rate" codes are present for the DEF sensor and other aftertreatment devices, focus troubleshooting efforts on items that are common amongst them (power supply/grounds, harnesses, CAN resistors, etc)
 - iii. If only "Abnormal Update Rate" codes for the DEF sensor are present, focus troubleshooting efforts directly on the DEF sensor
2. Check equipment battery voltage
 - i. Turn keyswitch OFF
 - ii. Measure voltage across the positive (+) and negative (-) battery terminals
 - iii. If battery voltage is below 12V or 24V (depending on equipment power distribution system), follow Cummins service procedure for weak/damaged batteries
3. Check sensor supply voltage
 - i. Turn keyswitch ON
 - ii. Locate the sensor/ equipment harness connector interface
 - iii. Using a multimeter, insert probes into connector pins 3 (GND) and 4 (Power) from the back of the equipment side of the connector and measure voltage
 - a. If no voltage is present, check the fuse/breaker for the sensor circuit, check ground continuity between the sensor connector and chassis ground, and check all harness connections between the fuse/breaker and sensor connector
4. Check J1939 terminating resistors
 - i. Turn keyswitch OFF

NOTICE OF CONFIDENTIAL INFORMATION AND PROPRIETARY RIGHTS

THIS DOCUMENT MAY NOT BE DISCLOSED TO OTHERS EXCEPT BY EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. THIS DOCUMENT CONTAINS CONFIDENTIAL COMMERCIAL AND TECHNICAL DATA, CONCEPTS AND OTHER INFORMATION, ALL OF WHICH ARE PROPRIETARY AND OF ECONOMIC VALUE TO SHAW DEVELOPMENT, LLC. THIS DOCUMENT MAY NOT BE USED FOR MANUFACTURE OR PROCESSING USES ABSENT EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. ANY USE OTHER THAN CONFIDENTIAL EVALUATION IS STRICTLY PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF SHAW DEVELOPMENT, LLC.

© 2017 Shaw Development, LLC. All rights reserved.

-
- ii. Locate the sensor/ equipment harness connector interface
 - iii. Disconnect the sensor connector from the equipment harness
 - a. Inspect connectors and pins for damage/engagement
 - iv. Using a multimeter, probe resistance across pins 1 (CANL) and 2 (CANH)
 - a. If measured resistance is not approximately 60Ω, follow Cummins troubleshooting procedure for incorrect J1939 terminating resistance
 - 5. Perform any additional troubleshooting steps listed in the Cummins Quickserve troubleshooting procedure for these fault codes

4.4 Level Sensor Abnormal Rate of Change (4769)

4.4.1 Discussion

In contrast to the fault codes in Section 4.3, this fault code indicates the sensor is still functional, however it has been unable to obtain a level measurement for some time (typically 2 hours). The root cause for this fault code can vary depending on which sensor generation is installed on the equipment. Some possible causes which are not related to a sensor failure are:

- 1. The DEF tank is empty, or extremely low
- 2. Crystallized DEF causing the sensor's float to stick
 - i. Gen4 and Gen5 only. Typically only after equipment is removed from storage
- 3. The DEF tank is frozen and not thawing in the expected period of time

4.4.2 Troubleshooting Procedure

- 1. Perform steps in Section 4.1
 - i. If the code is active, continue to Step 2
 - ii. If the code is inactive, monitor the equipment for reoccurrence, and proceed with Step 2 when the code goes active
- 2. Confirm the tank is not frozen
 - i. If the tank is frozen but has been running long enough that it can be reasonably expected to be thawed, troubleshoot the DEF header coolant loop per the procedure in Section 4.8.2.
- 3. Confirm there is fluid in the tank
 - i. If the tank was very low/empty, fill the tank to 100%
 - ii. If the tank is overfilled, remove fluid from the tank until the fluid level at the designed 100% fill level
- 4. If a Shaw Scan Gauge tool is available, connect the tool to the sensor and check sensor outputs L1, L2 and LF
 - i. If the values are not L1: 1004, L2: 6426 and LF:31, perform the steps to clear the code as described in Cummins Quickserve
- 5. Perform any additional troubleshooting steps listed in the Cummins Quickserve troubleshooting procedure for this fault code

NOTICE OF CONFIDENTIAL INFORMATION AND PROPRIETARY RIGHTS

THIS DOCUMENT MAY NOT BE DISCLOSED TO OTHERS EXCEPT BY EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. THIS DOCUMENT CONTAINS CONFIDENTIAL COMMERCIAL AND TECHNICAL DATA, CONCEPTS AND OTHER INFORMATION, ALL OF WHICH ARE PROPRIETARY AND OF ECONOMIC VALUE TO SHAW DEVELOPMENT, LLC. THIS DOCUMENT MAY NOT BE USED FOR MANUFACTURE OR PROCESSING USES ABSENT EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. ANY USE OTHER THAN CONFIDENTIAL EVALUATION IS STRICTLY PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF SHAW DEVELOPMENT, LLC.

© 2017 Shaw Development, LLC. All rights reserved.

4.5 Quality Sensor Abnormal Rate of Change (4277)

4.5.1 Discussion

In contrast to the fault codes in Section 4.3, this fault code indicates the sensor is still functional, however it has been unable to obtain a concentration measurement for some time. The root cause for this fault code can vary depending on which sensor generation is installed on the equipment. Some possible causes which are not related to a sensor failure are:

1. The DEF tank is empty or extremely low
2. The DEF tank was recently filled at a high GPM fill rate (Gen4 and Gen5 only)
3. Crystallized DEF causing the sensor shroud to seal, thereby now allowing DEF into the measurement chamber
 - i. Gen4 and Gen5 only. Typically only after equipment is removed from storage
4. The DEF tank is frozen and not thawing in the expected period of time
5. The DEF tank temperature is excessively hot ($>55^{\circ}\text{C}$)
 - i. At elevated temperatures, the solubility of air in the DEF is reduced, and dissolved air can spontaneously come out of solution and form bubbles on measurement surfaces, thereby affecting performance.

4.5.2 Troubleshooting Procedure

1. Perform steps in Section 4.1
 - i. If the code is active, continue to Step 2
 - ii. If the code is inactive, monitor the equipment for reoccurrence, and proceed with Step 2 when the code goes active
2. Confirm the tank is not frozen
 - i. If the tank is frozen but has been running long enough that it can be reasonably expected to be thawed, troubleshoot the DEF header coolant loop per the procedure in Section 4.8.2.
3. Confirm there is fluid in the tank
 - i. If the tank was very low/empty, fill the tank to 100%
 - ii. If the tank was recently filled, and was working correctly prior to filling, it could simply be air caught in the system. Perform the following:
 - a. Impact the side of the tank with a rubber mallet. In some cases this has been proven to cause the sensor to vent the trapped air
 - b. With the keyswitch OFF, unbolt the header from the tank, and raise it out of the fluid, allowing the sensor to drain. If the header is a Gen4 with a shroud, inspect the sensor "duck-bill" vent for interference with the "z-fin" (see Figure 14). If the header is a Gen4 with a shroud or Gen5, peel back the shroud (see Figure 15) and reseal it, and manipulate the "duck-bill" vent as shown in Figure 16 to ensure it is not sticking shut. Replace the header into the tank, turn the keyswitch ON and confirm the sensor is reading correctly (using either a Shaw Development Scan Gauge tool, or Cummins Insite).

NOTICE OF CONFIDENTIAL INFORMATION AND PROPRIETARY RIGHTS

THIS DOCUMENT MAY NOT BE DISCLOSED TO OTHERS EXCEPT BY EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. THIS DOCUMENT CONTAINS CONFIDENTIAL COMMERCIAL AND TECHNICAL DATA, CONCEPTS AND OTHER INFORMATION, ALL OF WHICH ARE PROPRIETARY AND OF ECONOMIC VALUE TO SHAW DEVELOPMENT, LLC. THIS DOCUMENT MAY NOT BE USED FOR MANUFACTURE OR PROCESSING USES ABSENT EXPRESS WRITTEN PERMISSION OF SHAW DEVELOPMENT, LLC. ANY USE OTHER THAN CONFIDENTIAL EVALUATION IS STRICTLY PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF SHAW DEVELOPMENT, LLC.

© 2017 Shaw Development, LLC. All rights reserved.

-
4. Check the DEF tank temperature
 - i. If the equipment was recently operating, using either Cummins Insite or a Shaw Development Scan Gauge tool (T1 and T2 values), record the DEF tank temperature measured by the sensor.
 - ii. If the equipment has not recently been operated, perform the DEF Tank Temperature Evaluation per Section 4.7.
 - iii. If tank temperatures greater than 55°C are observed during the above steps, perform the Coolant Loop Evaluation per Section 4.8 to determine if the elevated temperatures are caused by a defect on the equipment
 5. Perform any additional troubleshooting steps listed in the Cummins Quickserve troubleshooting procedure for this fault code




Figure 14: "Duck-Bill" Vent and "Z-Fin" Closeup



Figure 15: Shroud Manipulation Example



Figure 16: "Duck-Bill" Manipulation Example

4.6 Sensor Element Open/Short Circuit (FMI3 and FMI4 in Table 3)

4.6.1 Discussion

Sensor failures associated with these fault codes are directly detected by the sensor's internal diagnostic routines, and reported to the ECM; unlike most other fault codes in this document, which are set by diagnostic logic internal to the ECM.

4.6.2 Troubleshooting Procedure

1. Perform steps in Section 4.1
 - i. If the code(s) is/are active, replace the sensor
 - ii. If the code(s) is/are inactive, check the fault code count for the specific code
 - a. If multiple counts of the code have occurred, and they were associated with an equipment derate, replace the sensor
 - b. If a single count of the code is present, or multiple counts without associated equipment derate, monitor the equipment for reoccurrence. If possible, perform the steps in Section 4.2, and share the file with the equipment OEM and Shaw Development for troubleshooting support

4.7 DEF Tank Temperature Evaluation

4.7.1 Discussion

Some sensor failure modes have been associated with excessively high DEF tank temperatures. As such, it may be valuable to evaluate the temperature rise, and maximum temperature experienced by the DEF on a given application. Factors such as ambient air temperature, DEF tank fill level, and equipment load, amongst others can affect the temperature rate of change in the DEF, and must be considered.

Note: It is recommended to maintain nominal operating DEF temperatures below 55°C.

4.7.2 Procedure

1. Ensure the equipment is in a normal operating condition
 - i. Perform required maintenance to alleviate any fault codes
2. Ensure the equipment has enough fuel to run, and the DEF tank is full
3. Set the equipment up to simulate normal operation
 - i. If it is a power generation application, attach the equipment to a load bank set to 75% load
 - ii. If it is an on/off-road application, ideally plan to perform the equipment's primary operation during testing. If this is not possible, as a last resort, place the equipment into high-idle
4. Record the ambient air temperature
5. Using either a thermocouple, IR thermometer, Cummins Insite, or the Shaw Scan Gauge tool, measure and record the DEF tank temperature
6. Crank the engine and begin operating the equipment under the given operating conditions
 - i. Run the equipment for 4 hours, recording DEF temperature every 1 hour

4.8 DEF Tank Coolant Loop Evaluation

4.8.1 Discussion

In some applications where excessively high DEF tank temperatures have been identified, the cause has been found to be a defect in the coolant circuit on the equipment. If certain defects are present, they can allow hot coolant to enter the DEF header coolant loop when it shouldn't (ie the fluid is not frozen or near freezing), thereby causing the DEF to be heated. Examples of such defects include:

1. The CCV is stuck open/leaking due to debris in the coolant circuit or a failed solenoid
2. The CCV was installed backwards
3. The coolant source and return lines are swapped at the DEF MFHU
4. The coolant source and return lines are swapped at the engine

4.8.2 Procedure

1. Inspect the CCV installation for proper orientation
 - i. Most CCVs have an arrow indicating fluid flow direction on their body. The arrow should be pointing toward the DEF tank.
2. Inspect the coolant hose routing to ensure it is plumbed per the OEM drawings
 - i. The DEF header has indicators molded into it at the fittings denoting flow direction
3. Evaluate the functionality of the CCV solenoid
 - i. Many applications test the CCV during startup. If you are working on one of these applications, turn the keyswitch ON while listening/feeling for the engagement of the CCV actuator.
 - ii. If the above is not valid, the harness can be disconnected from the CCV, and equipment battery power can be applied directly to the CCV. The same engagement of the CCV actuator should be observed if the CCV is functioning correctly.
4. Ensure the equipment is in a normal operating condition, in an environment where the DEF temperature is above 5°C
 - i. Perform required maintenance to alleviate any fault codes
5. Ensure the equipment has enough fuel to run, and the DEF tank is full
6. Crank the engine, and run the equipment until the engine/coolant is warm
7. Using an IR thermometer or thermocouple, check the coolant hose skin temperature at the following locations. A significant ΔT should be observed at the most upstream location, with the higher temperature on the coolant source side of the component.
 - i. Either side of the CCV
 - a. If no ΔT is observed, the CCV likely needs service/replacement
 - ii. Either fitting of the DEF MFHU
 - a. If a higher temperature is present at the coolant return fitting, coolant hoses are likely routed incorrectly