



Technical Service Bulletin

69 Front seat belt is twisted

69 21 71 2058455/5 October 12, 2021. Supersedes Technical Service Bulletin Group 69 number 21-65 dated May 17, 2021 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7, A8, Q8, and Audi e-tron quattro	2019 - 2020	All	Not Applicable
S6, S7, and Audi e-tron sportback	2020	All	Not Applicable
A6, A7, S6, and S7	2021	000001 - 014000	Not Applicable
A8	2021	000001 - 004600	Not Applicable
RS 6, RS 6 Avant, and RS 7	2021	900001 - 901252	Not Applicable
Audi e-tron quattro, Audi e-tron sportback	2021	000001 - 005800	Not Applicable


Condition

REVISION HISTORY		
Revision	Date	Purpose
5	-	Revised header (Corrected Elsa display issue)
4	05/17/2021	Revised header (Added Model Year) Revised <i>Production Solution</i> (Modified production solution timing for A6, A7, A8 and Audi e-tron quattro)
3	05/11/2020	Revised <i>Service</i> (Removed Q8 procedure for seat belt not available) Revised <i>Warranty</i> (Removed second warranty table)

Customer states:

- One or both of the front seat belts are twisted.

Workshop findings:



Technical Service Bulletin

- The seat belt webbing was pulled through the deflector of the seat belt height adjuster while twisted. The twisting of the seat belt webbing is predominantly caused by the "seat belt park function" featured in the reversible seat belt tensioners.

Technical Background

When exiting the vehicle, the seat belt can slightly twist when unbuckled. This twist can move up to the deflector of the seat belt height adjuster when the seat belt retracts. If the "seat belt park function" then occurs, this twist can be pulled past the seat belt deflector resulting in a completely twisted seat belt.

Production Solution

Seat belts with modified deflector guides for A6, A7, A8, Audi e-tron quattro, and Audi e-tron sportback implemented in production in the 3rd quarter of 2020.

The modified seat belts were implemented in Q8 production starting in December of 2019.

Service

A6, A7, A8, Audi e-tron quattro, and Audi e-tron sportback

1. Remove the upper B-Pillar trim on the affected side according to the Elsa Repair Manual.
2. Remove the bolt of the seat belt deflector (Figure 1, Pos. 3).



Tip: It is not necessary to remove the seat belt to perform this repair.




Figure 1. Seat belt deflector at height adjuster with B-Pillar trim removed.

Technical Service Bulletin

3. Use your thumb to remove the old belt guide (plastic part) from the steel deflector. Start by detaching the guide from the bolt hole, then press out the lower section covering the metal tab (Figures 2 -3).



Note:

Do not use sharp objects to remove the old belt guide to avoid damaging the seat belt webbing.





Figure 2. Backside of seat belt deflector. Deflector trim tabs engaged in the old belt guide.



Figure 3. Removing old seat belt guide starting at the bolt hole.



Technical Service Bulletin

4. With the old belt guide removed, turn the seat belt webbing to remove the twist (Figure 4).



Figure 4. Old seat belt guide removed. The seat belt twist is corrected.

5. Install the modified belt guide 4K8 857 799 on the front driver side and 4K8 857 800 on the front passenger side (Figure 2, Pos. 4).
6. Start installing the modified seat belt guide at the deflector metal tab (Figure 5).



Figure 5. Installing modified seat belt guide starting with the metal tab on the bottom.



Technical Service Bulletin

7. Push the new guide into the bolt hole until you can hear the plastic retainers snap into place (Figure 6).



Figure 6. Seat belt deflector with the new guide installed.

8. Inspect the front of the deflector for proper installation of the guide locking tabs at the bolt hole (Figure 7, Pos. 6).



Figure 7. Belt guide locking tabs correctly secured at the bolt hole.



Technical Service Bulletin

9. Inspect the back of the deflector for proper installation of the deflector trim locking tabs to the seat belt guide (Figure 8, Pos. 7).



Figure 8. Seat belt deflector trim locking tabs properly secured to the seat belt guide.

10. Reinstall the seat belt deflector at the height adjuster according to the Elsa Repair Manual.
11. Completely pull out the seat belt to ensure that the belt retracts as designed.
12. Reinstall the B-Pillar trim according to the Elsa Repair Manual.



Tip: Only perform this repair on the affected side.

Q8



Tip: Only perform this repair on the affected side. Only order modified seat belts for twist concerns. For all other concerns, the non-modified seat belts can be used.

1. Order the modified seat belt(s) according to the parts table (refer to ETKA for color code).
2. Replace the affected front seat belt(s) according to the Elsa Repair Manual.

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.
--------------------	--



Technical Service Bulletin

	<ul style="list-style-type: none">If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	6913		
Damage Code:	0010		
Labor Operations:	Modify 1 front belt	6911 4999	40 TU (A6 and A7 family) 50 TU (A8, Audi e-tron quattro, and Audi e-tron sportback)
	Modify 2 front belts	6911 5099	70 TU (A6 and A7 family) 90 TU (A8) 80 TU (Audi e-tron quattro, and Audi e-tron sportback)
	Q8 Only:		
	Remove and install 1 belt	6911 1900	See SRT with associated operations
	Remove and install 2 belts	6911 2000	See SRT with associated operations
Diagnostic Time:	GFF	0150 0000 (Q8 Only)	Time stated on the diagnostic protocol (Max 50 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2058455/5		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Required Parts and Tools

The part numbers mentioned in this TSB are different than the ones listed in ETKA. Only use parts listed in this TSB, this includes superseding part numbers!			
Part Number		Part Description	Quantity
See ETKA		Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
4K8857799		Relay fitting, left front (A6, A7, A8, Audi e-tron quattro, and Audi e-tron sportback)	01 as needed
4K8857800		Relay fitting, right front (A6, A7, A8, Audi e-tron, quattro, and Audi e-tron sportback)	01 as needed
Old	New	Q8 three-point automatic seat belt	
4M8857705*	4M8857705C*	Three-point automatic seat belt with belt tensioner	01 as needed
4M8857706*	4M8857706C*	Three-point automatic seat belt with belt tensioner	01 as needed
4M8857705A*	4M8857705D*	Three-point automatic seat belt with belt tensioner	01 as needed
4M8857706A*	4M8857706D*	Three-point automatic seat belt with belt tensioner	01 as needed
4M8857705B*	4M8857705E*	Three-point automatic seat belt with belt tensioner	01 as needed
4M8857706B*	4M8857706E*	Three-point automatic seat belt with belt tensioner	01 as needed
4ML857705*	4ML857705A*	Three-point automatic seat belt with belt tensioner	01 as needed
4ML857706*	4ML857706A*	Three-point automatic seat belt with belt tensioner	01 as needed

Additional Information

All parts and service references provided in this TSB (2058455) are subject to change and/or removal.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.