

# Service Alert

Mazda North American Operations  
Irvine, CA 92618-2922



<b>Subject:</b>  <b>CONNECTED VEHICLE SYMPTOM TROUBLESHOOTING</b>	<b>Service Alert No.: SA-013/21</b>
	<b>Last Issued : 10/13/2021</b>

## BULLETIN NOTES

This service alert supersedes the previously issued service alert listed below. The changes are noted in Red text.

Previous Service Alert	Date(s) Issued:
SA-013/21	09/14/21, 05/11/21, 04/27/21, 03/15/21, 02/22/21, 02/08/21 and 02/02/2021
SA-031/20	12/09/20, 11/30/20, 11/06/20, 10/28/20, 06/16/20, 06/05/20, 06/01/20, 05/18/20, 04/14/2020, 04/02/20, 03/11/20 and 02/27/20

## APPLICABLE MODEL(S)/VINS

2019-2021 Mazda3  
2020-2021 CX-30  
2021 CX-5  
2021 CX-9

## DESCRIPTION

Some customers may complain about any of the following:











- Infotainment Center Display does not provide the Authorization Code during the MyMazda App Connected Vehicle enrollment.
- Remote function(s) inoperative.
  - Engine Start / Stop
  - Door Lock / Unlock
  - Lights ON / OFF
- MAZDA CONNECT connected vehicle reception strength icon shows "X" or "\".

Confirm the customer's phone and vehicle have good to strong reception during the concern as shown in the table below.

- If the reception is weak, move the vehicle to a location where the reception is good to strong as shown in the table, then try to get the Authorization Code and/or operate the remote functions before proceeding to the Repair Procedure if there is still an issue.
- If the reception is good to strong, proceed to the Repair Procedure.

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Indication	Explanation
Mazda3, CX-30 	Radio waves are not being received. Move to a location with good reception.
	Weak reception.
	Good Reception
	Strong reception.
	Currently conducting an operation check of the communication unit. If this condition continues, consult an Authorized Mazda Dealer.
	Currently conducting an operation check of the onboard communication unit. <b>NOTE:</b> Communication is not possible during this display.
CX-5, CX-9 	The communication function is temporarily disabled due to infotainment system setting. 
Mazda3, CX-30 	<ul style="list-style-type: none"> <li>• Connected Service contract has ended (Subscription expired)</li> <li>• Customer deactivated Connected Services (Opt-Out)                             <ul style="list-style-type: none"> <li>◦ eMDCS Warranty Vehicle Inquiry will show Campaign <b>CSP04</b> Status Closed</li> </ul> </li> <li>• TCU has not been initialized, go to <a href="#">SA-004/21</a></li> </ul>
CX-5, CX-9 	

**Remote Engine Start Will Not Function under the following conditions**

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Item	Condition
1	Vehicle battery voltage low
2	Automatic Transmission shift position except "P"
3	Vehicles equipped with manual transmission
4	Vehicle speed above 3 mi/h (5 km/h)
5	Brake pedal switch malfunction
6	Engine has been running by remote engine start function
7	Engine started by remote engine start more than 2 consecutive times while the vehicle is not driven. The vehicle must be driven 1-mile or 24-hours must pass from the last successful Remote Engine Start for the use count to reset.
8	2021 Mazda3 and CX-30: Vehicle's electrical control area network (CAN) is in "Sleep Mode"
9	A registered key is detected in the vehicle
10	Brake pedal switch detects brake application
11	Low fuel warning message
12	Engine starts, then turns OFF due to abnormal high engine rpm detected. (Engine rotation over 3000 rpm continued for more than 0.2[s])
13	No engine rpm detected after sending engine start request. (Engine rotation 0 rpm continued for more than 0.2[s])
14	When the CAN data signal for engine shut off is present (e.g.: door ajar signal)
15	After 10 second maximum cranking time
16	Burglar alarm status is "Alarm" and "Alarm stand by" (CAUTION - DO NOT enable, see Theft-Deterrent System section in <a href="#">SA-012/20</a> )
17	Room fuse blown/missing
18	Connected Vehicle Maintenance Mode enabled (Restricted Transmitting Mode in MDARS)
19	Vehicle is parked (stored) for approximately 1 week or longer or in deep sleep mode. Drive the vehicle for a few miles to recover.
20	DTC Stored
21	Aftermarket Remote Engine Start accessory installed.
22	Mazda Remote Engine Start (BCKA-V7-620) accessory installed (No MyMazda app remote engine start function). <b>Mazda Remote Engine Start (RES) Removal</b> a. Remove the Mazda Remote Engine Start (RES) accessory module. b. Deactivate and activate Advanced Key(s). Refer to MGSS <a href="#">IMMOBILIZER SYSTEM-RELATED PARTS PROGRAMMING [(US)]</a>
23	First remote control attempt fails, second attempt works fine. Go to TSB <a href="#">16-002/20</a> .

#### Remote Engine Start Function Will turn engine OFF under the following conditions

Item	Condition
1	Vehicle door(s) opened

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

2	Vehicle trunk opened
3	Vehicle hood opened
4	Ignition switch push button "ON" detected
5	Remote engine STOP request
6	Brake pedal switch detects brake application
7	DTC Stored
8	Engine will stop running automatically after 15 minutes for safety, security and emissions.


**REPAIR PROCEDURE**

**CAUTION:** DO NOT swap TCU with another vehicle as the TCU is VIN locked after activation. A TCU swap with another vehicle will disable Connected Services on both vehicles.


**NOTE:** Vehicles stored for long periods may lose GPS clock synchronization. If the vehicle is stored for a long period, test drive the vehicle to give the GPS clock time to synchronize before enrolling or testing connected vehicle functions.

**Index**


1. Remote function(s) inoperative
2. Unable to enroll into connected services
3. Connected vehicle reception strength icon shows "X" or "\
4. MyMazda App displays incorrect tire pressures (Except CX-5, CX-9)
5. Unable to activate Connected Services (2019 Mazda3)
6. Software Update Error (2020 Mazda3)
7. Functions inoperative (2021+ CX-30, Mazda3)
8. First remote control attempt fails, second attempt works fine
9. Engine turns off when opening door
10. Low Tire pressure will not clear after correcting tire pressure

Connected Vehicle Troubleshooting			
	Symptom	Cause	Action
1	Remote function(s) inoperative. <ul style="list-style-type: none"> <li>• Engine Start / Stop</li> <li>• Door Lock / Unlock</li> <li>• Lights ON / OFF</li> </ul>	Go to the MyMazda App to view the reason for remote function failure.	<b>Push Notification</b> 

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



			<p><b>OS Lock Screen</b> Tap the push notification</p>	<p><b>Home</b> Tap the alert card</p>
	<p><b>Activity History</b></p>	<p>Go to the MyMazda App INBOX -&gt; ACTIVITY to view reason for remote function failure.</p> 	<p><b>Troubleshooting needed</b></p>	<p>1. Use MDARS to ID the vehicle and check for DTC's stored?  <ul style="list-style-type: none"> <li>• Yes - Go to MGSS and perform normal DTC diagnosis</li> <li>• No - Go to next step.</li> </ul>                 2. If applicable, confirm SSPC7 or DRW41 is closed. Go to Vehicle Inquiry.                  3. Confirm TCU software version is at the following using <a href="#">Version Check</a> <ul style="list-style-type: none"> <li>• CX-5 and CX-9 - 10020 or later</li> <li>• CX-30 and Mazda3 - 10004 or later</li> </ul>                 4. Perform KAM reset.  <b>NOTE:</b> Test drive vehicle after a KAM reset to allow clock to synchronize before retrying Authorization                  5. <b>Perform one of the following:</b> <ul style="list-style-type: none"> <li>• <b>Customer:</b> Un-enroll Connected Services, then re-enroll Connected Services as a new primary user.</li> <li>• <b>Dealer:</b> Perform customer take-over enrollment confirmation, then at customer pick-up, inform customer to enroll into Connected Services as a new primary user.</li> </ul>                 6. Contact Hotline for additional technical support if needed.</p>
	<p>Only a single</p>		<p>Customer needs to wait 60 seconds for the initial request</p>	

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



		remote request can be made per 60-second period	be completed to make the second request.
		Remote Transmitter Key(s) in the vehicle	Do not leave keys in vehicle.
		<p>1. Aftermarket Remote Engine Start accessory installed.</p> <p>2. Mazda Remote Engine Start (BCKA-V7-620) accessory installed.</p> 	<p>1. Remove the aftermarket accessory.</p> <p>2. The customer can use either the Mazda Remote Engine Start accessory or the MyMazda app function. Cannot use both.</p> <p><b>Mazda Remote Engine Start (RES) Removal</b></p> <p>a. Remove the Mazda Remote Engine Start (RES) accessory.</p> <p>b. Deactivate and activate Advanced Key(s). Refer to <a href="#">Mazda Immobilizer System-Related Parts Program</a>.</p>
		TCU in "deep sleep" mode due to vehicle being parked for a long period.	Advise customer to drive the vehicle as normal (at least 10 minutes) and the Connected Services should start working again.
		Low fuel	Advise customer that Remote Engine Start may start vehicle but vehicle will turn off automatically when the fuel level is low to conserve the remaining fuel.
		Vehicle is equipped with Manual Transmission	Advise customer that vehicles with a manual transmission do not have the Remote Engine Start/Stop function capability.
		Engine started with key transmitter instead of MyMazda App.	Advise customer they will see an error message when they attempt to make a Remote Engine Off request if they initially turned the engine off with a physical key (instead of through their MyMazda app).
2	Unable to enroll into connected services. (Vehicle center display does not provide the	Customer deactivate	Go to <a href="#">eMDCS Vehicle Inquiry</a> . Does eMDCS show <a href="#">CSF</a> closed?

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.






	<p>Authorization Code during the MyMazda App enrollment)</p>	<p>Connected Services (Opt-Out)</p>	<ul style="list-style-type: none"> <li>• Yes - Customer opt-out. No action needed.</li> <li>• No - CSP04 is not shown. Go to next Action below</li> </ul>
		<p>Troubleshooting needed</p>	<ol style="list-style-type: none"> <li>1. Use MDARS to ID the vehicle and check for DTC's stored?             <ul style="list-style-type: none"> <li>• Yes - Go to MGSS and perform normal DTC diagnosis</li> <li>• No - Perform <a href="#">ODR Data Collection</a> Procedure, then</li> </ul> </li> <li>2. Confirm TCU software version is at the following using <a href="#">Version Check</a>.             <ul style="list-style-type: none"> <li>• CX-5 and CX-9: 10020 or later</li> <li>• CX-30 and Mazda3: 10004 or later</li> </ul> </li> <li>3. Retrieve MAZDA CONNECT CMU log data. Go to MGSS Infotainment -&gt; <a href="#">MAZDA CONNECT CMU Data Retrieval</a></li> <li>4. Perform "<a href="#">Activating Remote Control by Smart Phone</a>" (BCM)</li> <li>5. Clear DTC(s).</li> <li><b>NOTE:</b> If DTC 2050:55 is stored, go to <a href="#">SA-003/20</a> to clear</li> <li>6. Perform KAM reset.</li> <li><b>NOTE:</b> Test drive vehicle after a KAM reset to allow the system to synchronize before retrying Authorization Code.</li> <li>7. Contact Hotline for additional technical support if needed</li> </ol>
<p>3</p>	<p>MAZDA CONNECT connected vehicle reception strength icon shows "X" or "\".</p> <p>Mazda3, CX-30</p>  <p>CX-5, CX-9</p> 	<p>No reception</p>	<ol style="list-style-type: none"> <li>1. Go to <a href="#">eMDCS Vehicle Inquiry</a>. Does eMDCS show CSP04 closed?             <ul style="list-style-type: none"> <li>• Yes - Customer opt-out. No action needed.</li> <li>• No - CSP04 is not shown. Go to next step.</li> </ul> </li> <li>2. Check for DTCs. Are there any DTC's stored?             <ul style="list-style-type: none"> <li>• Yes: Go to MGSS for normal DTC diagnosis.</li> <li>• No: Go to next step.</li> </ul> </li> <li>3. Confirm TCU software version is at the following using <a href="#">Version Check</a>.             <ul style="list-style-type: none"> <li>• CX-5 and CX-9: 10020 or later</li> <li>• CX-30 and Mazda3: 10004 or later</li> </ul> </li> <li>4. Disconnect battery terminal for 30 seconds, then test drive vehicle. Is the reception strength signal normal?             <ul style="list-style-type: none"> <li>• Yes: Repair complete.</li> <li>• No: Go to next step.</li> </ul> </li> <li>5. Perform TCU activation. Go to <a href="#">SA-004/21</a>. Is the reception strength signal normal?</li> </ol>

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


			<ul style="list-style-type: none"> <li>• Yes: Repair complete.</li> <li>• No: Go to next step.</li> </ul> <p>6. Compare Tel antenna No. 1 signal strength with good one near by. Go to DIAGNOSTIC ASSIST FUNCTION [CONFIRM] MASTER UNIT (US)] Functional Inspection / Adjustment -&gt; Navigation System</p> <p><b>Good</b> - Contact Hotline for technical support</p>  <p><b>No Good</b> - Swap Tel antenna No. 1 with known good one</p> 
4	<p>Except CX-5 and CX-9</p> <p>MAZDA CONNECT and/or MyMazda App displays incorrect tire pressures after battery disconnect and/or infotainment CMU software update.</p>	<p>Incorrect calendar entry (month/day/year) after a battery disconnect or infotainment system software update.</p>	<p>Go to <a href="#">SA-002/21</a></p>

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



			
5	<p>2019 Mazda3 only</p> <ul style="list-style-type: none"> <li>The customer is not able to activate Connected Services via the MyMazda app after CSP06 completion.</li> <li>MAZDA CONNECT connected vehicle reception strength icon is missing or shows unsubscribed after CSP06 completion.</li> </ul> 	<p>Improper telematics communication unit (TCU) software.</p>	<p>Go to <a href="#">CSP07</a> Repair instructions.</p>
6	<p>2020 Mazda3 only</p> <ul style="list-style-type: none"> <li>Infotainment center display does not provide the Authorization Code</li> <li>Infotainment center display "Software Update Error" message</li> </ul> 	<p>Enrollment error</p>	<p>Go to <a href="#">SSPC1</a></p>



**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

7	<p>2021 Mazda3 and CX-30 functions inoperative</p> <ul style="list-style-type: none"> <li>• Vehicle Status Alert</li> <li>• Remote Engine Start / Stop</li> <li>• Remote Door Lock / Unlock</li> <li>• Remote Hazard Lights ON / OFF</li> <li>• Vehicle Finder (vehicle location mapping function is available)</li> </ul>	<p>Vehicle's electrical control area network (CAN) is in "Sleep Mode"</p>	 <p>No dealer visit is required. Sleep Mode can be reset by engine and idling or driving for 5 minutes or longer.</p> <p>Go to <a href="#">SA-005/21</a>.</p>
8	<p>First remote control attempt fails, second attempt works fine.</p> <ul style="list-style-type: none"> <li>• Engine Start / Stop</li> <li>• Door Lock / Unlock</li> <li>• Lights ON / OFF</li> </ul>	<p>Improper telematics communication unit (TCU) software.</p>	<p>Go to TSB <a href="#">16-002/20</a>.</p>
9	<p>Engine turns off when customer opens vehicle door.</p>	<p>Normal Operation</p>	<p>Advise that, for customer's safety and security, vehicle shut-off automatically when the vehicle door is opened.</p>
10	<ul style="list-style-type: none"> <li>• Low Tire pressure will not clear after correcting tire pressure.</li> <li>• Vehicle status is inaccurate.</li> </ul>	<p>MyMazda App is not real time.</p>	<ul style="list-style-type: none"> <li>• Customer must go to MyMazda app's Inbox and messages related to the low tire pressure alert, the "pressure" alert will clear from MyMazda app's Home screen.</li> <li>• Message will clear after next drive cycle.</li> </ul>

**ODR Data Collection Procedure**


1. ID the vehicle using MDARS	---
-------------------------------	-----

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


<p>2. Select "Toolbox"</p>	 <p>The screenshot shows the Mazda diagnostic software interface. At the top, there is a navigation bar with 'Quick Check' and 'Toolbox' tabs. The 'Toolbox' tab is selected and circled in red, with a red arrow pointing to it. Below the navigation bar is a grid of diagnostic tool icons for various systems: ABS, AFS/ALM, AM, BSML, BSMR, CMU, DSM, EATC, EPB, EPS, F_BCM, FSC, GWU, HUD, IC, PCM, PLG, R_BCM, RCM, SBS/MRCC, SSU, TCM, TCU, and VMC. A legend at the bottom indicates the status of Diagnostic Trouble Codes (DTCs): green for 'No DTCs', red for 'Communication Error', blue for 'No Communication or Not Equipped', orange for 'DTC(s) exist', and grey for 'DTC Not Supported'.</p>
<p>3. Select Vehicle Icon</p>	 <p>The screenshot shows the Mazda diagnostic software interface. At the top, there is a navigation bar with 'Quick Check' and 'Toolbox' tabs. The 'Toolbox' tab is selected. Below the navigation bar is a toolbar with several icons. The vehicle icon, which is a car silhouette, is circled in red, and a red arrow points to it. Below the toolbar, the main area displays the text 'Activating or deactivating flexible setting for Maintenance Monitor' and a 'Run' button.</p>

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

4. Expand "Collect Diagnostic Information"




5. Select Collecting diagnostic information "Run".




**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

6. Turn the ignition ON, then select "Next"




7. Wait for collection to complete.



**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

8. Confirm that the ODR collection has been successful. Select "Next" to exit.



**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



**Activating Remote Control by Smart Phone (links TCU to BCM)**

**NOTE:** This procedure cannot be performed if the key transmitter power saving function is enabled. See [SA-040/20](#).

1. Connect MDARS.




2. Use MDARS to verify if the Telematics Control Unit (TCU) is at the latest software level (Toolbox > Software Update > Run > TCU).

**Is the TCU at the latest software level?**

- **Yes:** Go to step 3.
- **No:** Update TCU software, then go to step 3.

3. Select the following:

- Toolbox
- Repair icon
- MAZDA CONNECT
- Activating Remote Control by Smart Phone
- RUN.




4. Follow the on-screen instructions and wait for process to complete.

**NOTE:** If the Activating Remote Control by Smart Phone shows "Incomplete", the possible causes are:


**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

- a. The advanced key is not in the vehicle.
- b. The connected Vehicle Maintenance Mode is enabled.
- c. The Key transmitter power saving function is enabled.
- d. The pacemaker radio wave interference prevention function is enabled.



5. Select Quick Check (A), then start the engine and select the DTC Clear icon (B).

**CAUTION:** If the engine is not started, DTC P2610 is stored and cannot be erased.








**TCU Software Version Check**

1. Press and hold the Volume knob, then press and hold the Entertainment and Favorite buttons at the same time for 3-5 seconds and the Factory/Service Inspection screen will appear.

**CX-5 and CX-9**

**CX-30 and Mazda3**

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

		
<p>2. Select Service Information.</p>		
<p>3. Select TCU Linked information.</p>		
<p>4. Scroll down to TCU Software Version and confirm the software version is at:</p> <ul style="list-style-type: none"> <li>• 10020 or later for CX-5 and CX-9</li> <li>• 100004 or later for CX-30 and Mazda3</li> </ul> <p><b>Is the TCU software version correct?</b></p> <ul style="list-style-type: none"> <li>• <b>Yes:</b> TCU Software Version Check is complete.</li> <li>• <b>No:</b> Go to <a href="#">SSPC7</a> (Repair Procedure) to update the TCU software version.</li> </ul>		

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.