

Key Programs More Readily When Placed Directly on Transmitter

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Taycan	2020 - 2022	Y1A	N/A	N/A

Revision History

Revision	Release Date	Changes
0	February 13, 2020	Original document
1	October 12, 2021	Extension of Model Year

Condition

After many attempts, key programming is not successful for one or more keys. The workshop may observe this condition while performing WKK8.

Service Information

In cases where the workshop experiences this condition, programming is often successful after placing the key in direct contact communication device (found under the cup holder) instead of in the emergency start tray. (the key reading location found in the cup holder – see figure 1).



Figure 1

Search Items

KESSY, fob, teach

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.