

Advanced Technical Information

Bulletin #: 2014.2

Part ID: 9981D

9

AC Charging Hardware and Cable Temperature

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Taycan	As of 2020 up to 2022	Y1ADB1, Y1AFC1, Y1AFH1	All	73E, 73C

Revision History

Revision	Release Date	Changes
0	August 31, 2020	Original document
1	September 25, 2020	Content update
2	October 13, 2021	Extension of Model Year

Condition

Customer reports the car charger and/or its supply cable are hot to the touch.

Technical Background

The subject vehicles come standard with 9.6 kW supply equipment named Porsche Mobile Charger, Porsche Mobile Charger Plus, or Porsche Mobile Charger Connect (PMCC). Standard equipment includes a 40A supply cable with a NEMA 14-50 plug (4 prong, I-Nr. 73E). A 40A supply cable with NEMA 6-50 plug (3 prong, I-Nr 73C) can be selected as an option.

Both 40A supply cables are also available via Porsche parts channels under the following part numbers:

- 7PP971678ED 40A Supply cable, NEMA 14-50 plug (4-prong)
- 7PP971678EC 40A Supply cable, NEMA 6-50 plug (3-prong)

The supply equipment control unit is equipped with various temperature sensors and function monitors. If the device detects overheating, for example, then charging current can be automatically reduced for a period of time.



Advanced Technical Information

Bulletin #: 2014.2

Part ID: 9981D

9

Service Information

- The surface of the charger and associated equipment can become very hot. Observe the operating
 instructions provided with the charger, particularly the warnings and safety instructions.
- The Porsche charging equipment described in this bulletin is certified with all applicable cables to UL 2594 standards.
- It is believed the device and its components are operating within specification. Nevertheless,
 Porsche AG is investigating customer concerns
- If the temperature of the supply cable is a concern, then it is possible to reduce the supplied current through the charger interface.
 - Refer to the chapter Charging Current Limiting in the applicable Operating Manual.
- In the event of overheating of the Porsche Mobile Charger Connect, the message "Limited service" may appear on the charger display. Additional information can then be found through the Porsche Mobile Charger Connect Web Application (accessible through local IP query or the charger Hotspot). Refer to the Porsche Mobile Charger Connect Operating Manual for instructions on how to access that information.

NOTICE:

Errors exist in the label affixed to supply cables provided with vehicles produced before August, 2020, as well as cables currently available via normal parts channels.

Only one label variant exists and is affixed to all supply cables in USA and Canada (NEMA5-15, 6-/14-30, and 6-/14-50). Figure 1 shows the existing label with errors. Figure 2 shows the updated label.

The necessary recourse for labels with errors is being evaluated.

Advanced Technical Information

Bulletin #: 2014.2

Part ID: 9981D

9




Figure 1

Figure 2

Warranty

No warrantable work is described herein.

Where necessary, document customer complaint cases completely in PQIS.

Search Items

Y1A, Taycan, NEMA, NEMA 14-50, NEMA 6-50, Porsche Mobile Charger, Porsche Mobile Charger Connect, PMC, PMCC, ICCPD, EVSE, charging hardware, 40 amp

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.