
Mobile Charger Connect Displays Restricted Operation - PLC Failure

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Taycan	As of 2020 up to 2022	Y1A, Y1B	N/A	N/A

Revision History

Revision	Release Date	Changes
0	June 28, 2021	Original document
1	October 13, 2021	Extension of Model Year

Condition

The customer reports the Porsche Mobile Charger Connect (PMCC) displays the message "Limited Service | PLC-Failure", and charging is not possible.

Technical Background

The PMCC is configured with the default setting "Powerline Communication (PLC) – Enabled". If the PLC function is not used, the control unit may display the mentioned message.

Service Information

The PLC function should simply be deactivated via the Web Application. This is not a hardware malfunction and it is not necessary to replace parts for this message.

Please refer to *Advanced Technical Information (ATI) Group 9 2016*, "Porsche Mobile Charger Connect Diagnosis and utilizing the Web Application" along with existing documentation for the PMCC and the PMCC Web Application.

In rare cases, the customer infrastructure and/or smart-home systems may occasionally utilize the PLC function and deactivation of PLC could cause an unwanted change in system behavior. If the message appears but the customer wishes to continue utilizing the PLC function, then it may be advisable to either re-calibrate the PLC modem with network consumers switched off or in normal resting state –or– relocate the PLC modem to be closer to the charging hardware.




Figure 1

Search Items

Taycan, mobile charger connect, PMCC, PLC, powerline communication

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.