

# Advanced Technical Information

Bulletin #: 2125

Part ID: 2804

2

## 992 Ignition Lock Warning Along with Fault Code B143C29

### **Vehicles Affected**

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
911 Carrera	As of 2020 up to 2021	992	N/A	N/A

## **Revision History**

Revision	Release Date	Changes
0	October 14, 2021	Original document

### Condition

The customer reports an ignition lock warning present in the instrument cluster. The workshop confirms this warning along with fault code B143C29 in the rear BCM.

## **Technical Background**

The ignition switch has a mechanical problem. The spring-force pins do not produce good electrical contact to the circuit board. This leads to the fault and warning.

### Condition

Porsche is working to release updated parts. When these are available, we will update this document. Until then, do not replace parts. This will not fix the issue.

You can verify solid electrical connectivity and proper pin tension. This may mitigate the issue in some cases.

#### Search Items

Ignition lock, ignition switch, rotor, dummy, key

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.