

SRS DTC U3000-49 Internal Failure Of The SRS Unit

AFFECTED VEHICLES

Year	Model	Trim Level
2020–2021	ILX	ALL
2020	MDX	ALL
2020–2021	NSX	ALL
2020–2021	RDX	ALL
2020	RLX	ALL
2020–2021	TLX	ALL

EDITOR'S NOTE: This article revises the one posted in October 2021.

There are several possible causes for the SRS DTC U3000-49 (Internal Failure of the SRS Unit) to be stored. If you can duplicate the DTC, the troubleshooting will take you through the step-by-step process in isolating the faulty component. In most situations, the SRS Unit should be last on the list of components to replace. Here is a quick tip for troubleshooting a faulty seat weight sensor.

Disconnect all seat weight sensors and clear DTCs. If the DTC U3000-49 (Internal Failure of the SRS Unit) does not reappear then replace seat frame/rail.

NOTE: If you are not fully replacing the seat frame and are using a known good one, always find a vehicle with the same trim level. Swapping seat frames with different trim levels may result in the same DTC condition and cause confusion.