



GROUP	MODEL
Product Improvement	2017-2019MY Soul (PS) w/2.0L GDI
NUMBER	DATE
PI2107	November 2021

PRODUCT IMPROVEMENT CAMPAIGN

SUBJECT: NU 2.0L GDI - KNOCK SENSOR DETECTION SYSTEM (KSDS) ECU LOGIC IMPROVEMENT (PI2107)

This bulletin provides information related to a software update to the Engine Control Unit (ECU) to install the Knock Sensor Detection System (KSDS), in order to protect the engine from excessive connecting rod bearing damage. This update is for certain 2017-2019MY Soul (PS) vehicles equipped with Nu 2.0L GDI engines, produced from July 29, 2016 through December 21, 2018.

The KSDS detects vibrations indicating the onset of excessive connecting rod bearing wear. It is designed to alert the driver at an early stage of bearing wear before the occurrence of severe engine damage, including engine failure. If vibrations caused by bearing wear start to occur, the Malfunction Indicator Lamp (MIL) will blink continuously, and the vehicle will be placed in Limp Home Mode. This will reduce further damage to the engine and ensure that the vehicle occupants are not exposed to the risk of a more severe engine failure. At that time, Diagnostic Trouble Code ("DTC") P1326, specific to the KSDS, will be recorded in the ECU. The vehicle can continue to be operated for a limited time in Limp Home Mode, but it will accelerate slowly and have a reduced maximum speed. Also, engine RPMs will be limited to approximately 1800-2000 RPM.

Kia is requesting the completion of this Product Improvement Campaign on all affected vehicles. Before conducting the procedure, verify the vehicle is included in the list of affected VINs. Also, please have your KDS connected to the internet regularly to get the latest software updates available.



Kia Diagnostic System (KDS)

NOTICE

To assure complete customer satisfaction, always remember to refer to WebDCS Warranty Coverage (validation) Inquiry Screen (Service → Warranty Coverage → Warranty Coverage Inquiry) for a list of any additional campaigns that may need to be performed on the vehicle before returning it to the customer.

NU 2.0L GDI - KNOCK SENSOR DETECTION SYSTEM (KSDS) ECU LOGIC IMPROVEMENT (PI2107)

ECU Upgrade Procedure:

To correct this condition, the ECU should be reprogrammed using the KDS download, as described in this bulletin.

Upgrade Event Name
578. PS NU 2.0GDI Knock Sensor Detection System (KSDS) ECU UPGRADE (17~19MY)


NOTICE

- Confirm a fully charged battery (12.3 volts or higher is necessary) is used or utilize a fully charged jump starter box connected to the battery.
- **Ensure the KDS GDS is sufficiently charged at 60% or higher prior to reflash.**
- All ECU upgrades must be performed with the ignition set to the 'ON' position unless otherwise stated.
- **Damaged VCI II units should not be used and promptly replaced.**
- Be careful not to disconnect the VCI-II connected to the vehicle during the ECU upgrade procedure.
- **DO NOT start the engine during ECU upgrade.**
- DO NOT turn the ignition key 'OFF' or interrupt the power supply during ECU upgrade.
- **When the ECU upgrade is completed, turn the ignition 'OFF' and wait 10 seconds before starting the engine.**
- ONLY use approved ECU upgrade software designated for the correct application.

IMPORTANT

It is recommended to ALWAYS check the Electronic Parts Catalog (EPC) to locate the ECU Part Number respective to Auto/Manual Mode ROM IDs. DO NOT reference the parts label affixed to the ECU.

NOTICE


Before attempting an ECU upgrade on any Kia model, make sure to first determine whether the applicable model is equipped with an immobilizer  security system. Failure to follow proper procedures may cause the PCM to become inoperative after the upgrade and any claims associated with this repair may be subject to chargeback.

SUBJECT:

NU 2.0L GDI - KNOCK SENSOR DETECTION SYSTEM (KSDS) ECU LOGIC IMPROVEMENT (PI2107)

ROM ID INFORMATION TABLE:

Upgrade Event #578

Model	Model Year	SCC	Wheel Size	EM	IMMO 	ECU P/No.	ROM ID	
							Previous	New
PS (Nu 2.0L GDI)	2017	-	16"/17" Inch	ULEV	Yes	39131 2EHB0	GGPS HNUAQS00C00	GGPS HNUAQK00C00
					No	39133 2EHB0	GGPS HNUAPS00C00	GGPS HNUAPK00C00
				SULEV	Yes	39131 2EHB2	GGPS HNSAQS00C00	GGPS HNSAQK00C00
					No	39133 2EHB2	GGPS HNSAPS00C00	GGPS HNSAPK00C00
			18" Inch	ULEV	Yes	39131 2EHB4	GGPS HNUAQSROCO0	GGPS HNUAQKROCO0
					No	39133 2EHB4	GGPS HNUAPSR0CO0	GGPS HNUAPKROCO0
				SULEV	Yes	39131 2EHB5	GGPS HNSAQSROCO0	GGPS HNSAQKROCO0
					No	39133 2EHB5	GGPS HNSAPSR0CO0	GGPS HNSAPKROCO0
	2018	-	16"/17" Inch	ULEV	Yes	39131 2EHB6	GGPS INUAQS03C00	GGPS INUAQK03C00
					No	39133 2EHB6	GGPS INUAPS03C00	GGPS INUAPK03C00
				SULEV	Yes	39131 2EHB7	GGPS INSAQS03C00	GGPS INSAQK03C00
					No	39133 2EHB7	GGPS INSAPS03C00	GGPS INSAPK03C00
			18" Inch	ULEV	Yes	39131 2EHB8	GGPS INUAQSR3CO0	GGPS INUAQKR3CO0
					No	39133 2EHB8	GGPS INUAPSR3CO0	GGPS INUAPKR3CO0
				SULEV	Yes	39131 2EHB9	GGPS INSAQSR3CO0	GGPS INSAQKR3CO0
					No	39133 2EHB9	GGPS INSAPSR3CO0	GGPS INSAPKR3CO0


To verify the vehicle is affected, be sure to check the Calibration Identification of the vehicle's ECM ROM ID and reference the Information Table as necessary.



NU 2.0L GDI - KNOCK SENSOR DETECTION SYSTEM (KSDS) ECU LOGIC IMPROVEMENT (PI2107)

ROM ID INFORMATION TABLE (continued):

Upgrade Event #578

Model	Model Year	SCC	Wheel Size	EM	IMMO 	ECU P/No.	ROM ID	
							Previous	New
PS (Nu 2.0L GDI)	2019	-SCC	16"/17" Inch	ULEV	Yes	39131 2EHC6	GGPS JNUAQS02C00	GGPS JNUAQK02C00
					No	39133 2EHC6	GGPS JNUAPS02C00	GGPS JNUAPK02C00
				SULEV	Yes	39131 2EHC7	GGPS JNSAQS02C00	GGPS JNSAQK02C00
					No	39133 2EHC7	GGPS JNSAPS02C00	GGPS JNSAPK02C00
			18" Inch	ULEV	Yes	39131 2EHC8	GGPS JNUAQRS2C00	GGPS JNUAQKR2C00
					No	39133 2EHC8	GGPS JNUAPSR2C00	GGPS JNUAPKR2C00
				SULEV	Yes	39131 2EHC9	GGPS JNSAQRS2C00	GGPS JNSAQKR2C00
					No	39133 2EHC9	GGPS JNSAPSR2C00	GGPS JNSAPKR2C00
		+SCC	16"/17" Inch	ULEV	Yes	39131 2EHD6	GGPS JNUAQS01C01	GGPS JNUAQK01C01
					No	39133 2EHD6	GGPS JNUAPS01C01	GGPS JNUAPK01C01
				SULEV	Yes	39131 2EHD7	GGPS JNSAQS01C01	GGPS JNSAQK01C01
					No	39133 2EHD7	GGPS JNSAPS01C01	GGPS JNSAPK01C01
			18" Inch	ULEV	Yes	39131 2EHD8	GGPS JNUAQRS1C01	GGPS JNUAQKR1C01
					No	39133 2EHD8	GGPS JNUAPSR1C01	GGPS JNUAPKR1C01
				SULEV	Yes	39131 2EHD9	GGPS JNSAQRS1C01	GGPS JNSAQKR1C01
					No	39133 2EHD9	GGPS JNSAPSR1C01	GGPS JNSAPKR1C01

To verify the vehicle is affected, be sure to check the Calibration Identification of the vehicle's ECM ROM ID and reference the Information Table as necessary.

SUBJECT:

NU 2.0L GDI - KNOCK SENSOR DETECTION SYSTEM (KSDS) ECU LOGIC IMPROVEMENT (PI2107)

NOTICE

Prior to performing the ECU upgrade, be sure to check that the KDS is fully charged.

1. Connect the VCI-II to the OBD-II connector, located under the driver's side of the instrument panel.

NOTICE


The ECU upgrade function on KDS operates wirelessly. It is not necessary to perform the upgrade via USB cable.




2. With the ignition ON, turn ON the KDS tablet. Select 'KDS' from the home screen.



3. Confirm communication with VCI (A) and then configure the vehicle (B) using the 'AUTO VIN' (C) feature.



4. Select 'ECU Upgrade'.



**NU 2.0L GDI - KNOCK SENSOR DETECTION SYSTEM
(KSDS) ECU LOGIC IMPROVEMENT (PI2107)**

- The KDS will check the server for recently uploaded Events and then automatically download Upgrade Event #578.

NOTICE

The vehicle must be identified in Vehicle Selection to download an Event for that vehicle.

After the download is complete, the program will shut down to install. Please wait until the program restarts.

Event	Status
271.QF 2.4GDI DTC P0171,P0420 LOGIC IMPROVEMENT	Downloading
273.TF 2.4GDI DTC P0171,P0420 LOGIC IMPROVEMENT	Ready

36%

Do not touch any system buttons while performing this function.

KDS screenshot shown above is for demonstration purposes only. Events shown in screenshot are not applicable to this bulletin.

- Select Auto Mode.

CAUTION

Do NOT attempt to perform a Manual Mode upgrade UNLESS Auto Mode fails. Always follow the instructions given on the KDS in either Auto or Manual mode.

Auto Mode Manual Mode

- Select the ENGINE system under the System selection menu. Touch ID Check (D) and confirm that the latest update is available. Select Upgrade Event #578 and select Upgrade to continue.

System

ENGINE A/T

ROM ID

Currently in Vehicle ##### ID Check

Latest Update #####

Event Group TSB

###.XX ----

Previous Upgrade

- The ECU upgrade will begin and the progress of the upgrade will appear on the bar graph. Upgrade part (1/2) (E) will download the upgrade event to the VCI-II. Upgrade part (2/2) (F) will upgrade the ECU.

CAUTION

Do not touch the system buttons (like 'Back', 'Home', 'etc.') while performing ECU Upgrade.

E

23%

ECU Upgrading...(1/2)

ECU is in the process of being upgraded. Please wait a few minute.

F

6%

ECU Upgrading...(2/2)

ECU is in the process of being upgraded. Please wait a few minute.




SUBJECT:

NU 2.0L GDI - KNOCK SENSOR DETECTION SYSTEM (KSDS) ECU LOGIC IMPROVEMENT (PI2107)


9. If a "Communication Fail" screen appears, verify that the VCI-II and KDS are communicating properly. Select 'OK' and restart the procedure from step 4.

NOTICE


If an error notice continues to appear or if the upgrade cannot be performed, DO NOT disconnect the KDS/VCI-II. Contact GIT America Help Desk at (888) 542-4371 or Techline.




10. When instructed on the KDS, turn the ignition OFF for ten (10) seconds then back on. Select 'OK' to continue.



11. Once the upgrade is complete, select 'OK' to finalize the procedure.



12. When prompted, select 'YES' to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.



13. Start the engine to confirm normal operation of the vehicle.

NU 2.0L GDI - KNOCK SENSOR DETECTION SYSTEM (KSDS) ECU LOGIC IMPROVEMENT (PI2107)

Manual Upgrade Procedure:

NOTICE

The manual upgrade should ONLY be performed if the automatic upgrade fails.

If the automatic upgrade fails, turn the ignition 'OFF' for about 10 seconds then place it back in the 'ON' position to reset the control unit BEFORE performing manual upgrade.

See table below for 'Manual Mode' passwords.

Manual Mode ECU Upgrade Passwords

Menu	Password
PS Nu 2.0GDI AT ULEV +IMMO/SMK (17MY): 39131-2EHB0	3120
PS Nu 2.0GDI AT ULEV -IMMO (17MY): 39133-2EHB0	3121
PS Nu 2.0GDI AT SULEV +IMMO/SMK (17MY): 39131-2EHB2	3122
PS Nu 2.0GDI AT SULEV -IMMO (17MY): 39133-2EHB2	3123
PS Nu 2.0GDI AT ULEV +IMMO/SMK (17MY): 39131-2EHB4	3124
PS Nu 2.0GDI AT ULEV -IMMO (17MY): 39133-2EHB4	3125
PS Nu 2.0GDI AT SULEV +IMMO/SMK (17MY): 39131-2EHB5	3126
PS Nu 2.0GDI AT SULEV -IMMO (17MY): 39133-2EHB5	3127
PS Nu 2.0GDI AT ULEV +IMMO/SMK (18MY): 39131-2EHB6	3128
PS Nu 2.0GDI AT ULEV -IMMO (18MY): 39133-2EHB6	3129
PS Nu 2.0GDI AT SULEV +IMMO/SMK (18MY): 39131-2EHB7	3130
PS Nu 2.0GDI AT SULEV -IMMO (18MY): 39133-2EHB7	3131
PS Nu 2.0GDI AT ULEV +IMMO/SMK (18MY): 39131-2EHB8	3132
PS Nu 2.0GDI AT ULEV -IMMO (18MY): 39133-2EHB8	3133
PS Nu 2.0GDI AT SULEV +IMMO/SMK (18MY): 39131-2EHB9	3134
PS Nu 2.0GDI AT SULEV -IMMO (18MY): 39133-2EHB9	3135
PS Nu 2.0GDI AT ULEV -SCC +IMMO/SMK (19MY): 39131-2EHC6	3136
PS Nu 2.0GDI AT ULEV -SCC -IMMO (19MY): 39133-2EHC6	3137
PS Nu 2.0GDI AT SULEV -SCC +IMMO/SMK (19MY): 39131-2EHC7	3138
PS Nu 2.0GDI AT SULEV -SCC -IMMO (19MY): 39133-2EHC7	3139
PS Nu 2.0GDI AT ULEV -SCC +IMMO/SMK (19MY): 39131-2EHC8	3140
PS Nu 2.0GDI AT ULEV -SCC -IMMO (19MY): 39133-2EHC8	3141
PS Nu 2.0GDI AT SULEV -SCC +IMMO/SMK (19MY): 39131-2EHC9	3142
PS Nu 2.0GDI AT SULEV -SCC -IMMO (19MY): 39133-2EHC9	3143
PS Nu 2.0GDI AT ULEV +SCC +IMMO/SMK (19MY): 39131-2EHD6	3144
PS Nu 2.0GDI AT ULEV +SCC -IMMO (19MY): 39133-2EHD6	3145
PS Nu 2.0GDI AT SULEV +SCC +IMMO/SMK (19MY): 39131-2EHD7	3146
PS Nu 2.0GDI AT SULEV +SCC -IMMO (19MY): 39133-2EHD7	3147
PS Nu 2.0GDI AT ULEV +SCC +IMMO/SMK (19MY): 39131-2EHD8	3148
PS Nu 2.0GDI AT ULEV +SCC -IMMO (19MY): 39133-2EHD8	3149
PS Nu 2.0GDI AT SULEV +SCC +IMMO/SMK (19MY): 39131-2EHD9	3150
PS Nu 2.0GDI AT SULEV +SCC -IMMO (19MY): 39133-2EHD9	3151

SUBJECT:

**NU 2.0L GDI - KNOCK SENSOR DETECTION SYSTEM
(KSDS) ECU LOGIC IMPROVEMENT (PI2107)**

1. Within the ECU Upgrade screen displayed, select **Manual Mode**.
2. Select the **ENGINE** system under the System selection menu. Select **Upgrade Event #578** and select **Upgrade** to continue.
3. Select the appropriate control unit part number with reference to the ROM ID Information Table on page 3, and select **OK**.
4. Enter the appropriate password from the Manual Mode password table above and select **OK**.
5. The upgrade will begin and the progress of the upgrade will appear on the bar graph.
6. When instructed on the KDS, turn the ignition **OFF** for ten (10) seconds then back on. Select **OK**.
7. Once the upgrade is complete, select **OK** to finalize the procedure.
8. When prompted, select **YES** to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.
9. Start the engine to confirm proper operation of the vehicle.



NU 2.0L GDI - KNOCK SENSOR DETECTION SYSTEM (KSDS) ECU LOGIC IMPROVEMENT (PI2107)

SUBJECT:

AFFECTED VEHICLE RANGE:

Model	Production Date Range
Soul (PS)	July 29, 2016 to December 21, 2018

REQUIRED TOOL:

Tool Name	Figure	Comments
KDS		Kia Diagnostic System

WARRANTY INFORMATION:**N Code: X99 C Code: X99**

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
R	39171 2ELCO	0	(PI2107) KSDS Logic Improvement (PS)	210149R0	0.3 M/H	N/A	0

NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference PI2107 when accessing the WebDCS system.