

Subject:

A/C BLOWS WARM AIR OR NOT COLD ENOUGH

Service Alert No.: SA-053/21

Last Issued : 11/08/2021

BULLETIN NOTES

APPLICABLE MODEL(S)

2020-2021 CX-30 vehicles with VINs lower than 3MVDM******223943 (produced before Oct. 22, 2020)

DESCRIPTION

A customer may complain of poor A/C operation (either completely inoperative or not cold enough).

Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify the customer concern.

2. Inspect the A/C system operation according to MGSS online:

- TROUBLESHOOTING INDEX [MANUAL AIR CONDITIONER]
- TROUBLESHOOTING INDEX [FULL-AUTO AIR CONDITIONER]

- If the troubleshooting finds a low system charge, but no leaks are found in the A/C system, inspect the evaporator according to MGSS online EVAPORATOR INSPECTION [(US)].

- If an evaporator leak is found, replace the evaporator according to MGSS online A/C UNIT DISASSEMBLY/ASSEMBLY [(US)].

3. Confirm the entire HVAC system is operating properly.

PARTS INFORMATION

Parts Number	Description	Qty.	Notes
BDTS-61-J10	Evaporator	1	Verify the part number before installation.
BBM4-61-J17	O-ring	1	Verify the part number before installation.
****-61-J14	Expansion Valve	1	If expansion valve is leaking, replace it. Verify the correct part number using the VIN in GEPC.
555-FG-00*	Refrigerant	As	Verify the type and quantity required for subject vehicle. If

Page 1 of 2

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

© 2021 Mazda North American Operations, U.S.A.

Service Alert No.: SA-053/21 Last Issued : 11/08/2021	
---	--

Ne		ne label is missing, use the VIN in GEPC to determine if it s HFC-134a or HFO-1234yf.
----	--	--

NOTE: Refer to the Warranty Policy and Procedures Manual section 3.10 for the appropriate part number and instructions on how to claim refrigerant.

WARRANTY INFORMATION

Warranty Type	NVLM
Symptom Code	78
Damage Code	9К
Part Number Main Cause	BDTS-61-J10
Quantity	1
	U0604ARX (EVAPORATOR, R&R)
Operation Number / Labor Hours:	NOTE: Labor time varies slightly by VIN, look up the exact time using Warranty Wizard.

Page 2 of 2

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

© 2021 Mazda North American Operations, U.S.A.