



Volvo Chassis - Particulate Matter (PM) Sensor Diagnostic Trouble Codes (DTC) Illuminating The Malfunction Indicator Lamp (MIL); Tech Tip TT-014-2016 - US14+OBD16, US17+OBD16 And Newer Emissions, Common Model Year 2017 And Newer - To Be Used For EVER




> Internal Content

This Solution is relevant regardless of previous visits and sensor replacements. At this time, multiple sensor failures are not uncommon, regardless of how new the sensor is. The same procedure should be followed for every instance.

PLEASE NOTE: Instructions have been updated as of 20 June 2019. If diagnostics indicate that sensor replacement is required, please follow FSB 284 - 068 Exhaust Particulate Sensor, Repair (2016) or FSB 284 - 069 (2017) Exhaust Particulate Sensor, Repair. An eService case is not required

Precautions

1. The PM sensor is a smart sensor (12V supply and CAN lines) with an orientation tab as seen below:



Live UI

Installation torque of 50

NM +/- 5 NM

2. PM sensors need to be handled carefully. Dropping them most likely results in permanent damage to the sensor. Keep cap on the sensor until ready to install the sensor to avoid any contamination.

3. NEVER (DO NOT) apply anti-seize to install the PM sensor. *If for some reason someone applied it before this repair, thoroughly clean the threads and sealing surfaces while replacing the sensor.*

4. A removed PM sensor should be capped immediately (cap from replacement sensor) and packaged carefully, if returning to warranty or investigation purposes.


Repair

IMPORTANT:

- If a chassis arrives with a derate warning active, the PM sensor is not the source of the derate and there is a separate existing issue.
- **Prior to installing a new sensor for any of the steps below, gently shake the sensor and ensure it does not rattle. If noise is heard, another sensor should be used.**

1. Verify the chassis emissions level

- Details can be found in the Product Details box on the Product tab in PTT as seen below:



- **For US17+OBD16 (Common Rail Fuel System) Chassis setting**

Live UI **'24DA or P1031 ONLY:**

- Software improvements have been released to address this code.

Refer to CBR Solution **CBR-274**.

• **For US17+OBD16 Chassis setting any other codes for the PM Sensor**, Proceed with instructions below.

• **For US14+OBD16 (Commonly 2017 model year)**: Proceed with instructions below.

2. Check the DTC Status

Only troubleshoot PM sensor faults if the fault is *Active* or *Confirmed* as shown below.

Detailed status information	
Title ▲	Value
Confirmed DTC	True
Pending DTC	False

3. Follow the set of instructions for the relevant DTC(s):

• **P1033, P1034, P24D0 or U02A3 fault codes (*Confirmed* or *Active*)**

- These PM sensor fault codes require connections and wiring harness checks for power supply and CAN communications. Repair can be verified with just KEY ON as diagnostics run immediately.

- If wiring harness and connections check isolates the problem to the sensor:

1. Remove the sensor from the exhaust.
2. Obtain a new sensor. Gently shake the new sensor to ensure it does not rattle.
NOTE: A sensor that rattles should **not** be installed.
3. Install the new sensor.
4. Clear the DTCs and release the vehicle.

• **P1031 and P24DA (both fault codes and only these fault codes *Active*)**

1. Replace the PM sensor with the latest part. Gently shake the new sensor to ensure it does not rattle.
NOTE: A sensor that rattles should **not** be installed.
2. Update the Engine Control Module (EMS) software and clear all codes.

 Live UI ↴. Release the vehicle.

- If the PM sensor is the current part number:

1. Verify that the EMS software is current.
2. Remove the sensor from the exhaust.
3. Obtain a new sensor. Gently shake the new sensor to ensure it does not rattle.

NOTE: A sensor that rattles should **not** be installed.

4. Install the new sensor.
5. Clear the DTCs and release the vehicle.

• All other PM sensor fault codes (*Confirmed or Active*)

P24B3, **P24AF**, P2AB0, P24B1, P24B0, **P24DA**, P24B7, P24B5, P24D1, P24FC, **P24AE**, P24B4, and P1032. (Highlighted are common faults).

1. Verify that the EMS software is current.
2. Remove the sensor from the exhaust.
3. Obtain a new sensor. Gently shake the new sensor to ensure it does not rattle.

NOTE: A sensor that rattles should **not** be installed.

4. Install the new sensor.
5. Clear the DTCs and release the vehicle.

[p24b700](#)[p24d000](#)[p24da00](#)[p103200](#)[p24ae13](#)[p103400](#)[p249c00](#)[p24ae13](#)

p24af00	p24b000	p24b100	p24b313	
k47547856	p1031	p1032-00	p1033-00	
p1034-00	p249c-00	p24ae-13	p24af-00	
p24b0-00	p24b1-00	p24b3-13	p24b4-92	
p24b5-00	p24b7-00	p24d0-00	p24d1-00	
p24da-00	p24fc-00	p2ab0-47	p24b492	
p24b500	p24d100	p24fc00	p2ab047	volvo

Related links and attachments

No content available



Feedback

[Give feedback](#)

to help improve the content of this article