



Preliminary Information

PIT5039E Removing / Disabling Rear Park Assist RPO UD7

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Express	2013 - 2022	All	All	All	All
Chevrolet	Silverado	2007 - 2013	All	All	All	All
Chevrolet	Silverado 2500/3500	2014	All	All	All	All
GMC	Savana	2013 - 2022	All	All	All	All
GMC	Sierra	2007 - 2013	All	All	All	All
GMC	Sierra 2500/3500	2014	All	All	All	All

With Rear Park Assist (RPO UD7)

Supersession Statement

This PI was superseded to add Express/Savana Models and update model years.. Please discard PIT5039D.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

Some customers / upfitters may remove the rear bumper, install a different rear bumper, or add a different box/flat bed/cube box/hitch, etc. to the rear of the truck, which affects the rear park assist operation.

Recommendations / Instructions

In these cases, the rear park assist option can be removed from the vehicle. Follow the instructions below for the model year of the vehicle involved:

- 1) On all model years, disable the Park Assist Module (Note: In most cases, for Silverado / Sierra removing the OBS DET fuse 20 (10 amp) from the Left I/P fuse block and Express / Savana removing OBS DET fuse 33 (10 amp) from Underhood fuse block will work).
- 2.a) For 2007-2009 models, contact Techline Customer Support Center (TCSC: 800-828-6860) to obtain an IPC calibration to disable the option.

2.b) For 2010-2022 models, remove power to the IPC for several minutes and then reconnect (disconnecting the battery will work).
When power is reconnected the IPC will not see the Park Assist Module on the low speed data buss (because it was disabled in Step 1), thus reconfiguring the IPC without Park Assist. After this is complete there will be no Park Assist Warning Messages displayed.

Warranty Information

As the associated vehicle was modified outside of production specifications, labor associated with these procedures should NOT be charged under warranty.

Rather, this should be customer pay.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



GENERAL MOTORS

© 2021 General Motors. All Rights Reserved.