167 GLE/GLS and 167 Maybach with M177LS2 - CEL for P218762/P218797/P218962/P218997: The mixture is too lean at idle speed (Bank 1/ Bank 2)

Topic number LI07.61-P-072259

Version 3

Function group 07.61 - ME fuel injection/ ignition system

Date 8/5/21

Validity All AMG 167 models with M177LS2.

All Maybach 167 models with M177LS2

Reason for change Software availability

Complaint

Customer complains that check engine light is on.

Cause

A gross increase in the vehicle's ORA (idle fuel adaptations) is observed in conjunction with a code setting and the CEL activating.

Remedy

If the vehicle has one or more of the listed codes stored in the ME, update the ME control unit via Xentry.

The table "Software by Baumuster" in the attachments provides the software numbers that should be present after the update.

Upon completing the update please perform the following:

- Clear the mixture adaptations in the ME control unit
- Perform an AMG engine adaptation drive per the AMG User's Guide (provided in the attachments)
- Afterwards drive the vehicle normally in "C" mode with ECO disabled for a distance of ~35 miles
- Check the injector performance data.
- You may release the vehicle if ALL of the following conditions are met:
- FRA and FRA2 are both below 1
- ORA and ORA2 are both below 1.2
- There is at least one injector per bank reporting an adaptation
- If any of the conditions are not met, drive the vehicle again in "C" mode with ECO disabled for a distance of ~35 miles
- If the data remains the same or does not improve, OR other codes appear during the follow up operations STOP and open a PTSS case
- Include the following in the case:
- Initial quick test with fault freeze

XENTRY TIPS

- ME control unit log Latest Injector performance data

Attac	Attachments									
File										
AMG	AMG User Guide.pdf									
Software by Baumuster.JPG										
Model	Baumuster	Hardware Part Number	Software Part Number	Software Part Number	Boot Software					
GLS63	167.989	177 901 6603	177 902 16 09	177 903 52 05	177 904 96 00					
GLE63	167.188	177 901 6603	177 902 16 09	177 903 52 05	177 904 96 00					
GLE63	167.989	177 901 6603	177 902 16 09	177 903 52 05	177 904 96 00					
GLE63	167.388	177 901 6603	177 902 16 09	177 903 52 05	177 904 96 00					
	167.389	177 901 6603	177 902 16 09	177 903 52 05	177 904 96 00					
GLE63	107.389	177 301 0003	177 302 10 03	177 300 02 00	1,, 30, 30, 00					

Symptoms Power generation > Engine management > Indicator lamp > Engine diagnosis > lit

Control unit/fault code							
Control unit	Fault text						
N3/10 - Motor electronics 'MED1775' for combustion engine 'M176/M177/M178' (ME)	an. The system function is restricted.						
	P218797 - The mixture (cylinder bank 1) is too lean at idle speed. The system function is restricted.						
N3/10 - Motor electronics 'MED1775' for combustion engine 'M176/M177/M178' (ME)	P218962 - The mixture (cylinder bank 2) at idle is too lean. The signal comparison is faulty.						
	P218762 - The mixture (cylinder bank 1) is too lean at idle speed. The signal comparison is faulty.						

Operation numbers/damage codes									
Op. no.	Operation text	Time	Damage code	Note					