

McLAREN ELVA– FACIA BLOCK FIXING REWORK

Bulletin type:	Service Campaign
Campaign reference:	SCB 26 N 001
Attention:	Retailer Service Managers, Retailer Service Advisors, Retailer Technicians
Affected vehicles:	McLaren Elva
Situation:	Potential bolt relaxation on retention fixings of upper and lower facia block assembly
Procedure:	Action affected vehicles on next Retailer visit
Date:	16 th December 2021

This bulletin will cover:

1. Overview
2. Parts Information
3. Procedure
4. Warranty Information
5. Affected Vehicles

1. Overview

Through continuous product quality monitoring, McLaren Automotive has identified a bolt torque relaxation condition that could affect the upper and lower facia block retention fixings in some McLaren Elva vehicles. A potential relaxation of those fixings may have an adverse effect on panel gap which can influence the knee airbag deployment profile. Therefore, a facia block fixing rework procedure has been released for all affected vehicles.



View of the upper and lower passenger facia blocks

2. Parts Information

The below parts are required to complete this rework. All parts are available to order via Unipart.

PART NUMBER	PART DESCRIPTION	QUANTITY REQUIRED
-------------	------------------	-------------------

00RA774

Bolt - M5 x12

6

3. Procedure

To perform the facia block fixing rework, Document SCB 26 N 001 WI has been attached with this Bulletin. This Document contains the relevant work instructions and care points to ensure the required work is carried out to bring the vehicle up to the latest manufacturing standard.

4. Warranty Information

Submit a claim to the Warranty department following completion of the work, using the details below.

McLaren Elva – Facia Block Fixing Rework:

LABOUR TIME DESCRIPTION	REPAIR TIME
Pre works	0.05 hours
Rework	0.15 hours

Care Point: The work instructions and related labour times may be different from work instructions in the Service Information System (SIS). When you do this work you must refer only to the advice in this Bulletin.

5. Affected vehicles

Affected vehicles will be flagged in the Retailer Portal when next opening a Workshop Visit related to the vehicle. Your Regional Aftersales Manager will contact you with a list of affected vehicles.

If you have any questions, please contact your Regional Aftersales Manager.

The information contained in McLaren bulletins is for internal use only by McLaren Authorised Retailers and must not be published on external websites or social media forums etc.

Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle. Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.