



SERVICE BULLETIN

Classification: BT21-027	Reference: NTB21-118	Date: December 17, 2021
-----------------------------	-------------------------	----------------------------

RESIDUE ON OUTER SURFACE OF FRONT DOOR GLASS

- APPLIED VEHICLES:** 2022 Frontier (D41)
APPLIED GRADES: SV with Convenience Package
All PRO-X and PRO-4X
APPLIED SYSTEMS: All vehicles with external Intelligent Key door request switches

IF YOU CONFIRM

Adhesive residue is found on the outer surface of front driver (LH) side and/or front passenger (RH) side window glass.

ACTION

Follow the service procedure in this bulletin to:

1. Remove the door finisher on the affected side.
2. Confirm that the Intelligent Key door request switch wiring harness is contacting the glass.
3. Reroute the harness as needed.
4. Confirm that the harness is no longer contacting the glass.

IMPORTANT: The purpose of ACTION (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire SERVICE PROCEDURE as it contains information that is essential to successfully completing this repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

1. Remove the door finisher on the affected side.
 - Refer to the **ESM: BODY INTERIOR > INTERIOR > REMOVAL AND INSTALLATION > DOOR FINISHER**
2. Inspect the routing of the Intelligent Key request switch wiring harness and confirm if it is routed as shown in Figure 1.
 - If routed as shown in Figure 1, proceed to step 3.
 - If routed as shown in Figure 2, skip to step 5.




Figure 1

Figure 2

3. Reroute the harness behind the outside handle cable, as shown in Figure 2.
4. Confirm that neither the harness or cable are no longer contacting the glass.
5. Reassemble the door finisher.

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Reroute Intelligent Key Wiring Harness on Left Front (LH) Side Door	(1)	RX0VAA	ZE	32	0.2

- (1) Reference the electronic parts catalog and use the Front Door Handle Assembly LH (806B1-*****) as the Primary Failed Part (PFP).

AND/OR On a Separate Line

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Reroute Intelligent Key Wiring Harness on Right Front (RH) Side Door	(1)	RX0WAA	ZE	32	0.2

- (1) Reference the electronic parts catalog and use the Front Door Handle Assembly RH (806B0-*****) as the Primary Failed Part (PFP).

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
December 17, 2021	NTB21-118	Original bulletin published