



S.A.T.	268 MV
area	n°

Service Bulletin

Service Bulletin - Technisches Rundschreiben - Circulaire Technique - Circular Tecnica

Date: **23rd April 2021**

Subject: **New ECU software update**

Product: **Brutale 800 RR Euro 5**
VIN up to

.....**MV000200**

It cancels and replaces the Service Bulletin no.: --- (first update for this model)

We inform you with this Service Bulletin that new ECU calibrations for Brutale 1000 Serie Oro – RR and Rush are available.

The contents of the new maps introduce the following changes:

- Improved Cruise Control set-up
- Improved management of the oil pressure warning light
- Other minor improvements

It is necessary verifying, and, if needed, updating the control unit during the pre-delivery phase, during a maintenance service or on the first useful occasion at your workshop.

Issues on motorcycles related to outdated software or software intended for another vehicle could affect the approval of warranty claims, therefore we ask you for particular attention in ALWAYS updating motorcycles in transit at your workshop.

It is recommended to pay the utmost attention in choosing the correct mapping for the model and version of the motorcycle concerned.

For any doubt regarding the choice of the correct mapping, it is recommended to contact your MV Agusta technical manager or the MV Agusta Technical Assistance dept.

The installation of a mapping different from that provided for the on the motorcycle concerned, will be the exclusive responsibility of the dealer performing the update.

MV AGUSTA MOTOR S.p.A. therefore disclaims any responsibility for any consequence (civil and / or criminal and / or administrative) that the dealer or third parties could sustain due to the modification of the ECU (ECU mapping) and / or a different use of the motorcycle that is in contrast with the limits and prohibitions provided for by local law and by the regulation relating to the approved power of motorcycles that are intended for use on public roads.

TOOLS REQUIRED TO PERFORM THE INTERVENTION:

- Diagnosis tool **TEXA Navigator**
- PC equipe with TEXA Software **IDC5**
- Cable **3151/AP34**.

ECU UPDATE PROCEDURE:

- Update your TEXA Navigator diagnosis tool by connecting the computer with IDC5 software to internet, select "Software Update" and start the download to download version **34.0.3.a \ MAP 3251** or later versions.

- Verify that the battery voltage is greater than 12.5V and keep the original battery charger connected for the entire duration of the update.

- Connect the TEXA diagnosis system by following the path:

MOTO – MV AGUSTA – Brutale 800 RR – [--/21>].

- Select "**ECU Update**" then "**Injection Reprogramming**" and finally the **ELDOR** control unit

- Connect the motorcycle following the instructions of the program and select "**MAPPING**".

The installation of the new mapping requires the presence of the boot **BTMV6D-0700** in the control unit: check for the presence of the **BTMV6D-0700**; if the control unit is not equipped with the boot described above, contact the MV Agusta technical assistance service.

Install the new ECU map by selecting the file for your market:

Brutale 800 RR Euro 5 :

Version	Software	Password
Europa	B3800RR_1102UE14	NEMO#14f4uk21
USA / Canada	B3800RR_1102US14	NEMO#14prrr21
Corea	B3800RR_1102KR14	NEMO#14f3zw21
Kit racing exhaust	B3800RR_1102KY14	To be requested to Technical Assistance Service

then follow the instructions of the program to complete the installation.

- At the end of the procedure, check the code of the installed calibration / map version in the "INFO ECU" menu.

- Exit the "ECU Update" environment and open the "Self-diagnosis" environment.

- Select "petrol injection" and control unit model

- Select "Settings" and then "Reset self-adaptive parameters" and follow the instructions of the program

- Start the engine and leave it to idle until the radiator cooling fan will be activated.

- Test the motorcycle on the road before delivering it to the customer to verify correct operation.

IMPORTANT NOTE:

In case of replacement of the ECU, or if the system does not recognize the presence of the EAS, reset the vehicle configuration through the "Vehicle configuration learning" adjustment in the IDC5 self-diagnosis in the "Adjustments" section, in order to detect its presence and allow correct operation.

Thanking you in advance for your collaboration, we remain at your disposal for any support.

Best regards

MV AGUSTA MOTOR S.p.A.

Technical Assistance Service