



NUMBER: 05-002-21

GROUP: 05 - Brakes

DATE: January 28, 2021

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

SUBJECT:

Uneven Front Brake Pad Wear

OVERVIEW:

This bulletin involves inspecting the front brake pads for uneven wear and it involves re-torquing front brake fasteners and checking for proper caliper slide action.

MODELS:

2019 - 2020

(DJ)

RAM 2500 Pickup

NOTE: This bulletin applies to vehicles within the following markets/countries: LATAM.

SYMPTOM/CONDITION:

The customer may comment on the following:

• Unusual noise when braking, likely a grinding noise as though pads are worn out.

DIAGNOSIS:

If the customer describes the symptom/condition listed above, perform the Diagnosis Procedure.

- Raise and support the vehicle. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info: 04 - Vehicle Quick Reference/Hoisting -Standard Procedure.
- 2. Remove both front wheel and tire assemblies. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info: 22 Tires and Wheels/Removal and Installation.
- 3. Inspect the front brake pads. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info: 05 Brakes / 05 Brakes, Base / Hydraulic/Mechanical / Pads, Brake, Front / Inspection.
- 4. Do the brake pads show uneven wear from inboard side to the outboard side?
 - YES>>> Proceed to Step 1 of the repair procedure.
 - NO>>> This Bulletin does not apply. Normal diagnosis should be performed. Proceed to Step 5 of Diagnosis Procedure.
- 5. Install both front wheel and tire assemblies. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info: 22 Tires and Wheels/Removal and Installation.

05-002-21 -2-

PARTS REQUIRED:

Qty.	Part No.	Description
(AR)	68414882AB	Front Rotor
(AR)	68049153AB	Pin Kit
1 (AR)	68461656AB	Front Pad Kit

REPAIR PROCEDURE:

 Replace the front brake pads. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info: 05 - Brakes / 05 - Brakes, Base / Hydraulic/Mechanical / Pads, Brake, Front / Removal and Installation.

NOTE: If the pads wore into the rotors, replace if necessary. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info: 05 - Brakes / 05 - Brakes, Base / Hydraulic/Mechanical / Rotor, Brake / Removal and Installation

- 2. Were the front rotors replaced?
 - YES>>> Proceed to Step 3 of the repair procedure.
 - NO>>> Torque caliper adaptor bolts to new spec of 380 N·m (280 ft lbs) and proceed to Step 4 of the Repair Procedure.
- 3. Reinstall the front brake caliper bracket. Torque caliper adaptor bolts to new spec of 380 N·m (280 ft lbs).
- 4. Remove excess air from guide pin boots, by sliding pin in and out several times, making sure not to dislodge the boots.
- 5. Check the correct position of the guide pins (Fig. 1).




Fig. 1
Front Brake Components

- 1 Guide Pin
- 2 Front Caliper Bracket
- 3 Front Caliper

6. Install caliper to adaptor, snug upper pin bolt to 20 N·m (15 ft lbs) first, then snug lower pin bolt to 20 N·m (15 ft lbs).

-3-

- 7. Final torque the upper pin bolt to 75 N·m (55 ft lbs) first, then torque lower pin bolt to 75 N·m (55 ft lbs).
- 8. Confirm front brake caliper slides inward and outward with hand force (Fig. 2) .

NOTE: If the front brake caliper is locked, loosen the lower guide pin bolt, reset the torque to 75 N·m (55 ft lbs) and check front brake caliper sliding again.



Fig. 2
Check Front Caliper Side to Side Movement

- 9. Does the caliper slide freely?
 - YES>>> Proceed to Step 10 of the Repair Procedure.
 - NO>>> Replace guide pins/boots and proceed to Step 4 of the Repair Procedure.
- 10. Install both front wheel and tire assemblies. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info: 22 Tires and Wheels/Removal and Installation.

05-002-21 -4-

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
05-70-22-9U	Pad, Disc Brake Front - Replace (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.7 Hrs.

	Related		
05-70-22-5E	Rotor, Disc Brake Front - Replace	6 - Electrical and	0.1 Hrs.
	(1 - Semi-Skilled)	Body Systems	

FAILURE CODE:

_	7	O ' A '
		Service Action
		00171007101011