



**NUMBER:** 08-128-21

**GROUP:** 08 - Electrical

**DATE:** August 5, 2021

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**SUBJECT:**

Flash: Memory Seat Module - Driver (MSMD) Updates

**OVERVIEW:**

This bulletin involves reprogramming the MSMD with the latest available software.

**MODELS:**

2021 (WL) Jeep Grand Cherokee

**NOTE:** This bulletin applies to vehicles within the following markets/countries: North America, APAC, LATAM and EMEA.

**NOTE:** This bulletin applies to vehicles built on or before June 21, 2021 (MDH 0621XX) equipped with Driver Seat Memory (Sales Code LEQ).

**SYMPTOM/CONDITION:**

Customers may experience the following:

- Drivers massage seats do not recall lumbar and bolster position when profile selected on radio (Recall from door switches and keyfob work as expected).

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the one listed are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

**REPAIR PROCEDURE:**

**NOTE:** Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

**NOTE:** If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the MSMD module with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
2. Using wiTECH, perform a proxi configuration alignment. This routine is available under the 'Diagnostic Procedures' tab found on the home, 'Vehicle View', page of wiTECH.
3. Go to the MSMD in the vehicle topology, go to Misc Functions, Perform the "Calibration/Standardization MSMD. Follow the wiTECH Prompts.
4. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
18-52-33-94	Module, Memory Seat (Driver) - Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.

**NOTE:** The expected completion time for the flash download portion of this procedure is approximately 2 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

**FAILURE CODE:**

The dealer must use failure code CC with this Service Bulletin.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Service Bulletin flash/reprogramming conditions.

CC	Customer Concern
----	------------------