



NUMBER: 08-020-21

GROUP: 08 - Electrical

DATE: February 2, 2021

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Technical Service Bulletin (TSB) 08-103-20 REV. A, date of issue December 18, 2020, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include an updated build date, software enhancements to existing Diagnostic Trouble Codes (DTCs) and LOPs.

This Technical Service Bulletin (TSB) has also been released as a Rapid Response Transmittal (RRT) 20-096, date of issue December 18, 2020. All applicable Un-Sold RRT VINs have been loaded. To verify this RRT service action is applicable to the Un-Sold vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. This RRT will expire 18 months after the date of issue.

SUBJECT:

Flash: Drive Style Control Module (DSCM) Updates

OVERVIEW:

This bulletin involves checking if the vehicle dynamic (DNA) selector is operable and possibly reprogramming the DSCM with the latest available software.

MODELS:

2020 (GU) Alfa Romeo Stelvio

NOTE: This bulletin applies to vehicles within the following markets/countries: North America and EMEA.

NOTE: This bulletin applies to vehicles built on or before ****December 11, 2020 (MDH 1211XX)****.

SYMPTOM/CONDITION:

Customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find that one or more of the following DTCs have been set in the Drive Style Control Module (DSCM):

- ****U1700-87** - Body Control Module (BCM) - Missing Message.
- U0011-14 - Down Rotary Knob Failure-Circuit Short To Ground Or Open.
- U0011-15 - Down Rotary Knob Failure-Circuit Short To Battery Or Open.
- U0012-14 - Up Rotary Knob Failure-Circuit Short To Ground Or Open.
- U0012-15 - Up Rotary Knob Failure-Circuit Short To Battery Or Open.
- B1603-68 - Rotary Encoder Fault-Event Information.**

The following DTC has been set in the Body Control Module (BCM):

- ****U1A18-87** - DSCM (Drive Style Control Module) - Missing Message.**

The customer may also comment on the following:

- The vehicle dynamic (DNA) selector is inoperable.

DIAGNOSIS:

Using a Scan Tool (wiTECH 2) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If any DTCs or symptom/conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary, before proceeding further with this bulletin.

NOTE: The DNA driving mode selector will be inoperative if the vehicle has an active check engine light. Refer to the appropriate diagnostic information to correct the condition.

If a customer's VIN is listed in VIP or your RRT VIN list, perform the Inspection Procedure. If any vehicle not on the VIN list exhibits the symptom/condition or DTC, perform the Inspection Procedure.

1. Open the trunk, leave it open and make sure all other doors are closed.
2. Verify that the Instrument Panel Cluster (IPC) times out in the key-off position.
3. Wait a minimum of **four minutes** without opening or closing any doors.
4. Disconnect and isolate the negative battery cable. **Wait one minute.**
5. Connect the negative battery cable.
6. Clear all DTCs that may have been set.
7. Verify if the DNA selector is now functioning properly and is operable.
8. Is the DNA selector operable?
 - YES>>> Proceed to [Step 1](#) of the Repair Procedure.
 - NO>>> This bulletin has been completed, use the Inspection LOP (18-19-22-96) to close the active RRT.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the DSCM with the latest software. Detailed instructions for flashing control modules using the wiTECH 2 Diagnostic Application are available by selecting the application's "HELP" tab.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH 2 application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
**18-19-22-96	Modules, Drive Style Control (DSCM) - Inspect (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
18-19-22-97	Modules, Drive Style Control (DSCM) - Inspect and Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.**

NOTE: The expected completion time for the flash download portion of this procedure is approximately 1 minute. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

The dealer must choose which failure code to use depending on if this is a Rapid Response Transmittal (RRT) or Service Bulletin.

- The “RF” failure code is required for essential module flash/reprogramming and can only be used after confirmation that the VIN is included on the RRT.
- The failure code “RF” (Required Flash) can no longer be used on Service Bulletin flashes. **The “RF” failure code must be used on an RRT.**
- If the customer’s concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used. When utilizing this failure code, the 3C’s must be supplied.

RF	Required Flash - RRT
CC	Customer Concern