



NUMBER: 08-028-21

GROUP: 08 - Electrical

DATE: March 2, 2021

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Technical Service Bulletin (TSB) 08-088-19, date of issue August 28, 2019, which should be removed from your files. All revisions are highlighted with **asterisks**** and include an additional market, symptom/condition and LOP.**

This Technical Service Bulletin (TSB) has also been released as a Rapid Response Transmittal (RRT) 18-129, date of issue November 17, 2018. All applicable Sold and Un-Sold RRT VINs have been loaded. To verify this RRT service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RRT will expire 18 months after the date of issue.

SUBJECT:

Flash: Body Control Module (BCM) Updates

OVERVIEW:

This bulletin involves reprogramming the BCM with the latest available software.

MODELS:

2019 (BV) Jeep Renegade

NOTE: This bulletin applies to vehicles within the following markets/countries: North America, EMEA and **APAC.******

SYMPTOM/CONDITION:

Customers may notice after locking the car, two horn chirps are heard, under normal operation only one horn chirp is heard. Upon further investigation the technician may find the following Diagnostic Trouble Code (DTC):

- U1413-09 - UAM (Ultrasonic and Anti-tilt Module) - Component Failures. **equipped with Premium Security Alarm (LSC Sales Code only).**

In addition, the customer may notice one or more of the following:

- ****Message on the cluster - Headlamp (low beam) is out but the headlamps are all functioning properly. equipped with Bi-Function LED Projector Headlamps (LM6 Sales Code only).****
- Brake lights will intermittently remain on (Only one side which clears and functions normally with a brake apply or ignition cycle).
- Rear windows are inoperative and will not roll down.
- Intermittently, unable to turn on high beam headlights.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. If any vehicle not on the VIN list exhibits the symptom/condition and the technician finds the DTC, perform the repair.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Check the BCM software version to see if it is the latest available.
2. Is the BCM software the latest available?
 - YES >>> This bulletin has been completed, use inspect LOP (18-19-02-F2) to close the active RRT.
 - NO >>> Proceed to [Step 3](#).
3. Reprogram the BCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
4. Using wiTECH, restore configuration and align proxi. This routine is available under the 'Diagnostic Procedures' tab found on the home, 'Vehicle View', page of wiTECH.
5. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-02-F2	Module, Body Control (BCM) - Inspect (0 - Introduction)	6 - Electrical And Body Systems	0.2 Hrs.
18-19-02-FT	Module, Body Control (BCM) - Inspect and Reprogram (0 - Introduction)	6 - Electrical And Body Systems	0.3 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 4 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

The dealer must choose which failure code to use depending on if this is a Rapid Response Transmittal (RRT) or Service Bulletin.

- The “RF” failure code is required for essential module flash/reprogramming and can only be used after confirmation that the VIN is included on the RRT.
- The failure code “RF” (Required Flash) can no longer be used on Service Bulletin flashes. **The “RF” failure code must be used on an RRT.**
- If the customer’s concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used. When utilizing this failure code, the 3C’s must be supplied.

RF	Required Flash - RRT
CC	Customer Concern