



15-22-01TT - Camshaft Timing Faults P0011, P0014, P0016, P0341, P0017 after Engine or Cylinder Head Replacement

Release date: 1/21/2022

## Condition

**ATTENTION:**

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.  
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

## Applicable Vehicles

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta	2013-2022	1.4L (CNLA, CZTA,DGXA, DJXA)	All	All	All

## Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2065888/1	1/21/22	15-22-01TT	Original publication.

## Technical Background:

The technician may find camshaft timing faults after a cylinder head or engine replacement. The cam adjuster spacer tubes may not have been transferred from the original engine or cylinder head.

## Service:

If camshaft timing faults are encountered after engine or cylinder head replacement, check for cam adjuster spacer tubes on the camshafts of the original engine. Usually there are not provided on the replacement engine (Figure 1).



15-22-01TT - Camshaft Timing Faults P0011, P0014, P0016, P0341, P0017 after Engine or Cylinder Head Replacement

Release date: 1/21/2022



Figure 1

## Additional Information

© 2022 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.