



# Technical Service Bulletin

**57 Power closing door latch is intermittently inoperative, door adjustment is required**  
**57 22 89 2058159/4 January 19, 2022. Supersedes Technical Service Bulletin Group 57 number 21-83**  
**dated September 15, 2021 for reasons listed below.**

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7 and SQ7	2016 – 2023	All	Power closing door latch

## Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised header (Added Model Year 2023)
3	09/15/2021	Revised header (Added Model Years 2020 - 2022)
2	02/06/2020	Revised title Revised <i>Condition</i> (Added DTC information)
1	01/08/2020	Initial publication

### Customer states:

- The power closing door latch system intermittently does not work and the electronic parking brake warning is displayed in the instrument cluster.
- The door closes and latches properly otherwise.

### Workshop findings:

- The door striker stops in the pre-latch position and the door is not closed via the power closing door system.
- No relevant DTC's are stored in the door control modules.

## Technical Background

The door latch requires counter-pressure from the door/door seal, in order to generate a reliable signal for the door control module that the customer wants to close the door. If the door striker is adjusted in such a way that



# Technical Service Bulletin

---

does not provide enough counter-pressure for the latch, the door control module does not recognize the door latch signal long enough or at all. Hence the door will not be closed.

## Production Solution

### Service

Before performing any repairs as outlined in this TSB, please check any applicable TSBs (e.g. TSB 2051540: *57 Power closing door latch is intermittently inoperative* for MY18) to ensure that the door control modules have the latest software levels installed. Perform any software update related TSBs prior to proceeding with this TSB.

If the customer concern persists with the latest door control module software installed, perform the following steps:

Check the door striker to latch alignment and perform any adjustments necessary to center the striker to the latch.



# Technical Service Bulletin

---

At the same time, adjust the door striker inward as far as possible (at least 0.5 mm) (Figure 1). The front door can be flush or slightly under flush to the rear door without causing a wind noise concern (Figure 2).



*Figure 1. Adjust door striker inward by at least 0.5 mm.*



# Technical Service Bulletin

---



*Figure 2. The front door can be flush or slightly under flush to the rear door.*

Recheck the functionality of the power closing door latch system. If after the striker adjustment the door closes properly, do not proceed with any additional repairs.



# Technical Service Bulletin

---

If the customer concern persists, install a new outer door seal with an inward offset of 1.0 mm when compared to the original door seal location (Figure 3).



**Tip:** Mark the position of the original outer door seal before replacing it.



*Figure 3. Install the new outer door seal with an inward offset of 1.0 mm.*



# Technical Service Bulletin

---

## Warranty

Claim Type:	<ul style="list-style-type: none"> <li>• 110 up to 48 Months/50,000 Miles.</li> <li>• G10 for CPO Vehicles – Verify Owner.</li> <li>• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li> </ul>		
Service Number:	<ul style="list-style-type: none"> <li>• 5741</li> <li>• 5841</li> </ul>		
Damage Code:	0016		
Labor Operations:	Front striker plate adjust	5725 1500	See SRT with associated operations
	Rear striker plate adjust	5825 1500	See SRT with associated operations
	Front door outer seal remove + reinstall	5765 1955	See SRT with associated operations
	Rear door outer seal remove + reinstall	5864 1950	See SRT with associated operations
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU



# Technical Service Bulletin

---

Claim Comment:	As per TSB 2058159
----------------	--------------------

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
4M0837911C	Front outer door seal	0-2
4M0839911C	Rear outer door seal	0-2

## Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

- TSB 2051540: *57 Power closing door latch is intermittently inoperative.*

All part and service references provided in this TSB (2058159) are subject to change and/or removal.

©2022 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.