

#### 90 Instrument cluster: trip odometer and/or clock sporadically resets to zero 90 22 39 2064301/2 January 28, 2022. Supersedes Technical Service Bulletin Group 90 number 21-12 dated August 19, 2021, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2021	All	All

### Condition

REVISION HISTORY					
Revision Date Purpose		Purpose			
2	-	Revised service (corrected update table)			
1	08/19/2021	Initial publication			

#### **Customer states:**

• The trip odometer and/or the clock in the instrument cluster will sporadically reset to zero (Figure 1).



Figure 1. Clock and trip odometer reset to zero.

## **Technical Background**

A software issue in the instrument cluster can cause it to reset on start-up clearing the clock and trip odometer.

## **Production Solution**

© 2022 Audi of America, Inc.

#### Page 1 of 4

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Not applicable.

### **Service**

This TSB replaces Pending Service Solution (PSS) TSB 2062440: PSS 90 Instrument cluster clock and trip odometer reset to midnight or zero – MY21.

#### **Required equipment:**

- ODIS Tester.
- SVM code.

#### Time to complete update:

Approximately 30-60 minutes (includes 20-50 minutes for the software update and 10 minutes for the SVM work).

#### Service work:

• Affix the vehicle key to the key reader coil before starting the update (for example with adhesive tape), then turn on the ignition (Figure 2).



Figure 2. Key reader coil location.

© 2022 Audi of America, Inc.

- 1. Follow all instructions in TSB 2011732: 00 Software Version Management (SVM), operating instructions.
- 2. Update the instrument cluster, J285 (address word 0017) using the SVM action code as listed in the table below, if necessary:

# All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Page 2 of 4



**Wote:** The display of the instrument cluster might be completely black during the update. This is normal. The display content will reappear after the update is completed.

Model	Old Software Part Number	Old Software Version	New Software Part Number (or higher)	New Software Version (or higher)	SVM Code Input
	83A920700C 83A920800C	5165	83A920700C 83A920800C	5200	
Q3	83A920700D 83A920800D 83A920704B	5320	83A920700D 83A920800D 83A920704B	5400	17A038

### Warranty

Claim Type:	<ul> <li>110 up to 48 Months/50,000 Miles.</li> <li>G10 for CPO Covered Vehicles – Verify Owner.</li> <li>If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li> </ul>					
Service Number:	9025					
Damage Code: 0039						
Labor Operations:	Software Update (Includes checking for DTCs)	0151 0000	Time stated on the diagnostic protocol (Max 100 TU)			
Diagnostic Time:	GFF	No allowance	0 TU			
	Road test prior to the service procedure	No allowance	0 TU			
	Road test after the service procedure	No allowance	0 TU			
Claim Comment:	mment: As per TSB 2064301					

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual.* Claims are subject to review or audit by Audi Warranty.

## **Required Parts and Tools**

© 2022 Audi of America, Inc.

Page 3 of 4

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



## **Additional Information**

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

• TSB 2011732: 00 Software Version Management (SVM), operating instructions.

All part and service references provided in this TSB (2064301) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair. **©2022 Audi of America, Inc.** All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

<sup>© 2022</sup> Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.