



SIB 37 01 21

2022-01-31

**SELF LEVELING FAULT 80422D STORED IN BODY DOMAIN  
CONTROLLER (BDC)**

This Service Information Bulletin (Revision 2) replaces SI B37 01 21 **dated September 2021**.

**What's New** (Specific text highlighted):

- Situation
- Correction
- Procedure

**MODEL**

E-Series	Model Description	Production Date
G05	X5 Sports Activity Vehicle	From June 28, 2021 to August 31, 2021
G06	X6 Sports Activity Coupe	From June 28, 2021 to August 31, 2021

**SITUATION**

After performing vehicle test, fault code 80422D "self-leveling suspension missing slave" will not clear.

Only applies to vehicles that do **NOT** have options:

- S2VR- 2 axle air suspension
- S3E3 – X offroad package

And **WITH** I-levels greater than or equal to S18A-21-03-567 or less than or equal to S18A-21-03-565.

**CORRECTION**

Program the vehicle using ISTA ISTA 4.32.3x or higher.

**PROCEDURE**

For conditions that are similar to the situation described:

1. Using the latest version of ISTA, verify the fault code 80422D is entered into the BDC fault memory.
  2. Determine the vehicle's current I-level by either using AIR or the Key reader/ISPA NEXT application.
  3. If the I level is greater than or equal S18A-21-03-567 or less than or equal to S18A-21-03-565
- Program/encode the vehicle with ISTA ISTA 4.30.3x to I-level S18A-21-11-530 or a more recent version.

Program the vehicle using **ISTA 4.32.3x** or higher (released **November 2021**).

Model	Target Integration level
G05 (X5 M Sports Activity Vehicle)	<b>S18A-21-11-530</b> or higher
G06 (X6 M Sports Activity Coupe)	

Note that ISTA will automatically reprogram and code all programmable control modules that do not have the latest software.

**Always connect a BMW-approved battery charger/power supply ([SI B04 23 10](#)) when performing programming.**

For information on programming and coding with ISTA, refer to DealerSpeed / TIS / Technical Documentation / Diagnostics and Programming / Programming Documentation.

**Do not replace any parts for this issue.**

## **WARRANTY INFORMATION**

During this workshop visit, the affected vehicle may show one or more programming and encoding Technical Campaign repairs open, the programming and encoding procedure may only be invoiced one time.

**Select one of these open Technical Campaigns to perform and submit for updating the vehicle's software to the required I-level or higher.**

**Please be sure to perform any additional before and/or after work (including attaching labels) as required by the open campaigns on the vehicle. Close any remaining open programming and encoding Campaign repairs as outlined in the corresponding Service Information Bulletin.**

Only if the above situation does not apply, the BMW software solution is then:

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks, or the BMW Certified Pre-Owned Program as described below.

<b>Defect Code:</b>	<b>6131680200</b>	<b>Front controller/joystick (slide-type rotary pushbutton in centre console) Software error / internal device fault</b>
---------------------	-------------------	--

Refer to AIR for the corresponding flat rate unit (FRU) allowances.

<b>Labor Operation</b>	<b>Description</b>	<b>Labor Allowance</b>
00 00 006	Performing vehicle test (with vehicle diagnosis system – checking faults) (Main work)	Refer to AIR
Or:		
00 00 556	Performing vehicle test (with vehicle diagnosis system – checking faults) (Plus work)	Refer to AIR
And:		
61 21 528	Support voltage of the vehicle electrical system / recharge vehicle electrical system battery	Refer to AIR
And		
61 00 730	Programming/encoding control unit(s)	Refer to AIR

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead of 00 00 006.

### **Programming and Encoding - Vehicle Control Units (RO and Claim Comments Required)**

This procedure automatically reprograms and encodes any vehicle control modules that do not have the latest software I-level.

If one or more control modules fail during the reprogramming procedure, claim the required consequential repair work procedures to address this issue (including performing the IRAP Control Unit Recovery first as required, refer to the SIB in AIR) under the Defect Code in this bulletin with the labor operations in AIR that apply.

Please explain the additional work procedures that were performed (The why and the what) on the repair order and in the claim comments.

For covered repairs that address control module failures that occurred prior to performing this reprogramming procedure, claim this work with the Defect Code and labor operations (including diagnosis) in AIR that apply.

Based on which one applies to your center, please refer to **SI B01 01 20** or **B01 07 20** for claiming your diagnosis work time, job/repair work time (WT), RO/Claim WT and/or repair explanation procedures, unless otherwise required by State law.

## Other Repairs

If other eligible and covered work is performed as a result of performing the ISTA diagnostics and related test plans, claim this work with the applicable Defect Code and the labor operations listed in AIR (including diagnosis).

## QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Submit feedback at the top of this bulletin
Warranty inquiries	Please contact the Warranty department by either using the Live Chat that's available in the Warranty Documentation Portal or through IDS by selecting <u>Coverage, Policy, Coding Questions and Mileage Corrections</u>
Parts inquiries	Submit an IDS ticket to the Parts Department