

## **VOLKSWAGEN DEALERSHIP COMMUNICATION**

Date: February 23, 2022

To: Dealer Principal, Sales Manager, Service Manager, Parts Manager and Warranty Administrator

Subject: Upcoming Update 97FX – Alternator Cable – (NVLW) 2021 Passat

## **IMPORTANT NOTICE TO DEALERS - FOR IMMEDIATE DISTRIBUTION**

This is to inform you of an upcoming Update that will be visible in Elsa and ServiceNet on or about February 24, 2022.

Please refer to the Elsa campaign/action screen for confirmation of whether the Update applies to each specific vehicle, and look to Elsa and ServiceNet for additional information and complete repair instructions.

Consistent with general Volkswagen corporate policy governing Updates, Volkswagen is not notifying consumers. (Updates differ from recalls and service actions; consumers are notified in writing of recalls and service actions.) Each vehicle should be completed when it is in to the dealer for maintenance or any other service visit. Dealer stock vehicles **cannot**, **however**, **be delivered** to consumers until the Update is completed.

To identify any vehicles in your inventory that are affected by this Update, please run the "New and CPO Inventory Open Campaign/Action Listing" report from the OMD Web system.

Dealers must ensure that every affected vehicle gets the update <u>before delivery to consumers</u>. Your effort is integral in reaching the highest quality expectations of Volkswagen customers.

If you have any questions or require additional assistance, please contact Warranty.

Volkswagen Customer Protection

Attachment: Update Data Sheet (1)



## UPDATE DATA SHEET

SAGA CODE		97FX
MARKET(S)		United States and Canada
AFFECTED VEHICLES		2021 Passat
		Check your daily campaign open inventory report or OMD for affected vehicles in your inventory.
CODE VISIBILITY DATE		On or about February 24, 2022
ТОРІС		Alternator Cable – (NVLW)
PROBLEM DESCRIPTION		The B+ Cable on the back of the alternator may have been installed in the incorrect orientation. As a result, the cable terminal could make contact with the metallic portion of the air conditioning line. The cable terminal is protected with rubber insulation; however, this insulation is not intended for constant contact and may wear through over time, which would result in a high-current short circuit.
CORRECTIVE ACTION		Inspect and reroute alternator cable (if necessary).
VEHICLE WARRANTY PARAMETER		NVLW
VEHICLE COUNT	TOTAL AFFECTED	<b>USA:</b> 430
		Canada: 88
APPROXIMATE REPAIR TIME		Up to 50 TU
ADDITIONAL INFORMATION		Please ensure that this UPDATE is performed on every applicable vehicle before delivery to consumers. Your effort is integral in reaching the highest quality expectations of Volkswagen customers.
		Please reinforce the correct repair description of this action with all dealership personnel – this action is a vehicle UPDATE, <u>not</u> a recall.