

## **Advanced Technical Information**

**Bulletin #: 2205** 

Part ID: 1750

1

### Wanted: E3 and G2 Vehicles with EVAP Faults sought for Analysis Purposes

#### **Vehicles Affected**

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Cayenne	2019 - 2022	9YA/ 9YB	N/A	N/A
Panamera	2017 - 2022	971	N/A	N/A

### **Revision History**

Revision	Release Date	Changes
0	February 23, 2022	Original document

#### Condition

Wanted are any E3 or G2 models with any combination of the following tank system EVAP faults for analysis:

#### **DME Faults:**

P0456 – Tank system micro leak

P0441 – Evap Emission Control System Incorrect, Purge Flow

P0442 - Fuel Tank system - fine leak

#### Related Faults:

NOTE: Fault combination and sub-fault information may vary depending on engine type and DME software version.

#### Service Information

If possible, please contact David Merkel (PCNA-AQ3) at <a href="mailto:engineeringreview@porsche.us">engineeringreview@porsche.us</a> if a vehicle with these faults is found.

#### Search Items

Fuel Tank system, EVAP Fault, micro leak, emission control system, purge flow, fine leak, P0456, P0441, P0442, Evap leak

**AfterSales** 



# **Advanced Technical Information**

**Bulletin #: 2205** 

Part ID: 1750

2

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.