

Drive-Off Delay During Cold Start (16/22)

Vehicle Type: **911 GT3 (992)**

Model Year: **As of 2022**

Concerns: **7-speed Porsche Doppelkupplung PDK (M-no. G1C)**

Information: Customers complain that driving off when cold is not possible intermittently. Readjustment of the customer complaint is not possible at times. In addition, no fault memory entry is stored with regard to the drive-off delay.

This problem only occurs during the engine warm-up phase together with a certain accelerator pedal position. The fault type described here is often no longer present when you try to drive off again.

Action required: We are currently working on a software solution for the described fault type, but no software or hardware solution is currently available.

Component replacement will not work in the case of this fault pattern.

Please inform the customer about this circumstance as well.



Information

As soon as a permanent solution for the fault type described here is available, this Technical Information (TI) will be updated accordingly.

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.