

## 27 48V Vehicle electrical system warning, DTC P0CA700 and/or U046900 stored in the starter/generator control module/ECM

27 22 41 2058831/4 March 2, 2022. Supersedes Technical Service Bulletin Group 27 number 21-40 dated December 6, 2021 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
S6, S7, RS 7, S8, R8, and R8 Spyder	2018		
A6, A7, A8, and S8	2018 – 2021		
Q8	2019 – 2021		
A8 e quattro	2020	A.II.	19.1/ Detten/
A6 allroad, S6, S7, S8, SQ7, SQ8, RS Q8, R8, and R8 Spyder	2020 – 2021	All	48 V Battery
RS 6 avant, A7 e quattro, and A8 e quattro	2021		

## Condition

REVISION HISTORY				
Revision	Date	Purpose		
4		Revised Warranty (Updated Labor Operation)		
3	12/06/2021	Revised <i>Condition</i> (Added customer statements) Revised <i>Technical Background</i> (Added information) Revised <i>Service</i> (Added photo and new Steps 1-2) Revised <i>Warranty</i> (Added Labor Operation)		
2	04/01/2021	Revised header (Added MY21)		

© 2022 Audi of America, Inc.

#### Page 1 of 5

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



			Revised Service (Updated SVM Table)
--	--	--	-------------------------------------

#### Customer states:

• Intermittently a warning for the 48V vehicle electrical system is displayed in the instrument cluster.

Additionally, the customer may state:

- "The vehicle does not start."
- "The vehicle stalled."
- "The battery is dead."

#### Workshop findings:

One or more of the following DTC(s) may be stored relating to the battery management 2 (Battery 48V) control module, J1120 (address word 0021) and/or in the engine control module (ECM), J623 (address word 0001):

#### Battery management 2 (Battery 48V) control module, J1120 (address word 0021):

• DTC P0CA700 (hybrid battery discharge current too high static or sporadic).

#### ECM, J623 (address word 0001):

• DTC U046900 (invalid data received from starter/generator control module).

### **Technical Background**

The software needs to be updated in the starter/generator control module, C29 (address word 00CC).

If the warning shown in the instrument cluster for the 48V vehicle electrical system is ignored, the 12V system may drain, resulting in a vehicle stall or no start condition.

### **Production Solution**

Updated software version implemented in production.

### Service

© 2022 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



- 1. If DTC U046900 is found in the ECM, J623 (address word 0001), check the expanded ambient conditions of this DTC for the value of "Starter generator, actual mode 48V."
- 2. If the expanded ambient conditions value for "Starter generator, actual mode 48V" is 5 (Figure 1) for DTC U046900, then replace the starter generator. If no value is displayed, please submit an ODIS feedback.

ss: 0001 System name: 0001 - Engine Electronics Log versions: Identification:	
DTC memory entries (Data source: Vehicle):	
DTC memory entry	
Number	J046900: Invalid Data Received From Starter Generator Control Module
	bassive/sporadic
	34763
Status:	00100000
+ Standard ambient conditions:	
- Expanded ambient conditions:	12/22/200
Engine rpm	946.0 1/min
یکم شاه به با با از از از ا	
Starter generator, engine control module condition sta machine	te Gen
Param_TestProgrXExChpdEiuFhobBysCicaNfrr6SpUi	3YTE4
Starter generator, actual mode 48V	5
Starter generator, thermal load	48 %

*Figure 1.* DTC U046900 with Expanded ambient condition "Starter generator, actual mode 48V" value of 5 in the engine control module (ECM), J623 (address word 0001).

#### SVM Update Instructions

© 2022 Audi of America, Inc.

- 3. Follow all instructions in TSB 2011732: 00 Software Version Management (SVM), operating instructions.
- 4. Update the starter/generator control module, C29 (address word 00CC) using the SVM action code as listed in the table below, if necessary:

Model	Old Hardware	Old Hardware	Old Software	Old Software	New	SVM Code
	Part Number	Version	Part Number	Version	Software	Input
		(or lower)			Version	

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



					(or higher)	
A6, A7, Q7, and Q8	4N0903028 (H, J, M, and N)	H17	4N0903028 (F, G, H, J, M, and N)	523	527	CCA001

### Warranty

Claim Type:	<ul> <li>110 up to 48 Months/50,000 Miles.</li> <li>G10 for CPO Covered Vehicles – Verify Owner.</li> <li>If the vehicle is outside any warranty, this Technical Service Bulletin is informational</li> </ul>					
	only.					
Service Number:	2726					
Damage Code:	0040					
Labor Operations:	Software Update (Includes checking for DTCs) Only if update required	0151 0000	Time stated on the diagnostic protocol (Max 100 TU)			
	Expanded ambient condition "Starter generator, actual mode 48V" value of 5 only:					
	Replace starter-alternator	2726 XXXX	See SRT with associated operations			
Diagnostic Time:	GFF – Only if part replaced	0150 0000	Time stated on the diagnostic protocol (Max 100 TU)			
	Road test prior to the service procedure	No allowance	0 TU			

© 2022 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2058831/4		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

### **Additional Information**

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

• TSB 2011732: 00 Software Version Management (SVM), operating instructions.

All part and service references provided in this TSB (2058831) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

**©2022** Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

© 2022 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prin expressed written permission of the publisher.