

# Harsh 4 - 3 Downshift During Deceleration

Category	Drivetrain		
Section	Automatic Transmission/Transaxle	Market USA	Toyota Supports

#### Applicability

Service

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION	
2020 - 2021	Land Cruiser		

### Introduction

Some 2020 - 2021 model year Land Cruiser vehicles may exhibit a harsh 4 - 3 downshift during deceleration from 45 - 5 mph. This condition typically occurs at low mileage and may also be found during the Pre-Delivery Service (PDS) inspection. This condition does not set any DTCs or trigger any warning lights or messages. Follow the Repair Procedure in this bulletin to address this condition.

#### Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	I	-	_	_

# Harsh 4 - 3 Downshift During Deceleration

#### **Required Tools & Equipment**

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream ADVI*	ADE	TSADVUNIT	1
Techstream 2.0		TS2UNIT	
Techstream Lite		TSLITEPDLR01	
Techstream Lite (Green Cable)		TSLP2DLR01	]

\*Essential SST.

#### NOTE

- Only ONE of the Techstream units listed above is required.
- Software version 16.30.011 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.

#### **Repair Procedure**

1. Confirm the condition exists.

Does the vehicle exhibit a harsh 4 – 3 downshift during deceleration from 45 – 5 mph?

- **YES** Continue to step 2.
- NO This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.

## 2. Using Techstream, check for ANY DTCs.

Are there ANY transmission related DTCs present?

- YES This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
- NO Continue to step 3.

## Page 3 of 3


# Harsh 4 - 3 Downshift During Deceleration

#### **Repair Procedure (continued)**

- 3. BEFORE performing the targeted self-learning procedure, confirm the following:
  - The transmission fluid level is acceptable.
  - The transmission fluid temperature is between 122°F 230°F (50°C 110°C).
  - There is a flat road surface available (no hills).
  - There is a smooth road surface available.
  - There are NO DTCs present.
- 4. Perform the targeted self-learning procedure until the condition is no longer present or up to 14 times.
  - A. While the vehicle is in Drive (D), accelerate to above 35 mph.
  - B. Decelerate the vehicle to 7 mph with very light braking (coasting is best).
  - C. Do NOT make any turns to keep a gradual deceleration speed.
  - Repeat this procedure until the condition is no longer present or up to 14 times.
- 5. Test-drive the vehicle to confirm the condition is no longer present.

Is the condition still present?

- YES This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
- NO The repair is complete.



1	35 mph
2	4 – 3 Downshift
3	7 mph
4	About 25 Seconds