

Technical Service Bulletin

Mazda North American Operations
Irvine, CA 92618-2922



Subject: FUEL-FILLER LID DOES NOT LOCK	Bulletin No.: 09-006/22
	Last Issued : 03/01/2022

BULLETIN NOTES

APPLICABLE MODEL(S)/VINS

2019-2021 Mazda3 (Japan built) with VINS starting with JM1
2020-2021 CX-30

DESCRIPTION

Some customers may experience that after the doors are locked and the Fuel Door Lock Delay with MAZDA CONNECT has passed (default setting is 90 seconds), the fuel-filler lid does not lock and can be opened when pressing it.

NOTE:

- The fuel-filler lid does not lock immediately after the doors are locked, but after the time set in the Fuel Door Lock Delay (0, 30, 60, 90, and 120 seconds).
- Although the root cause has not been identified, the vehicle should be repaired by adjusting the fuel-filler lid opener cable position when there is a customer complaint.


Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE


1. Verify the customer concern by locking the doors and pressing the fuel-filler lid after 2 minutes to see if it opens.
 - If the fuel-filler lid can be opened, adjust the fuel-filler lid opener cable position using the Adjustment Procedure of Fuel-Filler Lid Opener Cable below.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

2. After adjustment of the cable, wait for 2 minutes after locking the doors, then press the fuel-filler lid again to verify that the lid does not open.



(1) Trunk side trim




Detail A: (2) Fuel-filler lid opener cable

Adjustment Procedure of Fuel-Filler Lid Opener Cable

1. Remove the following parts according to the instructions on MGSS.

- Mazda3 (FUEL-FILLER LID LOCK ACTUATOR MANUAL RELEASE PROCEDURE)
- CX-30 (FUEL-FILLER LID LOCK ACTUATOR MANUAL RELEASE PROCEDURE)
 - Rear package tray
 - Trunk covering
 - Trunk board
 - Trunk end trim
 - Trunk side upper trim (LH)

2. Partially peel the trunk side trim (LH) (1).




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

3. Remove the trunk side insulator.



(1) Location of Trunk side insulator

(2) Trunk side insulator
(3) Clip (2pcs.)


4. Cut the zip tie securing the fuel-filler lid opener cable.



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


5. Pull the fuel-filler lid opener cable (1) slowly to the end (manual release procedure).

NOTE: DO NOT pull the cable with too much force, otherwise it could be damaged.



TIP: By pulling the cable (1), the lock connected to the opener lever (2) leaves the cam hole and the actuator rod (3) is unlocked.


Inside of Fuel-Filler Lid Lock Actuator



- (1) Opener cable
- (2) Opener lever
- (3) Actuator rod
- (4) Lock


CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

6. Secure the fuel-filler lid opener cable end (1) with another tie band (2) (return to the normal position).



TIP: By pushing the opener cable (1), the lock connected to the opener lever (2) inserts into the cam hole and the actuator rod (3) is locked.

Inside of Fuel-Filler Lid Lock Actuator



- (1) Opener cable
- (2) Opener lever
- (3) Actuator rod
- (4) Lock


7. Verify that the fuel-filler lid does not open 2 minutes after closing and locking the doors and liftgate.

8. Install the parts removed in step 1 in the reverse order of removal.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

PARTS INFORMATION

Parts Number	Description	Qty.	Notes
E120-68-AB1	Clip	1	For trunk side upper trim (CX-30)

**WARRANTY INFORMATION****NOTE:**

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	42
Damage Code	9G
Part Number Main Cause	7777-SP-T30
Quantity	0
Operation Number / Labor Hours:	XXT5BARX / 0.3 Hrs.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.