

**Tire Pressure Monitoring Control Unit Cannot be Accessed Using the PIWIS Tester:
Replacing Tire Pressure Monitoring Control Unit and Control Unit Holder (31/22)**

Model Line: **Panamera (971)**

Model Year: **As of 2017 up to 2022**

Concerns: **Tire pressure monitoring control unit and control unit holder**

- Information:
- The tire pressure display fails or a warning message about tire pressure monitoring appears on the instrument cluster.
 - Fault code '**U012700 – Tire pressure monitoring control unit – no communication**' is stored in the fault memory of the gateway control unit.

This may be caused by water leaking into the tire pressure monitoring control unit. Water leaking in is facilitated by the geometry of the control unit holder.

Action required: In the event of a complaint, replace the faulty tire pressure monitoring control unit and the holder for the control unit.

Parts required

Parts Info:	Part No.	Designation	Number
	971907297C	⇒ Tire pressure monitoring control unit holder	1 ea.
	971907273M	⇒ Control unit for tire pressure monitoring (M-no. 7K3)	1 ea.
		or	
	971907273N	⇒ Control unit for tire pressure monitoring (M-no. 7K4)	1 ea.

Replacing control unit for Tire Pressure Monitoring and control unit holder

Work Procedure: 1 Replace control unit for tire pressure monitoring and control unit holder. ⇒ *Workshop Manual '443419 Removing and installing control unit for Tyre Pressure Monitoring'*

Invoicing

For documentation and warranty invoicing, enter the working position and PCSS encryption specified below in the warranty claim:

APOS	Labor operation	I No.
44345500	Replacing control unit for tire pressure monitoring	

PCSS encryption:

Location (FES5)	44340	Tire pressure monitoring control unit
Damage type (SA4)	4000	electrical fault

References: ⇒ *Workshop Manual '443419 Removing and installing control unit for Tyre Pressure Monitoring'*

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2022 Porsche Cars North America, Inc.