

Technical Information

Service 40/22 ENU 6170

Convertible Top Mechanism Replacement: Rework Required Before Installation (40/22)

| Model Line: | Boxster (987) | | | | |
|--------------------|--|-----------|----------|--|--|
| Model Year: | As of 2005 up to 2006 | | | | |
| Concerns: | Convertible top mechanism | | | | |
| Information: | The remaining convertible top inventory (Part Nos.: 98756117901 or 98756118001) may contain convertible top mechanisms without guide pegs for the drive shaft. | | | | |
| Action required: | Before installing a new convertible top mechanism, secure the drive shaft to the convertible top mechanism with a tie-wrap if necessary. | | | | |
| Required materials | | | | | |
| Materials: | Required materials per convertible top mechanism (usually already available at the Porsche dealer): | | | | |
| | Part No. De | signation | Quantity | | |

| Part No. | Designation | Quantity |
|----------|--|----------|
| | \Rightarrow Tie-wrap (commercially available, 2 – 3 mm/ 0.08 | 1 unit |
| | — 0.12 in wide) | |

Reworking convertible top mechanism

Work Procedure:



Convertible top mechanism

AfterSales

1 Use a tie-wrap to secure the drive shaft \Rightarrow Convertible top mechanism -1 - to the bore of the convertible top mechanism.



Information

The bore on the convertible top mechanism has already been drilled by the supplier.

Labor time

The following labor steps have been defined for reworking the convertible top mechanism:

| APOS | Labor operation | I No. |
|----------|------------------------------------|-------|
| 61724901 | Reworking left mechanism | |
| 61724902 | Reworking right mechanism | |
| 61725000 | Reworking left and right mechanism | |

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know how to do the job properly and safely. Part numbers listed in these builtetins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2022 Porsche Cars North America, Inc.

AfterSales