

Service Bulletin

INFORMATION

Subject: Diagnostic Tips on GDS Graphing after Road-Test, for Shake and/or Shudder During Steady and/or Light Throttle Acceleration Between 25 and 50 MPH (40 and 80 KM/H) at Steady Speed, and Decel at approximately 15 MPH (24 KM/H).

Brand:	Model:	Model Year:		VIN:		Engine	Tronomicoion
		from	to	from	to	Engine:	Transmission:
Cadillac	Escalade Models	2021	2022				
Chevrolet	Silverado 1500	2020	2021			L84, L87	MQB, MQC, MHS
	Silverado 1500 (LTD, RPO J21, 12th VIN Digit = 4 or less)	2022	2022				
	Silverado 1500 (RPO J22, 12th VIN Digit = 5 or greater)						
	Suburban	2021	2022				
	Tahoe						
GMC	Sierra 1500	2020	2021				
	Sierra 1500 (Limited, RPO J21, 12th VIN Digit = 4 or less)	2022	2022				
	Sierra 1500 (RPO J22, 12th VIN Digit = 5 or greater)						
	Yukon Models	2021	2022				

Involved Region or Country	North America, Australia, New Zealand, Europe, Uzbekistan, Middle East, Israel, Argentina (Mercosur), Brazil (Mercosur), Bolivia (West), Chile (West), Colombia (West), Ecuador (West), Paraguay (West), Peru (West), Uruguay (West)			
Condition	Some customers may comment of a shudder, shake, vibration from approximately 25 – 50 mph (40-80 km/h) while under steady to lightly accelerating throttle.			
Cause	 This condition may be caused by various transmission and engine concerns. See the Diagnostic Tips below. Check for Transmission and Engine related DTC's. Resolve any DTC's before and reevaluate the vehicle before proceeding. 			
Correction	Diagnostic Tips Test Drive The customers vehicle should be test driven in an effort to duplicate the condition. Details of vehicle speed, driving conditions and throttle input may need to be discussed with the customer. Some normal shudder, shake, vibration or growl can be expected in low speed, light throttle applications as the vehicle may be going in and out for Dynamic Fuel Management (DFM). DFM can be turned off for a test drive by shifting the transmission into Manual Range "L9". Driving a like vehicle under the same conditions may help determine if the vehicle is operating like other vehicles and should be considered characteristic of design.			

Diagnostic Tips Engine Performance

⇒ Diagnostic Tip Related Shutter: 21–NA-207



1. Engine Speed

- 2. Engine Torque
- 3. Vibration Felt after Engine Refuel, Should be in Reduced Firing Fraction
- 4. Pedal
- 5. Transmission Input Shaft Speed (ISS)

Diagnostic Tip Closed Throttle Shudder – TSB 21-NA-207: 2021 Silverado Sierra 5.3 (L84) 10 Speed (MQB) only.

The condition is only present at 0% throttle during a coast event at approximately 15 mph (24 km/h). Note the engine RPM and torque oscillations at engine refuel points.

Diagnostic Tip Engine Related Shudder – PIP5794B Camshaft Actuator



- 1. Torque
- 2. Engine Speed
- 3. Transmission ISS
- 4. Pedal

Record a GDS session log and monitor engine speed, transmission input speed and engine torque. If engine torque is larger than +- 25 Nm while no gear shift is active, and throttle is relatively constant the issue most likely lies within the engine.

Observe the large variation in engine torque while engine speed and Transmission ISS follow each other more closely. Although this feels like shudder to the customer it is most likely an engine related concern.

Diagnostic Tips TCC Solenoid – Valve Body



5975003

- 1. Torque
- 2. Engine Speed
- 3. Transmission ISS
- The shudder condition is present both in Drive "D" or Manual "L9".
- Typically occurs at less than 15,000 miles (24,000 km)
- Transmission ISS follows engine speed
- Relatively consistent engine torque. <+- 25 Nm

Engine torque remains relatively flat while engine speed rises and falls. The valve body should be replaced.

Diagnostic Tip TCC Solenoid (Drift) – Valve Body



5975005

- 1. Torque
- 2. Engine Speed
- 3. Transmission ISS
- 4. TCC Pressure
- Shudder condition is present in Drive "D" but NOT present in Manual "L9"
- Throttle would typically be less than 10% and engine torque less than 100 Nm
- TCC slip speed will be 0 or near 0
- TCC pressure command will remain at 100 kPa

The valve body should be replaced.

Diagnostic Tip TCC Shudder – Torque Converter



- 1. Torque
- 2. Engine Speed
- 3. Transmission ISS
- 4. Pedal
- TCC pressure control is steady
- TCC slip is elevated
- Engine RPM will increase at the shudder point while Transmission ISS remains steady
- Engine torque remains relatively steady during the shudder event
- Throttle angle remains steady during the shudder event

The torque converter should be replaced.

Version	2
Modified	Released January 27, 2022 Revised March 21, 2022 - Revised Subject, Added Additional Countries, Change Turbine Speed to Transmission Input Shaft Speed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION

GM bulletins are intended for use by professional technicians, NOT a "<u>do-it-yourselfer</u>". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

