TECHNICAL TOPICS

Powertrain



HVAC systems taking longer than expected to warm the cabin in cold environments	21MY Discovery Sport, RR Evoque 21MY E-PACE
 Customer Voice: Heater blows cold for a long time after a cold start then suddenly temperature gauge moves from cold to normal range, and heat blows hot. May oscillate between hot and cold several times when driving at beginning of drive cycle. Technical Description: Coolant pump flow setting too low resulting in reduced cabin heating performance in cold weather. Status: PCM Software is available via Topix (OTX) currently. PCM SW will also go out over SOTA at a later date (timing to be confirmed) Refer to SSM 75666/75667 	<image/>
Image: Comparison of the second se	35