

## **SSM 50646 - 2020-2022 F-Super Duty - 6.7L - Illuminated MIL With Cylinder Injection Pulse Offset DTCs - P2B11 Through P2B1F**

Some 2020-2022 F-Super Duty vehicles equipped with a 6.7L engine may exhibit an illuminated malfunction indicator lamp (MIL) with cylinder injection pulse offset diagnostic trouble codes (DTC) P2B11, P2B13, P2B15, P2B17, P2B19, P2B1B, P2B1D, and/or P2B1F stored in the powertrain control module (PCM) after various fuel system repairs. This may be due to incorrect learned values in the PCM. To correct the condition, allow the engine to idle for at least 6 minutes with the engine at normal operating temperature. Clear DTCs and retest. PCM replacement is not necessary for this condition.

APPLICABLE VEHICLES  
2020 - 2022 TRUCK: FE P558N SUPER DUTY