



Release Date	04/12/2022	Technical Service Bulletin
90T6 UPDATE		
ConBox Software Update – (NVLW)		Audi

Applicable Vehicles				
Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count
USA	2022	2022	A4 ALLROAD	1
USA	2022	2022	A4 SEDAN	382
USA	2022	2022	A5 CABRIOLET	120
USA	2022	2022	A5 SPORTBACK	252
USA	2022	2022	A6 ALLROAD	39
USA	2022	2022	A6 SEDAN	156
USA	2022	2022	A7	63
USA	2021	2021	A8	160
USA	2022	2022	E-TRON GT	187
USA	2022	2022	E-TRON QUATTRO	751
USA	2022	2022	E-TRON SPORTBACK QUATTRO	135
USA	2022	2022	Q5	5,911
USA	2022	2022	Q5 SPORTBACK	560
USA	2022	2022	Q7	1,196
USA	2022	2022	Q8	209
USA	2022	2022	RS5 COUPE	1
USA	2022	2022	RS5 SPORTBACK	6
USA	2022	2022	RS6 AVANT	79
USA	2022	2022	RS7	55
USA	2022	2022	RSQ8	127
USA	2022	2022	S5 CABRIOLET	29
USA	2022	2022	S5 SPORTBACK	57
USA	2022	2022	S6 SEDAN	5
USA	2022	2022	S7	2
USA	2021	2021	S8	17
USA	2022	2022	SQ5	353
USA	2022	2022	SQ5 SPORTBACK	131
USA	2022	2022	SQ7	314
USA	2022	2022	SQ8	97

Revision History		
Revision	Date	Purpose
1	April 12, 2022	Original publication

Release Date	04/12/2022	Technical Service Bulletin
90T6 UPDATE ConBox Software Update – (NVLW)		

Condition/Technical Background

This Update has been proactively released to prevent the following condition(s) from occurring in the vehicle:	
Criteria	Technical Background
01	<ul style="list-style-type: none"> The myAudi login fails with an error message of “Your login was unsuccessful. Please try again later.” The online traffic in the navigation map does not show speed and flow or is delayed. The over-the-air navigation map updates does not start or complete. Intermittent technical issues with all other Audi connect services.

Remedy

Criteria	Remedy
01	Update the ConBox software via SVM.

This Update is in effect until removed.

Vehicle must meet all of the following criteria:

- Procedure is valid only for vehicles that show the **90T6** code in the Elsa Campaign/Action Information screen on the day of repair.
- Vehicle must be within the New Vehicle Limited Warranty.
- Procedure must be performed within the allotted time frame stated in this Technical Service Bulletin.
- Procedure must be performed on applicable vehicles in dealer inventory prior to sale.

Service

NOTE:

- Elsa is the only valid inquiry/verification source. Check Elsa on the day this vehicle UPDATE will be performed to verify vehicle eligibility for the UPDATE. Status must show “open”. Attach an Elsa printout showing the “open” status to the repair order.
- If this UPDATE appears to have already been performed but the code still shows open in Elsa, contact Warranty before proceeding further. Another dealer may have recently performed this UPDATE but not yet entered a claim for it in the system.
- Elsa may also show additional open action(s); if so, inform your customer - this work can be done while the vehicle is in for this UPDATE.
- Contact the Warranty Helpline (U.S.) or the Warranty Campaign Specialist (Canada) if you have any questions.

Applicable criteria ID(s)	Campaign/Action Status
01 ← 2	Open ← 1

EXAMPLE

Campaign/Action	Start	Designation
← 3	2015-11-10	W-SERV_ACT -
	2018-12-13	RECALL -
	2017-05-16	A-RECALL -

EXAMPLE

- Enter the VIN in Elsa and proceed to the “Campaign/Action” screen.

TIP

On the date of repair, print this screen and keep a copy with the repair order.


- Confirm the Campaign/Action is open <arrow 1>. If the status is closed, no further work is required.
- Note the Applicable Criteria ID <arrow 2> for use in determining the correct work to be done and corresponding parts associated.

CRITICAL REPAIR STEP

STOP! STOP!

If multiple software update Campaign/Actions are open, they must be performed in order of the Start date <arrow 3>. The oldest should be performed first.

- **All Safety Recalls must be completed prior to completing this campaign.**

Release Date	04/12/2022	Technical Service Bulletin
90T6 UPDATE ConBox Software Update – (NVLW)		

SVM Update Instructions


NOTE

Prior to launching the VAS Diagnostic Tester and starting an update, ensure the following conditions are met;

- ✓ **The ODIS software is completely up to date.**
 - Refer to the “Alerts” section on ServiceNet home page for the current ODIS version.
- ✓ **The battery charger is connected to the vehicle battery and remains connected for the duration of the software update.**
 - Battery voltage must remain above 12.5 volts for the duration of the software update. Failure to do so may cause the update to fail, which could result in damage to the control module. Control modules damaged by insufficient voltage will not be covered.
- ✓ **The screen saver and power saving settings are off.**
 - Failure to do so may result in the tester entering power save mode during the software update, which could result in damage to the control module.
- ✓ **The VAS Diagnostic Tester is plugged in using the supplied power adapters.**
 - Under no circumstances should the tester be used on battery power alone during the software update. Failure to do so may result in the tester powering off during the update, which could result in damage to the control module.
- ✓ **Flash process through “Audi Flashing” not Guided Fault Finding (GFF).**
 - DO NOT USE Guided Fault Finding (GFF) to perform this flash. Using GFF will cause the flash to take longer. Requests for additional time will not be considered.
- ✓ **The VAS Diagnostics Interface MUST ONLY be connected to the tester with a USB cable.**
 - Performing a software update using a Bluetooth or WiFi connection increases the risk of losing connection during the update, which could result in damage to the control module. It also greatly increases the time required to perform the update. Requests for additional time or parts will be denied if the GFF log shows the update was performed using Bluetooth or WiFi.

TIP

As a best practice, customer presets should be documented prior to performing any update in the event these settings are lost during the update.

Release Date	04/12/2022	Technical Service Bulletin
90T6 UPDATE ConBox Software Update – (NVLW)		 Audi

NOTE

- All campaign software updates must be completed during a single, standalone ODIS Diagnostic Session. You must fully complete this campaign and send all logs before beginning any other campaigns or operations.
- If there are any ODIS “Hot-Fix” patches installed, they must be removed from the scan tool before beginning this operation. ODIS “Hot-Fix” patches may affect the update process.

WARNING

Radiator Fan(s) may cycle ON high speed during the Update Process! There is a serious risk that personal injury may result if contact is made with spinning fan blades. Keep hands and all objects away from Radiator Fan(s) during Update Process!

TIP

To Update-Programming using SVM, review and follow instructions in Technical Bulletin 2014603: *Software Version Management (SVM) Operating Instructions*.

The SVM Process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim.

- Open the hood.
- Open the battery cover.
- Attach the GRX3000VAS Tester/Charger (or equivalent) IN POWER SUPPLY MODE to the vehicle battery or underhood charging posts.

NOTE


When connecting the charger directly to the battery, connect the positive cable to the positive terminal of the battery and connect the negative cable to the grounding lug on the chassis. DO NOT connect the ground cable directly to negative terminal of the battery.

- Switch on the hazard warning lights.


CAUTION

The procedure may cancel itself if the hazard warning lights are not switched on. The hazard warning lights prevent the system from switching to bus sleep mode during the update.

- Connect the VAS6150X/VAS6160X Diagnostic Tester to the vehicle.
- Start the ODIS program.



- Confirm that scan tool is communicating with the diagnostic head by USB cable.
 - If the Bluetooth or WiFi symbol is shown, then disconnect the diagnostic head from the vehicle and reconnect the USB cable to the diagnostic head and then reattach to the vehicle.



⚠ CRITICAL REPAIR STEPS



Changing the communication path to “Only allow DoIP communication” MUST be performed to ensure consistent success of this software update. The software update will fail if these steps are not followed.


As stated in the Note on the scan tool, “This selection field only applies for the diagnostic session that follows. When the current diagnostic session ends, the setting will be reset to “Automatic detection.”

When connecting to a different vehicle or initiating a new diagnostic session this step must be performed again.


- From the home screen of the scan tool, select “Admin.”

90T6 UPDATE

ConBox Software Update – (NVLW)



- From the “General” tab <arrow 1>, select “GFF Process” <arrow 2>.




- From the “Communication path selection,” select “Only allow DoIP communication” <arrow 1>.
- Select “Save” <arrow 2>.

NOTE

As stated in the Note on the scan tool, “This selection field only applies for the diagnostic session that follows. When the current diagnostic session ends, the setting will be reset to “Automatic detection.”


When connecting to a different vehicle or initiating a new diagnostic session this step must be performed again.



- Select “Yes” when prompted, “Do you really want to save?”
- Return to the home screen of the scan tool.

90T6 UPDATE


ConBox Software Update – (NVLW)




- From the home screen of the scan tool highlight “Flash” <1>.
- Follow the on-screen prompts.

NOTE

Operating mode “Flash” must be used. Performing this software update using “Diagnosis” (Guided Fault Finding) could result in non-payment of the claim.




- Select “Starting Flashing” and follow the on-screen prompts.




- Select “No RO”.


90T6 UPDATE
ConBox Software Update – (NVLW)



- Highlight “SVM – Code Input”.



- Select “Perform test”.



NOTE

Using Bluetooth or WiFi for this action is PROHIBITED!

Damage caused to electronic components (e.g. ECM, TCM, etc.) during the SVM flash process is not covered.


- Enter the corrective action code (SVM code) as listed below.

SVM code
90T6A016


- Select “Accept” <arrow>.
- Follow the on-screen prompts.

90T6 UPDATE

ConBox Software Update – (NVLW)



- After receiving confirmation that the flash completed successfully, select “Send” <arrow> to send the diagnostic protocol online.
- Follow the on-screen prompts.




- Click “Flash” <arrow> to exit the flash session.

i TIP

Various event memory entries may be generated after the flashing procedure on some vehicles. Put the vehicle in a corresponding bus sleep mode after performing the update in order to clear the faults.

To put the vehicle in bus sleep mode, disconnect the diagnostic tester, remove the key from the vehicle and lock the vehicle with the remote for 5 minutes.

Release Date	04/12/2022	Technical Service Bulletin	
90T6 UPDATE ConBox Software Update – (NVLW)			 Audi


Claim Entry Instructions			
After Update has been completed, enter claim as soon as possible to help prevent work from being duplicated elsewhere. Attach the Elsa screen print showing action <u>open on the day of repair</u> to the repair order.			
If customer refused campaign work or vehicle is out of the specified warranty parameter for this Update:			
✓ <u>U.S. dealers</u> : Submit the request through Audi Warranty Online under the <u>Campaigns/Update</u> option.			
Service Number	90T6		
Damage Code	0099		
Parts Vendor Code	002		
Claim Type	Sold vehicle: 7 10 Unsold vehicle: 7 90		
Causal Indicator	Mark labor as causal		
Vehicle Wash/Loaner	Do not claim wash/loaner under this action		
Criteria I.D.	01		
	LABOR		
	Labor Op	Time Units	Description
	2706 89 50	10	Connect battery charger
	9170 25 99	Time stated on diagnostic protocol	Update infotainment control module software

Additional Actions Some of the affected vehicles may be involved in additional Actions. Please check your Elsa Campaign/Action Information screen so that any *additional required work can be done simultaneously*.



Verifying Vehicle Eligibility To verify vehicle eligibility for this Update, *always* check the Elsa Campaign/Action Information screen. The Elsa system is the *only* binding inquiry and verification system; other systems are not valid and *may result in non-payment* of a claim.

Help for Claim Entry For questions regarding claim entry, contact Audi Warranty.

Required Customer Notification Inform your customer in writing by recording on the Repair Order any and all work that was conducted on the vehicle, including any and all updates completed under this Update.

Release Date	04/12/2022	Technical Service Bulletin	
90T6 UPDATE ConBox Software Update – (NVLW)			 Audi

Required Special Tools

	<p>Battery Tester/Charger</p> <p>- GRX3000VAS-</p> <p>(or equivalent)</p>		<p>Diagnostic Tester</p> <p>-VAS6150X/VAS6160X-</p> <p>(or equivalent)</p>
---	---	--	--

Additional Information

All parts and service references provided in this Update are subject to change and/or removal. Always check Elsa for the most current version of this document.