

Published date: 03/23/2022

## **Preliminary Information**

## PIP5845 Engine Coolant Reservoir Overfilled With Discolored Coolant Possible Engine Overheat Transmission Shake Shudder Vibration Shift Performance Or Slipping

<u>Models</u>

| Brand:    | Model:          | Model Years: | VIN:       |            | Engine  | Transmissions: |
|-----------|-----------------|--------------|------------|------------|---------|----------------|
|           |                 |              | from       | to         | Engine: | Transmissions. |
| Cadillac  | Escalade Models | 2021 - 2022  | 03/01/2021 | 02/27/2022 | LM2     | MQC            |
| Chevrolet | Silverado       | 2021 - 2022  | 03/01/2021 | 02/27/2022 | L3B LM2 | MQB MQE        |
| Chevrolet | Suburban        | 2021 - 2022  | 03/01/2021 | 02/27/2022 | LM2     | MQC            |
| Chevrolet | Tahoe           | 2021 - 2022  | 03/01/2021 | 02/27/2022 | LM2     | MQC            |
| GMC       | Sierra          | 2021 - 2022  | 03/01/2021 | 02/27/2022 | L3B LM2 | MQB MQE        |
| GMC       | Yukon Models    | 2021 - 2022  | 03/01/2021 | 02/27/2022 | LM2     | MQC            |

| Involved Region or Country | North America  |
|----------------------------|--|
|                            | Some customers may comment of the following conditions:<br>Engine coolant reservoir is discolored with a strawberry milkshake appearance and |
|                            | may be overfilled to the point where coolant is being expelled from the overflow.  |
|                            | See photo below (coolant is not bright orange and translucent).  |

| Condition | See photo below (coolant is not bright orange and translucent).<br>In addition to above, engine may experience an overheat condition<br>In addition, possible degraded transmission performance including any of the<br>following:<br>Shudder, vibration, shake, shift performance and slipping.<br>The transmission fluid level may be low when checked. |
|-----------|---|
| Cause     | The Automatic Transmission Fluid Cooling Exchanger may have an internal leak allowing transmission fluid and engine coolant to intermix contributing to the above conditions.   |

Correction:



Confirm the presence of coolant in the transmission fluid using Service Bulletin # 08-07-30-035 (Information on Water Ethylene Glycol in Transmission) in SI

Using 08-07-30-035 as a guide repair or replace the transmission assembly following SI Replace the Automatic Transmission Fluid Cooling Exchanger

Thoroughly Flush the Engine Coolant System to remove the contaminated engine coolant following SI. Refill the engine coolant system following SI

## Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

| Labor Operation | Description  | Labor Time                |
|-----------------|--|---------------------------|
| 8451010         | Automatic Transmission Fluid Cooling Exchanger<br>Replacement. | Use published labor time. |

Note: The Automatic Transmission Fluid Cooling Exchanger is the causal part the other components should be added to the warranty claim.

Time punches should be used to support the OLH required.

<u>Version History</u>

| Version  | 1                        |
|----------|--------------------------|
| Modified | 03/23/2022 - Created on. |



© 2022 General Motors. All Rights Reserved.