

72 Squeaking noise from the front seat height adjustment

72 22 43 2059448/4 April 16, 2022. Supersedes Technical Service Bulletin Group 72 number 21-36 dated September 17, 2021, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
Q5, and SQ5	2017 – 2023			
Q5 e quattro, Q5 Sportback, and SQ5 Sportback	2021 – 2022	All	Not Applicable	

Condition

REVISION HISTORY				
Revision	Date	Purpose		
4	-	Revised header (Added model years) Revised <i>Production Solution</i>		
3	09/17/2021	Revised header (Added Model Years 2021 - 2022)		
2	07/16/2020	Revised header (Added MY2020 Q5 and SQ5) Revised <i>Required Parts and Tools</i> (Updated ODIS)		

Customer states:

• A squeaking noise is audible from the front seats while moving in the seat or while driving.

© 2022 Audi of America, Inc.

Page 1 of 5

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Workshop findings:

• The source of the squeaking noise can be tracked to the front seat outer hinge area. The noise originates from behind the seat frame trim panel.



Figure 1. Noise originates from behind the seat frame trim panel near the hinge.

Technical Background

Depending on the seat position, under certain conditions, squeaking noises from the front seat height adjustment can occur. Specifically, in the lower seat adjustment positions, the toothed segment of the seat height adjustment can interfere with the support bracket resulting in squeaking noises.

Production Solution

Not applicable

Service

- 1. Remove the affected seat from the vehicle according to the Elsa Repair Manual.
- 2. Attach the seat to the seat repair fixture VAS6136 mounted to the engine and transmission holder VAS6095A according to the Elsa repair manual.

Page 2 of 5

^{© 2022} Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



 Remove the seat frame trim panel and tilt the seat forward to gain access to the seat height adjustment toothed segment.



Figure 2. Toothed segment of the seat height adjustment.

 Apply grease spray part number G 052 778 A2 on the toothed segment as shown in Figure 3 (lubricate teeth and lateral surfaces).



Figure 3. Grease applied to the seat height adjustment toothed segment.

© 2022 Audi of America, Inc.

Page 3 of 5

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



- 5. Reinstall the seat frame trim panel and install the seat in the car according to Elsa Repair Manual.
- 6. Adjust the seat up and down three times covering the full range of vertical movement to equally distribute the grease on the toothed segment.

Warranty

Claim Type:	 110 up to 48 Months/50,000 Miles. G10 for CPO Covered Vehicles – Verify Owner. If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	7210		
Damage Code:	0020		
Labor Operations:	Modify 1 height adjuster	7228 4999	80 TU
	Modify 2 height adjusters	7228 5099	120 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	0121 0002	10 TU
	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB 2059448/4		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.

^{© 2022} Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
G 052778A2	Lock cylinder lubricant spray	0.5

Tool Number	Tool Description
VAS 6095A	Engine and transmission holder
VAS 6136	Seat repair fixture
VAS 6160/VAS 6150 (Windows 10 with current version of ODIS)	ODIS Service with VAS tester

Additional Information

All parts and service references provided in this TSB (2059448) are subject to change and/or removal.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2022 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prin expressed written permission of the publisher.