



Technical Service Bulletin

96 Traffic sign recognition is not available, DTC U111000 stored in the 0017 and/or DTC U111100 stored in the 005F

96 22 76 2064361/2 April 14, 2022. Supersedes Technical Service Bulletin Group 91 number 21-27 dated September 2, 2021 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2021	Not Applicable	Traffic Sign Recognition

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Service</i> (Replaced measure with SVM update) Revised <i>Warranty</i> (Updated to reflect SVM update) Revised <i>Required parts and tools</i> (removed content)
1	09/02/2021	Initial publication

Customer states:

- The message "Traffic sign recognition: fault" is displayed permanently after the vehicle is started.

Workshop findings:

One or more of the following DTC(s) may be stored relating to the instrument cluster control module, J285 (address word 0017) and/or information electronics control module 1, J794 (address word 005F):

Instrument cluster control module, J285 (address word 0017):

- DTC U111000 (Function restriction due to communication interruption) with symptom code 16777012.

Information electronics control module 1, J794 (address word 005F):

- DTC U111100 (Function limitation due to missing message) with symptom code 7201.



Note:



Technical Service Bulletin

This TSB only applies if the vehicle has a front camera for driver assist systems, R242 (address word 00A5) with software 1202 installed and if at least one of the aforementioned DTCs are stored.

Technical Background

There is a software bug in the front camera for driver assist systems, R242 (address word 00A5).

Production Solution

SW1301 was introduced in production.

Service

SVM Update Instructions



Always use DoIP when flashing a control module via ODIS in supported vehicles.

To Activate DoIP, select *Administration*>>*General*>>*GFF Process*>>*DoIP communication*>>*Only allow DoIP communication*

This setting will automatically reset when the diagnostic session is ended.

You can tell if DoIP is active by observing a red LED on the VAS 6154(A)

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update the Camera for Driver Assist Systems -R242- (diag. addr. 00A5) using the SVM action code as listed in the table below, if necessary.

Perform the SVM code of step 1 first, then proceed to run the SVM code in step 2:

Model	Step	Old Software Part Number	Old Software Version	New Software Part Number (or higher)	New Software Version (or higher)	SVM Code Input



Technical Service Bulletin

Q3	1	2Q0980653B	1202	2Q0980653C	1304	A5A015A
	2					A5A015B

Restore the function activations using ODIS via Special functions >> SVM Activations >> Restore existing activations.

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9638		
Damage Code:	0039		
Labor Operations:	Software Update (Includes checking for DTCs)	0151 0000	Time stated on the diagnostic protocol (Max 75 TU)
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2064361/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information



Technical Service Bulletin

All parts and service references provided in this TSB (2064361) are subject to change and/or removal.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.