

E-Hybrid OBC Fault B200000 DTC E11C11 "Function restriction"

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Cayenne	2021	E-Hybrid and Turbo S E-Hybrid, All Variants	N/A	KB2 - 7.2 kW On-board Charger
Panamera	2021	E-Hybrid and Turbo S E-Hybrid, All Variants	N/A	KB2 - 7.2 kW On-board Charger

Revision History

Revision	Release Date	Changes
0	February 16, 2022	Original document
1	April 29, 2022	Content update

Condition

The customer reports the Check Engine Light (CEL) / Malfunction Indicator Light (MIL) is illuminated. The complaint may follow HV Battery charging. The 7.2 kW On-Board Charger (OBC) has stored Fault Code B200000, DTC E11C11 "Function restriction" (Figure 1).




Figure 1

Technical Background

An internal fault in the OBC, OBC control unit, or OBC software leads to repeat occurrences of the condition in affected vehicles. Charging of the high-voltage battery is no longer possible with this fault code present. This topic is currently under analysis for the affected vehicles.

Service Information

This topic remains under analysis for the affected vehicles at this time.

If no other fault codes or issues are identified in the vehicle, then the OBC can be programmed to erase the subject fault and switch off the MIL. This is not a permanent solution, but a temporary measure in lieu of replacing the OBC.

The OBC software in affected vehicles can be reprogrammed using **PT3G v40.900.050 (or higher) and a campaign code input via Additional Menu [F7] --> Campaign.**

Campaign Code **E3S3U** (re)programs software version 1183 in subject Cayenne E-Hybrid OBCs.

Campaign Code **G2S3U** (re)programs software version 1183 in subject Panamera E-Hybrid OBCs.

Following reprogramming of the OBC, erase all fault codes and verify normal vehicle operation.

OBC software version 1183 is also prescribed to remedy an error in software version 1177 that causes Fault Code U112100 DTC D1211D "Data bus - missing message". Please refer to Advanced Technical Information (ATI) #2202, 2021 E-Hybrid OBC Fault U112100 DTC D1211D "Data bus - missing message" for information specific to that fault code.

Warranty

Please document customer complaint cases and attach vehicle analysis logs to corresponding complaint lines in PCSS/PQIS.

Cause location: 27970 High-voltage charger

Cause symptom: 1134 Prgramming Error

Search Items

E-hybrid, Cayenne, Panamera, OBC, B200000, function restriction, E11C11

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.