



Service Campaign T3G & Warranty Extensions TXXC/TXXI - ENGINE BEARING INSPECTION / ENGINE REPLACEMENT- Dealer Best Practice

Revised publication April 15, 2022

Highlights

- A Warranty Prior Approval (PA) must be submitted on all applicable vehicles that exhibit the conditions outlined within this best practice document. PA will provide detailed confirmation of engine approval or denial based on all available case details and applicability of any related terms.
- The T3G Service Procedure TSB (# 22-01-033H or latest) Flowchart has been revised to remove KSDS prerequisite (Service Campaign 953) and includes conditions of Check Engine warning lamp illuminated with DTC P1326 and/or abnormal noise or no crank/no start condition related to connecting rod bearing wear or damage.
- Warranty Extension TXXC has been revised to include all models outlined in this Best Practice.
- Warranty Extension TXXI includes all models outlined in this Best Practice with exception of 2019MY Veloster N and clarifies PA submittal requirements.

Contents

<u>Campaign Overview</u>	2
<u>Readiness</u>	2
<u>Warranty Information</u>	3
<i>Before Proceeding with T3G</i>	4
<i>Prior Approval (PA)</i>	4
<i>PA Submission Examples</i>	6
<i>Warranty Claim Submission</i>	9
<u>Service Actions</u>	10
<u>Service Process Worksheet</u>	12
<u>Special Service Tools</u>	13
<u>Parts</u>	14
<u>Key Contact Information</u>	15

Overview

Description:

Certain vehicles with 2.0L T-GDI and 2.4L GDI engines may experience the Check Engine warning lamp illuminated with DTC P1326 and/or engine may exhibit abnormal noise or no crank/no start condition related to connecting rod bearing wear or damage. This Dealer Best Practice outlines the service procedure to inspect the vehicle and replace the engine or update the engine ECU software based on the inspection results, as well as related warranty coverage for the conditions outlined above.

Applicable Vehicles:

- Certain 2011-2014 MY Sonata (YF) Theta II vehicles with 2.0L Turbo and 2.4L GDI engines
- Certain 2015-2019 MY Sonata (LF) Theta II vehicles with 2.0L Turbo and 2.4L GDI engines
- Certain 2013-2018 MY Santa Fe Sport Theta II (AN) vehicles with 2.0L Turbo and 2.4L GDI engines
- Certain 2019 MY Santa Fe (TM) Theta II vehicles with 2.0L Turbo and 2.4L GDI engines
- Certain 2014-2015 MY Tucson (LM) Theta II vehicles with 2.4L GDI engines
- Certain 2018-2019 MY Tucson (TL) Theta II vehicles with 2.4L GDI engines
- Certain 2019 MY Veloster N (JSN) Theta II vehicles with 2.0L Turbo GDI engines

PLEASE NOTE:

- If a customer alleges to have experienced a fire related concern with their vehicle, please have them contact Consumer Affairs at 1-800-633-5151.

Readiness Checklist

The following items should be completed prior to performing TSB work:

Training:

- Training requirements recommended for Level of Technician Certification and/or Completed Coursework to perform TSB work:
 - Minimum Certified Level Certification
 - Successful completion of the Engine Technology - Classroom (#SVCET28_208) or the Engine Tech vILT Final Exam - Web (#SVCDENGVILTEXTW20_865) Course
- Ensure the entire team completes the “Engine Support” training course on HLP.

Special Service Tools:

- Ensure your dealer has all necessary Special Service Tools to perform campaign (see TSB # 22-01-033H or latest revision).

Shop Requirements:

- Ensure your dealer’s shop is configured properly to use SST bearing clearance tester.
- Confirm the following pressures meet requirements. The correct ranges for VC/AP air pressures are also indicated with red/blue decals on the gauges:
 - Shop air supply: 0.36MPa (50psi) minimum
 - AP: 0.1 ~ 0.11 MPa
 - VC: -73 ~ -83Kpa

- Bearing Tool SST Power Check
 - Supply 12 volts (or an alternate external AC/DC 13.8 volt power supply with at least ~2 amp output) to the power cable connected to the bearing tool SST.

Warranty Information

Warranty Extension:

The warranty coverage for engine long block repair or replacement regarding engine damage or malfunction from connecting rod bearing wear has been extended under Warranty Extensions TXXC & TXXI. Certain conditions may apply to each; However, a Warranty Prior Approval (PA) must be submitted on all applicable vehicles that exhibit the conditions outlined within this best practice document.

NOTICE

A Warranty Prior Approval (PA) must be submitted on all applicable vehicles that exhibit the conditions outlined within this best practice document. PA will provide detailed confirmation of engine approval or denial based on all available case details and applicability of any related terms.

- **Warranty Extension TXXC** (TSB 22-EM-002H-1 or latest revision): 10 years or 120,000 miles
 - Includes all applicable models outlined in this Dealer Best Practice
- **Warranty Extension TXXI** (TSB 22-EM-001H-1 or latest revision): Limited Lifetime
 - Includes all applicable models outlined in this Dealer Best Practice except does not include 2019 MY Veloster N (JSN) Theta II vehicles



Before Proceeding with T3G, TXXC or TXXI:

Make sure to confirm diagnosis meets warranty eligibility requirements relating to the conditions outlined within this document. If a vehicle is brought in for an engine condition unrelated to T3G (e.g. oil consumption), please follow the proper engine diagnosis procedures, and refer to standard warranty policies and procedures.

Prior Approval (PA):

A Warranty Prior Approval (PA) must be submitted on all applicable vehicles that exhibit the conditions outlined within this best practice document. PA will provide detailed confirmation of engine approval or denial based on all available case details and applicability of any related terms.

If during the engine diagnosis or repair process, there is evidence of a fire or other components are in need of replacement due to fire, please disclose all affected parts to PA as part of the engine PA review process and await further direction prior to proceeding with repairs.

Use STUI on the GDS to take and submit pictures and videos as required while following the steps outlined in the T3G TSB. A camera icon within the TSB flowchart indicates photos/videos are required for PA review.

Flow Chart: MAIN

NOTE: Icon indicates photos/videos required for PA review. Any STUI pictures require the VIN clearly visible in the photo. Use copy of RO or last 6-digits of VIN on paper.



Prior Approval Submission Documentation:

- ❖ Refer to chart on next page for items needed for submissions based on condition.

Prior Approval Submission Documentation

	No Oil On Dipstick w/ Drained Engine Oil Measured Less Than 1.5 Quarts	External Damage or Cannot Rotate Crankshaft @94lb-ft	Bearing Clearance Test (BCT) "No Pass"	Bearing Clearance Test "Pass" with Engine Knocking Concern	Bearing Clearance Test "No BCT" Result w/ Additional Steps
Repair Order	✓	✓	✓	✓	✓
Engine Diagnosis Worksheet	✓	✓	✓	✓	✓
Towing Invoice	<i>If Applicable</i>	<i>If Available</i>	<i>If Available</i>	<i>If Applicable</i>	<i>If Applicable</i>
GDS DTC Freeze Frame Screen Print	✓	✓	✓	✓	✓
One Bearing Test Result Uploaded	N/A	N/A	✓	✓	✓
BCT Calibration Photo	N/A	N/A	✓	✓	✓
Photo of Oil Dipstick	✓	✓	✓	✓	✓
Photo of Oil Cap	✓	✓	✓	✓	✓
Photo of Oil Fill Hole	✓	✓	✓	✓	✓
Photo of Oil Drain Measurement	✓	<i>If No External Damage and No Oil On Dipstick</i>	<i>If No Oil On Dipstick</i>	<i>If No Oil On Dipstick</i>	<i>If No Oil On Dipstick</i>
Crank Rotation Video	N/A	<i>If Crankshaft Cannot Rotate</i>	N/A	N/A	N/A
Engine Noise Video	N/A	N/A	N/A	✓	N/A
Photo of Cylinder Block Damage	N/A	<i>If Applicable</i>	N/A	N/A	N/A
"No BCT" Error Code	N/A	N/A	N/A	N/A	✓
STUI Video of Skipped Cylinder Test	N/A	N/A	N/A	N/A	Per "No BCT" Result → AP/VC or Compression measurement
Copy of Maintenance Records	<i>If Requested by PA</i>	<i>If Requested by PA</i>	<i>If Requested by PA</i>	<i>If Requested by PA</i>	<i>If Requested by PA</i>
Photo of Valvetrain	<i>If Requested by PA</i>	<i>If Requested by PA</i>	<i>If Requested by PA</i>	<i>If Requested by PA</i>	<i>If Requested by PA</i>
Photo of Accident Damage	<i>If Applicable</i>	<i>If Applicable</i>	<i>If Applicable</i>	<i>If Applicable</i>	<i>If Applicable</i>


Proper Photos / Videos:

- ❖ VIN in view when photo is taken of the item in question. (**Windshield or doorjamb VIN Plate**)
 - **Exception:** For oil Measurement photo, a Repair Order in photo will suffice.
- ❖ Photo taken with clear focus, showing the item being presented.
- ❖ BCT Connection Calibration Test - show connections and gauges clearly (up to two photos)
- ❖ Crank Rotation Video, Engine Noise Video, Skipped Cylinder AP/VC checking, or Skipped


PA Submission Examples

The following are good and bad examples of pictures and video PA documentation submissions.

Good Dipstick Photo (see below)



Example 1




Example 2

Bad Dipstick Photo (see below)



Good Oil Drain Photo (see below)



Bad Oil Drain Photo (see below)



Example 1




Example 2



Example 3

Good Oil Cap and Valvetrain Photos (see below)



When submitting a picture of the oil cap, please include it with a picture of the repair order showing the last 6 digits of the VIN as seen below

<p>HYUNDAI MOTOR AMERICA</p> 			<table border="1"> <tr><td>R/O Open Date</td><td>R/O Number</td></tr> <tr><td>11/05/20</td><td>27877/1</td></tr> <tr><td>R/O Close Date</td><td>Status</td></tr> <tr><td>11/06/20</td><td>Reprint</td></tr> <tr><td>Mileage In</td><td>Mileage Out</td></tr> <tr><td>1879</td><td>1880</td></tr> <tr><td colspan="2">Service Advisor / Tag #</td></tr> </table>		R/O Open Date	R/O Number	11/05/20	27877/1	R/O Close Date	Status	11/06/20	Reprint	Mileage In	Mileage Out	1879	1880	Service Advisor / Tag #							
R/O Open Date	R/O Number																							
11/05/20	27877/1																							
R/O Close Date	Status																							
11/06/20	Reprint																							
Mileage In	Mileage Out																							
1879	1880																							
Service Advisor / Tag #																								
<p>SERVICE DEPARTMENT HOURS 7:30 a.m. to 6:00 p.m. Monday - Friday 8:00 a.m. to 4:00 p.m. Saturday</p>			<table border="1"> <tr><td>Work Phone</td><td>Vehicle Identification Number</td></tr> <tr><td></td><td>KMHSA123456789871</td></tr> <tr><td>Home Phone</td><td>Delivery Date</td></tr> <tr><td>657-265-3316</td><td>In-Service Date</td></tr> <tr><td>Body</td><td>Color</td></tr> <tr><td></td><td>License Number</td></tr> </table>		Work Phone	Vehicle Identification Number		KMHSA123456789871	Home Phone	Delivery Date	657-265-3316	In-Service Date	Body	Color		License Number								
Work Phone	Vehicle Identification Number																							
	KMHSA123456789871																							
Home Phone	Delivery Date																							
657-265-3316	In-Service Date																							
Body	Color																							
	License Number																							
Year	Make	Model																						
2020	HYUNDAI	SANTA FE HEV																						
				AMOUNT																				
Customer Concern:																								
#1 - Check Engine Light is on																								
Oil filler cap: Clear view of cap underside		Oil filler opening: Clear view inside opening.																						
																								
<p><small>TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle here as described on slips, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repair hereof.</small></p> <p><small>DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitations on this herein does not apply where prohibited by law.</small></p>																								
<table border="1"> <tr><td>LABOR</td><td></td></tr> <tr><td>PARTS</td><td>.00</td></tr> <tr><td>DEDUCTIBLE</td><td>.00</td></tr> <tr><td>SUBLET</td><td>.00</td></tr> <tr><td>SHOP SUPPLIES</td><td>.00</td></tr> <tr><td>HAZARDOUS MATERIALS</td><td>.00</td></tr> <tr><td>SALES TAX OR TAX I.D.</td><td></td></tr> <tr><td>SPECIAL ORDER DEPOSIT</td><td></td></tr> <tr><td>DISCOUNTS</td><td>.00</td></tr> <tr><td>TOTAL DUE</td><td></td></tr> </table>		LABOR		PARTS	.00	DEDUCTIBLE	.00	SUBLET	.00	SHOP SUPPLIES	.00	HAZARDOUS MATERIALS	.00	SALES TAX OR TAX I.D.		SPECIAL ORDER DEPOSIT		DISCOUNTS	.00	TOTAL DUE				
LABOR																								
PARTS	.00																							
DEDUCTIBLE	.00																							
SUBLET	.00																							
SHOP SUPPLIES	.00																							
HAZARDOUS MATERIALS	.00																							
SALES TAX OR TAX I.D.																								
SPECIAL ORDER DEPOSIT																								
DISCOUNTS	.00																							
TOTAL DUE																								
<p>NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.</p>																								

Make sure the last 6 digits of the VIN are visible in your submission photo

Video Examples (click on link to watch)

- [Good Seized Engine Video 1](#)
- [Good Seized Engine video 2](#)
- [Bad Seized Engine Video 1](#)



Warranty Claim Submission:

- Claim Submission Training Video/QR code - <https://vimeo.com/642066125/1aec30b26a>
- **Refer to TSB #22-01-034H (or latest revision) for Campaign T3G OP Codes**
 - Note: OP Codes for engine replacement must only be used if engine replacement is deemed necessary by the service procedure in the T3G TSB, 22-01-033H or latest revision.
- **2 claims may be submitted for this campaign:**
 - 1 for the inspection portion
 - 1 for engine replacement/knock sensor portion as needed
 - An Op Code TSB with tables are available to help determine which Op Codes should be used
 - Look for the vehicle's model year, model, drive train (if applicable), and Smart Cruise Control (SCC) (if applicable)
 - Model year will determine submission on Campaign or Warranty screen in WEBDCS
 - Refer to TSB 22-01-034H for additional details on claim submission

What else you should know:

- If a **part is in need of replacement** and the failure is directly caused by Campaign T3G related engine failure, or if additional labor is required while performing Campaign T3G:
 - Submit one compiled separate claim using the same Repair Order number AND
 - Submit with 21101NTT using the engine Causal Part number associated with the T3G OP Code AND
 - Ensure part replacement and punch times are accurate and that they match the labor performed along with the service manager's signature approving the TT time.
 - For TT time best practices, refer to Hyundaidealer.com > Service Tab > Documents Library > Warranty > ATT-NTT Documentation and Claim Submission Guide
 - Note: If the part replacement does not require additional labor, follow the above steps and use the system minimum of .1 labor time with a quantity of 1.
- If a **part is found in need of replacement** while performing this campaign and the affected part (**failure not directly caused by Campaign T3G**) is still under warranty, submit a separate claim using the same Repair Order. If the affected part(s) are out of warranty, submit a Prior Approval request for goodwill consideration prior to completing the Campaign.

Service Actions



Reservation – Always check the Vehicle Information Screen in WebDCS for open campaigns and recalls, and advise the customer on time requirements.

- Make sure to check your appointment reservation settings and verify customer information. This will help reduce unplanned work and speed up the customer check in process.
- Make sure to review Blue Link alerts with DTC P1326 and reach out accordingly.
- Provide customer with transportation options such as SRC or alternative vehicle.



Readiness – Review this announcement and the accompanying FAQs with all Service and Parts staff including Reservationist/BDC. Also, complete all applicable training, check your reservation capacity settings (you can set separate capacities for every recall/campaign), confirm email addresses for campaign appointments, and that you have all necessary tools, campaign parts and shop equipment as needed.

- **Recommended Level of Technician Certification and/or Completed Coursework to perform TSB # 22-01-033H work:**
 - **Minimum Certified Level Certification**
 - **Successful completion of the Engine Technology - Classroom (#SVCET28_208) or the Engine Tech vILT Final Exam - Web (#SVCDENGVILTEXTW20_865) Course**
- Make sure to have necessary Special Service Tools to perform campaign (see latest TSB # 22-01-033H for more details).
- This campaign can possibly require additional repairs after initial inspection; make sure to prepare for unplanned work and maintain sufficient staff to keep vehicles moving through the shop.
- Print copies of the Service Process Results Worksheet available within the T3G TSB # 22-01-033H



Reception – Always check the Vehicle Information Screen in WebDCS for open campaigns and recalls, and print a copy for technicians. Provide SRC or an alternative vehicle, as needed.

- It is important to explain to each customer during the reception step of the service process what happens if their vehicle requires additional repairs after the inspection process.
- Make sure to advise customers of potential vehicle down time and provide alternative transportation such as an SRC or 3rd party rental.
 - All customers that come in with P1326 or “Engine Protection Mode” or those with 2.0L T-GDI and 2.4L GDI engines experiencing the Check Engine warning lamp illuminated with DTC P1326 and/or an engine concern/noise related to connecting rod bearing wear or damage. Additionally for those engines exhibiting Abnormal Noise or No Crank/No Start conditions should be provided an SRC or alternative 3rd Party Rental. **All SRC or Rental claims will be reimbursed regardless of PA’s decision to cover the engine replacement.**
- Do not charge diagnosis for vehicles that previously had campaign 953 performed and return to the dealership in “Engine Protection Mode” or with DTC P1326.




Repair – Always plug in the GDS before starting the repair. Make sure to complete an MPI on all vehicles and Quality Control your work.

- **Please review the TSB # 22-01-033H and service procedure flow chart thoroughly.**
- **Make sure to check through GDS that the vehicle has the latest software installed.**
- Confirm the GDS-M has the latest software update prior to plugging it in to the vehicle.
- This campaign can possibly require additional repairs. Make sure to refer to the most current TSB for all necessary steps of the repair process .
- Make sure to quality control work after repair is complete and confirm condition is resolved.
- Record the audio station presets (XM,AM,FM, etc) prior to disconnecting the battery.
- Clear DTC P1326 with engine **ON**. P1326 may reset if not cleared with the Engine **ON**.
- **NOTE: Not all vehicles will have a Check Engine light luminate or DTCs set.**
- If an engine replacement is required, PA may request dealers to perform additional steps before approving replacement. Dealers will be compensated for this additional time and such steps may include connecting the

GDS to retrieve additional information from the vehicle.

- Follow the **Service Procedure Flowchart** found in the latest TSB and update the Engine ECM if new version is available (Campaign T3G).

Service Procedure Flowchart:



- Important: If a vehicle passes the bearing inspection test, but DTC P1326 comes back on after the code is cleared, contact Techline for further assistance on diagnosing the vehicle.**
- Use the **Service Process Results Worksheet** (reference latest repair TSB) as a guide to help diagnose the vehicle. This should be used as a tool to assist.

6-Digit VIN:	Repair Order #:				
Options / Tests / Procedures	(Circle ALL Vehicle Options / Test Results / Performed Procedures That Apply)				
Vehicle Model Year	11	12	13	14	15
Vehicle Model Year	16	17	18	19	
Vehicle Model Type	SONATA		SANTA FE SPORT		
Vehicle Model Type	TUCSON		VELOSTER N		
Vehicle Engine Size	2.4L		2.0T		
Smart Cruise Control (SCC)	Yes		No		
All Wheel Drive (AWD)	Yes		No		
ECU already has KSDS Update and/or CEL ON w/ P1326	Yes		No		
External Lower End Damage To the Block	Yes		No		
Oil On Dipstick	Yes		No		
No Oil Found On Dipstick: Oil Drain Procedure Required ->	Drained Engine Oil at 1.5 Quarts (or higher)				
	Yes		No		
Crank Rotation (w/ 94 lb-ft. or less)	Yes		No		
Bearing Clearance Test Performed	Yes		No		
Bearing Clearance Test Result	BCT PASS		BCT NO PASS		NO BCT
Abnormal Engine Noise	Yes		No		
Knock Sensor Replaced (in this Repair Order)	Yes		No		
Replaced Engine (in this Repair Order)	Yes		NEW		REMAN
ECM Newly Updated* (in this Repair Order)	Yes		No		
*Submit separate 953 campaign claim	Yes		No		
Referred to HTSS Diagnostics	Yes		No		



Return – Review all completed campaign and repairs to answer any customer questions. Also, schedule the customer's next service.

- It's important to explain to each customer during the return step of the service process that the 953 Engine Improvement Campaign is still active and they should contact the dealership if any Check Engine Light is illuminated or Engine Protection Mode is activated.
- If a vehicle passes the bearing inspection test, ask your technician to print a copy of the results and present to the customer. Also, remember to inform the customer whose vehicle passed the bearing inspection test, that the vehicle has received the latest software update to monitor the health of their vehicle.



Reconnect – Follow up for customer satisfaction.



Service Process Results Worksheet: (Print copies of the form below in this page for multiple uses.)

6-Digit VIN:	Repair Order #:				
Options / Tests / Procedures	(Circle ALL Vehicle Options / Test Results / Performed Procedures That Apply)				
Vehicle Model Year	11	12	13	14	15
	16	17	18	19	
Vehicle Model Type	SONATA		SANTA FE SPORT		
	TUCSON		VELOSTER N		
Vehicle Engine Size	2.4L		2.0T		
Smart Cruise Control (SCC)	Yes		No		
All Wheel Drive (AWD)	Yes		No		
ECU already has KSDS Update and/or CEL ON w/ P1326	Yes		No		
External Lower End Damage To the Block	Yes		No		
Oil On Dipstick	Yes		No		
No Oil Found On Dipstick: Oil Drain Procedure Required →			Drained Engine Oil at 1.5 Quarts (or higher)		
			Yes	No	
Crank Rotation (w/ 94 lb-ft. or less)	Yes		No		
Bearing Clearance Test Performed	Yes	No			
Bearing Clearance Test Result	BCT <i>PASS</i>		BCT <i>NO PASS</i>	<i>NO BCT</i>	
Abnormal Engine Noise	Yes		No		
Knock Sensor Replaced (in this Repair Order)	Yes		No		
Replaced Engine (in this Repair Order)	Yes	NEW		No	
		REMAN			
ECM Newly Updated* (in this Repair Order) <small>*Submit separate 953 campaign claim</small>	Yes		No		
Referred to HTSS Diagnostics	Yes		No		

Special Service Tools (SST)

Review the Special Service Tools required starting on page 2 of TSB 22-01-033H (or latest revision).

- Engine Bearing Clearance Tester set (bearing tool)



- **Note:** the bearing tool must be accurately calibrated prior to performing the engine inspection procedure outlined in the T3G TSB. Refer to TSB 21-GI-009H (or latest revision) for the calibration procedure as needed.
- For Bearing Clearance Tester **software** related issues, contact GIT 1-888-437-0308
- For Bearing Clearance Tester **hardware** related issues, refer to HTSS: “Fix it Right’ Under Symptom “SST – Other”
- **Bearing tool warranty:**
 - 12 month warranty (does not include damage or abuse)
 - If defective:
 1. Utilize published resources to determine part needed
 2. Order applicable part listed in the T3G TSB
 3. Submit the warranty claim in Sublet as follows:
 - Use the related T3G VIN (or recent T3G VIN) in the claim
 - Use the bearing tester tool replacement part as the Causal Part
 - Use the first 5 digits of the part plus “AZZ” as the Labor Op
 - Use X1 Sublet Code
 - Attach parts invoice
 - Claim will be paid at dealer cost, no part markup and no labor
 4. Follow standard Warranty Procedure for parts retention
 5. Return the replaced/defective part to the Warranty Technical Center (WTC) by following the WTC part callback request instructions
 6. Please note: If the part failure is determined to be caused by damage or abuse, the warranty claim is subject to chargeback
- Torque Wrench Socket
- Injector Combustion Seal Ring Installer (Only needed if engine replacement is required. Refer to TSB# 19-FL-001H for detailed usage instructions)

□ 5 quart container



Individual Components of Engine Bearing Set

Please refer to [TSB # 21-EM-004H-1 \(or latest revision\)](#) – Bearing Clearance Test Service Procedure for Bearing Clearance Test SST components.

TOOL NAME	PART NUMBER	FIGURE
Engine Bearing Clearance Tester (Main Body)	KQ231-2T100QQH	
Spark Plug Rod (Connection for Clearance Gauge)	KQ231-2T101QQH (M12 type) KQ231-2T107QQH (M14 type)	
Crankshaft Rotator Tool	KQ231-2T102QQH	
Clearance Gauge	KQ231-2T103QQH	
Power Supply Cable	KQ231-2T104QQH	
Test Hose (Air Hose for Clearance Gauge)	KQ231-2T105QQH	

NOTE: Normal Warranty Applies.

Optional Tool:

Part Name	Part Number / Figure	Note
17 mm 12-Point Metric Flank Drive® Reversible Ratcheting Box/ Speed Open-End Combination Wrench	(Snap-on) SRXRM17 	For unfastening torque converter bolts to separate engine/trans between bellhousing if engine cannot rotate.

Parts

Refer to [TSB #22-01-033H \(or latest revision\)](#) for the parts required based on the vehicle inspection results.

NOTE: Use the Service Process Results Worksheet in the following page as a guide to determine the appropriate Part Number(s).

- Order the required parts based on the vehicle inspection results outlined in the Service Procedure Flowchart. (Use the Service Process Results Worksheet found on page 4 of the latest TSB as a guide to determine the appropriate part numbers.)
- Refer to [TSB # 22-01-034H \(or latest revision\)](#) for parts information.
- Consult the Hyundai Warranty Policy & Procedure to determine OE or Reman Engine usage. Please note there may not be a Reman or OE engine available in some cases.
 - In some cases, a Reman engine may not be available for certain vehicle models/model years listed in the TSB. Thus, an OE part would be used by default.

Key Contact Information

Key Contact Information		
Dealer Support	Contact Information	Description
Parts	HyundaiPartsHotline@MobisUSA.com 1-800-545-4515	Parts ordering hotline
Techline	1-800-325-6604	Vehicle Technical Support for Hyundai Dealer Technicians
Warranty HELPREP Line	1-877-446-2922	Warranty Claim questions for Hyundai Dealers
Warranty Prior Approval (PA) Center	PA@hmausa.com	Warranty Prior Approval (PA) Center for Hyundai Dealers
Xtime Technical Support	Support@xtime.com 1-866-984-6355	Assistance with Car Care Scheduling:
AutoLoop Technical Support	Support@autoloop.com 1-877-850-2010	Assistance with Car Care Scheduling:
CDK Technical Support	https://serviceconnect.support.cdk.com/	Assistance with Car Care Scheduling:
Customer Support	Contact Information	Description
Hyundai Customer Care Center (Recall/Campaign Questions)	1-855-671-3059	Customer questions or concerns related to <u>recall or service campaigns</u>
Hyundai Recall /Campaign Website	www.hyundaiusa.com/recall	Updated information related to the specific recall or service campaign
Hyundai Customer Care Center (General Questions)	1-800-633-5151	Customers general questions, <u>non-campaign related</u>
Hyundai Roadside Assistance	1-800-243-7766	Hyundai Roadside Assistance
Key Reference Information		
Name	Source	
Campaign Central	Consolidated repository of recall and service campaign dealer best practices. Located on the service tab homepage in www.HyundaiDealer.com	
Parts – Campaign Parts Management (CPM) Procedure	As applicable; www.HyundaiDealer.com > Parts > Documents Library > Campaign Parts Management	
Service Rental Car (SRC) Program	SRC Documentation: www.HyundaiDealer.com > Service tab > Documents Library > Service Rental Car TSD: www.HyundaiDealer.com > Service tab > SRC Fleet Mgmt Software Insurance: www.HyundaiDealer.com > Service tab > SRC Insurance	
Technical Service Bulletin (TSB)	www.HyundaiDealer.com > Service tab > Hyundai Tech Info	
Uncompleted Campaign VIN Listing	A listing of vehicles is located on WEBDCS> SERVICE tab> select UNCOMPLETED CAMPAIGN VIN LISTING – Dealer Stock (New, SRC, CPO, etc.) and Retailed.	
Recall Campaign Website	www.hyundaiusa.com/recall	
NHTSA Website	www.safercar.gov	