



# HYUNDAI Technical Service Bulletin

|                           |                                  |
|---------------------------|----------------------------------|
| GROUP<br><b>STEERING</b>  | NUMBER<br><b>22-ST-006H</b>      |
| DATE<br><b>April 2022</b> | MODEL(S)<br><b>Tucson (NX4A)</b> |

**SUBJECT:** MDPS ANTI-SHIMMY LOGIC UPDATE

**Description:** Certain 2022MY Tucson (NX4A) vehicles may exhibit a steering wheel shimmy at highway speeds not related to tire balance nor radial force variation (RFV). This bulletin describes the procedure to update the anti-shimmy logic in the Motor Driven Power Steering (MDPS) ECU.

### Applicable Vehicles:

- Certain 2022MY Tucson (NX4A, VINs starting with '5NM') vehicles produced from February 3, 2021 to December 6, 2021.

### GDS Information:

| System Selection: <b>MDPS</b> |   |
|-------------------------------|---|
| Event #                       | Description   |
| 814                           | NX4A STEERING WHEEL VIBRATION IMPROVEMENT W/O BRAKING |

### Warranty Information:

| MODEL         | OP CODE  | OPERATION    | OP TIME | CAUSAL PART | NATURE CODE | CAUSE CODE |
|---------------|----------|--------------|---------|-------------|-------------|------------|
| Tucson (NX4A) | 56300F29 | MDPS UPGRADE | 0.3 M/H | 56370-N9000 | I3T         | ZZ3        |

**NOTE:** Normal Warranty Applies

## NOTICE

**You must initially perform the GDS ECU Update in Auto Mode.**

- If the ECU Update starts but then fails in Auto Mode, perform the update in Manual Mode to recover.

**! WARNING**

**GDS-M Vehicle Battery Low Voltage Warning:**

When the vehicle battery is lower than 12 volts, the GDS-M will trigger a Low Battery Voltage Warning. If this Warning occurs,

**A.** Connect the battery to a fully charged battery jump pack or GR8 charger using “Power Supply Mode” to continue the software update.

**OR**

**B.** Select “BACK” to exit the SW update. Then, start the engine and idle with the headlights on for 20 minutes. Return to the SW update after charging the battery.



**Service Procedure:**

1. Perform GDS software update:
  - Refer to TSB **15-GI-001** for the detailed tablet-based Mobile GDS ECU update procedures.
2. Check for Diagnostic Trouble Codes in the **ALL** menus and erase any DTC.
3. Confirm normal vehicle operation.

**ROM ID Table:**

| MODEL | SYSTEM | PART NUMBER | ROM ID                |                       |
|-------|--------|-------------|-----------------------|-----------------------|
|       |        |             | OLD                   | NEW                   |
| NX4A  | MDPS   | 56370-N9000 | 56370-N9000 1.00 1.02 | 56300-N9100 1.00 1.00 |
|       |        |             | 56370-N9000 1.00 1.03 |                       |

**Manual Mode Password:**

| MENU                  | PASSWORD |
|-----------------------|----------|
| NX4A MDPS 56370-N9000 | 9100     |