

Release date:

Transaction No:

5/9/2022

Condition

Applicable Vehi	pplicable Vehicles								
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To				
Jetta	2019 - 2020	1.4T DGXA, DJXA	All	All	All				
Golf	2020 - 2021	1.4T DGXA	All	All	All				

Revision Table								
Instance Number	Published Date	Version Number	Reason For Update					
2065992/3	5/9/2022	01-22-02	Diagnostic Trouble code correction.					
2065992/2	3/24/22	01-22-02	Title change due to sister TB publishing.					
2065992/1	2/03/22	01-22-02	Original publication.					

Customer states there is low or no heat output from the air vents under certain cold weather conditions. This TB also proactively corrects faults listed below.



If the customer is experiencing a low/no heat output concern and the ECM part number and software level are not listed below please also check Technical Bulletin 2065975.



This software update also includes modification for: P0441 P04F0 P148D P0496 and P060C (37682) DTCs.

Technical Service Bulletin



01-22-02 - Mid Production - Update Programming Engine/Motor Control Module -J623-

Release date:

Transaction No:

5/9/2022

2065992/3

One or more of the following fault codes may be stored in the Engine Control Module (ECM) Fault Memory:

DTC	Description		
P0441	EVAP Emission Contr.Sys.Incorrect Purge Flow		
P04F0	EVAP system high pressure purge line performance		
P148D	Evaporative Emission System Leak Detection Pump		
	implausible frequency		
P0496	EVAP System High Purge Flow		
P060C (37682)	Internal Control Module Main Processor Performance		



DO NOT diagnose or replace components due to DTCs P0441, P04F0, P148D, P0496, P060C (37682) faults **before** performing the update function as explained in this bulletin.

Technical Background

Current Engine/Motor Control Module -J623- software can cause low engine heat output or may lead to various fault codes within the vehicle.

Production Solution

Improved Engine/Motor Control Module -J623- software.

Service

Update-Programming Procedure:

<u>Critical Warning</u>: The Midtronics battery charger <u>must</u> be connected to the vehicle battery for the duration of the programming, to ensure the battery state of charge remains above 12.5 volts during the update process. If the battery drops below 12.5 volts, the programming could fail which may result in damage to the control module. Control modules damaged by inadequate voltage will not be covered under the warranty policy. The technician should verify the vehicle voltage prior to starting the update process, and should monitor the voltage for the duration of the update.

The procedure may cancel itself if the hazard warning lights are not switched ON. The hazard warning lights prevent the system from switching to bus sleep mode during the update.

ODIS-Service tester should be updated to the latest GFF technical version 9.0.1 or higher and SW version 2.44.1 or higher.

Page 2 of 9 Plus attachment



Release date:

Transaction No:

5/9/2022



WARNING:

Radiator Fan(s) may cycle ON high speed during the Update Process! There is a risk that personal injury may result if contact is made with spinning fan blades.

Keep hands and all objects away from Radiator Fan(s) during Update Process!



Note:

Prior to launching the ODIS Service diagnostic applications and starting control module update process, confirm tester screen saver and power settings in accordance with Diagnostic Device Hardware & Windows® - VHW-20-02 Change Power Options After Windows®10 Upgrade. Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure. When using a VAS 6150/X or 6160/X tester in conjunction with a VAS 6154 wireless transmitter head for a flash procedure, connect a USB cable between the transmitter head and the tester. Failure to do so may lead to errors during the flash procedure.

VAS tools must only be used with their power adapters plugged in. Under no circumstances should they be used on battery power alone during the programming procedure.



TIP.

To Update-Programming using Software Version Management (SVM), **review and follow** instructions in **Technical Bulletin Instance 2014603** "Software Version Management".

The SVM process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim or action is carried out that is not explicitly stated in the Technical Bulletin.

Update the Engine Control Module using the SVM Unit code as listed in the table below:

Jetta

Model	Engine	Old Software Part No.	Old Software Version	New Software Part No.	New Software Version (or higher)	SVM Unit Code
Jetta	1.4T DGXA	04E 906 024 AG	5854 6549 6657	04E 906 024 AG	9971	4846

Page 3 of 9 Plus attachment



Release date:

5/9/2022

r		, ,		1		
			6810			
			6995			
			7295			
			7464			
			9910			
			9970			
Jetta	1.4T	04E 906 024 R	5852	04E 906 024 R	9971	4846
	DGXA		6546			
			6651			
			6808			
			6994			
			7293			
			7461			
			9907			
			9970			
Jetta	1.4T	04E 906 024	5853	04E 906 024	9971	4846
	DGXA	AF	6548	AF		
			6809			
			6993			
			7294			
			7463			
			9909			
			9970			
Jetta	1.4T	04E 906 024 C	Z720	04E 906 024 C	9971	4846
	DJXA		4214			
			6127			
			6551			
			6653			
			6812			



Release date:

Transaction No:

5/9/2022

		<u> </u>		1		Ì
			6997			
			7298			
			7462			
			9902			
			9970			
Jetta	1.4T	04E 906 024 M	Z720	04E 906 024 M	9971	4846
	DJXA		4215			
			6128			
			6550			
			6658			
			6813			
			6996			
			7299			
			7465			
			9906			
			9970			
Jetta	1.4T	04E 906 024	Z843	04E 906 024	9971	4846
	DGXA	AR	7257	AR		
			9509			
			9911			
			9970			
Jetta	1.4T	04E 906 024	Z843	04E 906 024	9971	4846
	DJXA	AS	7258	AS		
			9510			
			9912			
			9970			
Jetta	1.4T	04E 906 024	Z843	04E 906 024	9971	4846
	DJXA	AT	7259	AT		
			9511			





Release date:

Transaction No:

5/9/2022

	9913		
	9970		

Golf

Model	Engine	Old Software Part No.	Old Software Version	New Software Part No.	New Software Version (or higher)	SVM Unit Code
Golf	1.4T	04E 906 024 S	5804	04E 906 024 S	9971	4846
	DGXA		6130			
			6547			
			6655			
			6814			
			6999			
			7297			
			7467			
			9908			
			9970			
Golf	1.4T	04E 906 024 K	4204	04E 906 024 K	9971	4846
	DGXA		4393			
			4401			
			6129			
			6545			
			6652			
			6811			
			6998			
			7296			
			7466			
			9904			
			9970			



Release date:

Transaction No:

5/9/2022

Golf	1.4T DGXA	04E 906 024 AD	Z843 7256 9508 9939 9970	04E 906 024 AD	9971	4846
Golf	1.4T DGXA	04E 906 024 AC	Z843 7255 9507 9938 9970	04E 906 024 AC	9971	4846
Golf	1.4T DGXA	04E 906 024 BL	Z939 0654	04E 906 024 BL	2047	4846
Golf	1.4T DGXA	04E 906 024 BK	Z939 0655	04E 906 024 BK	2046	4846

The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.



The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.

Ensure attached ECM/TCM Tuning Form has been completed and signed by customer as required in SVM Technical Bulletin Instance 2014603.



Release date:

Transaction No:

5/9/2022

Warranty

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies
and Procedures Manual 1)

and i recording manda.							
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To		
Jetta	2019 - 2020	1.4T DGXA DJXA	All	All	All		
Golf	2020 - 2021	1.4T DGXA	All	All	All		
SAGA Coding							

Claim Type:	Use applicable Claim Type 1)				
Service Number:	Damage Code	нѕт	Damage Location (Depends on Service No.) Use applicable when indicated in Elsa (L/R)		
2470	0039				
Parts Manufacturer	Jetta, Golf			3ME ²⁾	
Labor Operation 3): (Charge Battery	27068950 = See	Elsa for latest time	e units	

Causal Part:	27068950
Labor Operation 3): Update Programming ECM Control Module	24705599 = 50 TU max
Labor Operation 3): Charge Battery	27068950 = See Elsa for latest time units

Diagnostic Time 4)

GFF Time expenditure	01500000 = Actual GFF print out	NO
Road Test	01210004 = 10 TU	YES
Technical Diagnosis	01320000 = 00 TU max.	NO

Claim Comment: Input "As per Technical Bulletin 2065992" in comment section of Warranty Claim.

Technical Service Bulletin



01-22-02 - Mid Production - Update Programming Engine/Motor Control Module -J623-

Release date:

Transaction No:

5/9/2022

2065992/3

- 1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only.
- ²⁾ Code per warranty vendor code policy.
- 3) Labor Time Units (TUs) are subject to change with ELSA updates.
- ⁴⁾ Documentation required per Warranty Policies and Procedures Manual.

Required Parts and Tools

No Special Parts required.

Tool Description	Tool No:	
Midtronics Battery Tester/Charger	GRX3000VAS	
	or	
	MTRMSP0702 battery maintainer/charger	
VAS Diagnostic Tool	VAS 6150/X & VAS 6160/X and	
	ODIS Service with current online updates	

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.



OWNER INFORMATION ABOUT CONTROL MODULE TUNING* ACKNOWLEDGEMENT AND AUTHORIZATION FOR REPROGRAMMING (REFLASHING) OF CONTROL MODULE(S)

*) "TUNING" is described as the addition of or modification of any convolkswagen vehicle to perform outside the normal parameters and sp Volkswagen Group of America / Volkswagen Group Canada.	•
Date: Dealer Number:	
Vehicle Identification Number:	
Repair Order Number:	
	Dealer stamp
I, owner or driver of the above identified	Volkswagen, confirm:
☐ "Tuning" as described above (especially power increasing modifiperformed on my vehicle.	cations) has NOT been
"Tuning" as described above has been performed on my vehicle and twere modified or installed:	the following components
TUNING was performed by (Please provide Company name and telephorto contact them):	ne number, if you wish us
I understand that if my Control Module is determined to have been tuned the tuning of the Control Module (including adverse emissions consequently VWGoA / VGC warranties.	
I am permitting an authorized Volkswagen Dealer to reflash (update) my doing so, I understand that this process will automatically overwrite (delete any tuning program that was previously installed on the Control M vehicle.	estroy) and permanently
By signing below, I fully acknowledge and understand that the tuning pro and VWGoA / VGC, will not be liable in any way for the loss of tuning da	•
Signature	of Customer