



# Preliminary Information

## PIT5688D Diagnostic Tip: Gurgle noise from Heater Core Possibly After Performing 19-NA-007

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2015 - 2022	All	All	All	All
GMC	Canyon	2015 - 2022	All	All	All	All

Involved Region or Country:	North America
Condition:	Gurgle noise from heater core, may persist after performing 19-NA-007.
Cause:	Orientation of the filler cap versus the heater core.

**NOTE: Some noise will be present from the heater core after cold start up and could last a couple minutes. This is normal.**

It can be difficult to remove the air from the heater core using the Vac N Fill method because the radiator cap and heater core are at about the same height. If the noise persists, raise the front of the vehicle with a hoist until the cap is above the cowl, add 400ml coolant to the overflow bottle, remove the radiator cap. Run the engine for an hour running the throttle up to ~1500 RPM 3 or 4 times during the hour.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation:	Description:	Labor Time:
<b>4486028</b>	<b>Purge Air From Heater Core</b>	<b>0.4 Hrs.</b>

Version History

Version	
5	
<b>Modified</b>	<b>05/20/2019 - Created on.</b> <b>09/19/2019 - Updated to add the 2020 Model Year.</b> <b>02/28/2020 Added note to text</b> <b>01/25/2021- Added 2021 Model Year</b> <b>04/27/2022- Added the 2022 Model Year.</b>

