



Technical Service Bulletin

44 TPMS message in the instrument cluster or the TPMS light is on, DTC U012700 is stored in the data bus control module

44 22 93 2065474/3 May 20, 2022. Supersedes Technical Service Bulletin Group 44 number 22-91 dated March 17, 2022, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, and A7	2019 – 2023	All	TPMS
A6 allroad, and S7	2020 – 2023		
S6, RS 6 Avant, and RS 7	2021 – 2023		

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised <i>header</i> (Added Model Year)
2	03/17/2022	Revised <i>Parts and Tools</i> (Part number change)
1	12/9/2021	Initial publication

Customer states:

- The tire pressure monitoring system (TPMS) warning light is on.

Workshop findings:

- The customer concern can be reproduced.

And

- The tire pressure monitoring system control module, J502 (address code 0065) cannot be reached with the diagnostic tester.



Technical Service Bulletin

The following DTC may be stored in the data bus on board diagnostic interface, J533 (address code 0019) as active/static:

- **DTC U012700** (Tire Pressure Monitoring Control Module - no communication) with symptom code 131595.

Technical Background

According to ambient conditions, moisture can enter the control module via the pressure equalization element; this leads to failure of the control module.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service

1. Check the wiring and pins in the connector for damage and measure the voltage supply at the tire pressure monitoring control module, J502 (address code 0065).
2. If no irregularities can be detected:
 - Replace the tire pressure monitoring system control module, J502 (address code 0065), and also fit with the new bracket, part number **4E0 810 675 B** (Figures 1 - 2).





Technical Service Bulletin

Figure 1. Installation location with standard A.



Figure 2. Installation location with new bracket.

3. Make sure that the wiring is routed correctly at the bracket and connector.



Tip: It is important for the wiring to be routed straight into the connector housing to ensure the correct s

Warranty

Claim Type:	<ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational. 		
Service Number:	4434		
Damage Code:	0040		
Labor Operations:	Remove and install Tire Pressure Monitoring System control module	4434 1900	Se as



Technical Service Bulletin

	Check Tire Pressure Monitoring System control module	4434 0199	10
	Repair Tire Pressure Monitoring System control module	4434 4199	10
Diagnostic Time:	GFF	0150 0000	Ti di (M
	Road test prior to the service procedure	No allowance	0
	Road test after the service procedure	0121 0004	10
Claim Comment:	As per TSB 2065474/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
4E0810675B	Bracket	01
See ETKA	TPMS Control Module	01

Additional Information

All parts and service references provided in this TSB (2065474) are subject to change and/or removal. ©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.