

Service Bulletin

Bulletin No.: 17-NA-222

Date: January, 2022

TECHNICAL

Subject: Information on Turbocharger Whine Noise

Brand:	Model:	Model Year:		VIN:		Engine	Transmission:
		from	to	from	to	Engine:	Transmission.
Chevrolet	Colorado	2016	2022				
	Express	2017				1.14/61	
GMC	Canyon	2016				LWN	
	Savana	2017					

Involved Region or Country	North America, Guatemala, Peru, Korea, Saudi Arabia, Israel, Thailand, Venezuela South Africa	,	
Additional Options (RPOs)	Equipped with 2.8L Diesel Engine (RPO LWN)		
Condition	Some customers may comment on a whine noise during acceleration, in gear, or Neutr		
Cause	This condition may be caused by a bent turbocharger compressor blade.		
Information	If one of the blades is bent as illustrated above, replace the turbocharger. Refer to Turbocharger Replacement in SI.	4818843	
	If none of the blades are bent, continue diagnosis referring to SI.		

Version	6
Modified	Released July 12, 2017 Revised August 24, 2017 — Added 2018 Model Years. Revised July 24, 2018 – Added 2019 Model Year. Revised September 18, 2019 – Added 2020 Model Year. Revised October 26, 2020 - Made bulletin an Informational Bulletin, Added 2021 Model Year and removed 2016 from Express and Savana. Revised January 14, 2022 — Added the 2022 Model Year.