



SIB 12 21 17

2022-04-11

ROUGH RUNNING IMMEDIATELY AFTER A COLD START

This Service Information Bulletin (Revision 3) replaces SI B12 27 17 **dated August 2021**.

What's New (Specific text highlighted):

- Defect Code updated
- Warranty Information updated

MODEL

E-Series	Model Description	Production Date	Affected Engine
F39	X2 Sports Activity Coupe	All	B46O
F48	X1 Sports Activity Vehicle	All	B46O

SITUATION

Immediately after a cold start, the engine may run roughly during the catalyst heating period.

Depending on the severity of this situation, the malfunction indicator lamp (MIL) can be illuminated and the following fault code may be set:

Fault code	Control module	Fault code text
151001	DME	Ignition angle adjustment while idle speed, cold start: ignition angle early

In some circumstances, if the vehicle is switched into a drive gear (R or D) when the RPM are low, the engine may switch off. Should this occur, the engine may be restarted normally.

CAUSE

Software error in the DME.

CORRECTION

Upgrade the vehicle software using **ISTA Next**.

PROCEDURE

For conditions that are similar to the situation described, first, determine the vehicle's current I-level by either using AIR or the Key reader/ISPA NEXT application.

1. Perform diagnosis with the latest version of ISTA.
2. Program the vehicle using **ISTA Next** to appropriate level shown below:

For 2-wheel drive vehicles (sDrive):

Model	Target integration level
F48 (X1 Sports Activity Vehicle)	F056-20-03-510 or higher
F39 (X2 Sports Activity Coupe)	

For all wheel drive vehicles (xDrive):

Model	Target integration level
F48 (X1 Sports Activity Vehicle)	F056-20-03-540 or higher
F39 (X2 Sports Activity Coupe)	

Note that ISTA will automatically reprogram and code all programmable control modules that do not have the latest software.

Always connect a BMW-approved battery charger/power supply ([SI B04 23 10](#)) when performing programming.

For information on programming and coding with ISTA, refer to DealerSpeed / TIS / Technical Documentation / Diagnostics and Programming / Programming Documentation.

WARRANTY INFORMATION

During this workshop visit, the affected vehicle may show one or more programming and encoding Technical Campaign repairs open, the programming and encoding procedure may only be invoiced one time.

Select one of these open Technical Campaigns to perform and submit for updating the vehicle's software to the required I-level or higher.

Please be sure to perform any additional before and/or after work (including attaching labels) as required by the open campaigns on the vehicle. Close any remaining open programming and encoding Campaign repairs as outlined in the corresponding Service Information Bulletin.

Only if the above situation does not apply, the BMW software solution is then:

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks, or the BMW Certified Pre-Owned Program as described below.

This repair is also covered by the terms of the Federal Emission Warranty for all affected vehicles, and when applicable, concurrently by the State-specific Emissions Warranty (dependent on the vehicle's model year and state of registration).

Defect Code:	1011000900	Cold start, combustion engine Goes out
---------------------	-------------------	---

Refer to AIR for the corresponding flat rate unit (FRU) allowances.

Labor Operation	Description	Labor Allowance
00 00 006	Performing vehicle test (with vehicle diagnosis system – checking faults) (Main work)	Refer to AIR
Or:		
00 00 556	Performing vehicle test (with vehicle diagnosis system – checking faults) (Plus work)	Refer to AIR
And:		
61 21 528	Support voltage of the vehicle electrical system / recharge vehicle electrical system battery	Refer to AIR
And		
61 00 730	Programming/encoding control unit(s)	Refer to AIR

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead of 00 00 006.

Programming and Encoding - Vehicle Control Units (RO and Claim Comments Required)

This procedure automatically reprograms and encodes any vehicle control modules that do not have the latest software I-level.

If one or more control modules fail during the reprogramming procedure, claim the required consequential repair work procedures to address this issue (including performing the IRAP Control Unit Recovery first as required, refer to the SIB in AIR) under the Defect Code in this bulletin with the labor operations in AIR that apply.

Please explain the additional work procedures that were performed (The why and the what) on the repair order and in the claim comments.

For covered repairs that address control module failures that occurred prior to performing this reprogramming procedure, claim this work with the Defect Code and labor operations (including diagnosis) in AIR that apply.

Based on which one applies to your center, please refer to **SI B01 01 20** or **B01 07 20** for claiming your diagnosis work time, job/repair work time (WT), RO/Claim WT and/or repair explanation procedures, unless otherwise required by State law.

Other Repairs

If other eligible and covered work is performed as a result of performing the ISTA diagnostics and related test plans, claim this work with the applicable Defect Code and the labor operations listed in AIR (including diagnosis).

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Submit feedback at the top of this bulletin
Warranty inquiries	Please contact the Warranty department by either using the Live Chat that's available in the Warranty Documentation Portal or through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections
Parts inquiries	Submit an IDS ticket to the Parts Department