

WNE2 - Re-Programming Instrument Cluster (Stop Delivery)

Important: **CRITICAL WARNING** -This campaign includes steps where control unit(s) in the vehicle will be programmed with the PIWIS Tester. The vehicle voltage must be maintained between 13.5 volts and 14.5 volts during this programming. Failure to maintain this voltage could result in damaged control unit(s). Damage caused by inadequate voltage during programming is not a warrantable defect. The technician must verify the actual vehicle voltage in the PIWIS Tester before starting the campaign and also document the actual voltage on the repair order.

Model Year: 2022

Model Line: Panamera (971)

Concerns: Instrument cluster

Information: **Due to the semiconductor shortages, the instrument cluster of the affected vehicles was built up with an alternative chip for audio output.**

With the current instrument cluster software, no visual error message is displayed in the instrument cluster if the new chip fails. As a result, audio output in the instrument cluster would not work and a corresponding error message will not be displayed.

Due to the possibility of failed programming, it is recommended that your dealer creates an extended logging sequence before starting programming. This can be started and stopped by using CTRL+L. In the event of failed programming, a PRMS ticket should be created as normal. Please attach the logging file to the ticket in order to help PCNA to investigate and resolve the issue.

Action required: Re-program the instrument cluster using the PIWIS Tester with software version **41.000.030** (or higher) installed.

NOTICE

Use of a PIWIS Tester software version that is older than the specified version

- Measure is ineffective
- ⇒ **Always use the prescribed version or a higher version of the PIWIS Tester software for control unit programming.**



Information

During the campaign, the instrument cluster is re-programmed and then coded **automatically**. It takes **about 60 minutes** to **program and code** the instrument cluster.

Affected Vehicles: Only the vehicles assigned to the campaign (see also PCSS Vehicle Information).

Required tools

- Tool:
- **9900 - PIWIS Tester 3** with PIWIS Tester software version **41.000.030** (or higher) installed
 - Battery charger with a current rating of **at least 90 A**, e.g. **VAS 5908 battery charger 90A**

Preliminary work

NOTICE

Fault entry in the fault memory and control unit programming aborted due to low-voltage.

- Increased current draw during diagnosis or control unit programming can cause a drop in voltage, which can result in one or more fault entries and the abnormal termination of the programming process.
- ⇒ Before starting control unit programming, connect a suitable battery charger or power supply, suitable for AGM type batteries, recommended current rating of 90A fixed voltage 13.5V to 14.5V.

NOTICE

Control unit programming will be aborted if the WLAN connection is unstable.

- An unstable WiFi connection can interrupt communication between the PIWIS Tester and the vehicle communication module (VCI). As a result, control unit programming may be aborted.
- ⇒ During control unit programming, always connect the PIWIS Tester to the vehicle communication module (VCI) via the USB cable.

NOTICE

Control unit programming will be aborted if the driver's key is not recognized

- If the driver's key is not recognized in the vehicle, programming cannot be started or will be interrupted.
- ⇒ Place the driver's key with the back facing down into the front left storage compartment in the center console to guarantee a continuous radio link between the vehicle and the driver's key.

NOTICE

Completely flat vehicle battery

- The break in communication in the vehicle system during programming causes safety-relevant functions, e.g. driving light and brake light, to be switched on automatically. This results in an increased current draw, which will run down the vehicle battery.
- ⇒ Before starting control unit programming, connect a suitable battery charger with a current rating of at least 90 A to the vehicle.

Work Procedure: 1 Carry out general preliminary work for control unit programming as described in ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'*.



Information

Programming can cause the individual customer settings to be lost. Always check these and write them down if necessary before getting started.

- 2 Check customer settings in the instrument cluster and write them down if necessary.
- 3 Connect a battery charger with a current rating of **at least 90 A** (e.g. **Battery charger 90A**) to the jump-start terminals in the engine compartment.
For instructions, see ⇒ *Workshop Manual '27061N External power connection, jump-lead starting'*

- 4 Place the driver's key with the back facing down in the front left storage compartment in the center console ⇒ *Driver's key in storage compartment*. This will guarantee an uninterrupted radio link between the vehicle and the driver's key.



Driver's key in storage compartment

- 5 Connect **9900 - PIWIS Tester 3** to the vehicle communication interface module (VCI) via the **USB cable**. Then connect the communication module to the vehicle and switch on the PIWIS Tester.
- 6 Switch on ignition.
- 7 On the PIWIS Tester start screen, call up the **'Diagnostics'** application.
The vehicle type is then read out, the diagnostic application is started and the control unit selection screen is populated.

Re-programming instrument cluster

Work Procedure: 1 **Re-programming instrument cluster.**

NOTICE

Use of a PIWIS Tester software version that is older than the specified version

- **Measure is ineffective**
- ⇒ **Always use the prescribed version or a higher version of the PIWIS Tester software for control unit programming.**



Information

The procedure described here is based on the PIWIS Tester 3 software version **41.000.030**.

The PIWIS Tester instructions take precedence and in the event of a discrepancy, these are the instructions that must be followed.

Deviations may occur with later software versions, for example.

The basic procedure for control unit programming is described in the Workshop Manual ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'*.

For specific information on control unit programming during this campaign, see table below.

Required PIWIS Tester software version:	41.000.030 (or higher)
Type of control unit programming:	Control unit programming using the 'Automatic programming' function of the instrument cluster: Instrument cluster' control unit – 'Coding/programming' menu – 'Automatic programming' function.
Programming sequence:	Read and follow the information and instructions on the PIWIS Tester during the guided programming sequence. During the programming sequence, the instrument cluster is re-programmed and then automatically re-coded . The display in the instrument cluster is switched off during programming. The ignition stays active in the background. When the programming is completed successfully, the display in the instrument cluster will be switched on again automatically. Switch the ignition off and then on again only when prompted to do so by the PIWIS Tester because otherwise, programming will be interrupted and will then have to be started again.
Programming time (approx):	55 minutes

<p>Software version programmed during this campaign:</p>	<p>Instrument cluster Software version: 0077</p> <p>Following control unit programming, the software version can be read out of the instrument cluster in the 'Incremented identification' menu using the PIWIS Tester.</p>
<p>Procedure in the event of abnormal termination of control unit programming:</p>	<ul style="list-style-type: none"> • Switch ignition off and then on again. • Read out and erase the fault memory ⇒ <i>Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - "Rework" section'</i>. • Repeat control unit programming by restarting programming.
<p>Procedure in the event of error messages appearing during the programming sequence:</p>	<p>⇒ <i>Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester - section on "Fault finding"</i>.</p>

- 2 Once programming has been carried out successfully, continue with ⇒ *Technical Information '9X00IN Concluding work'*.

Concluding work

Work Procedure: 1 Carry out general rework for control unit programming as described in ⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'*.



Information

The values for the Tire Pressure Monitoring (TPM) system may be lost during re-coding of the instrument cluster.

If the Tire Pressure Monitoring (TPM) system is reset, the wheel electronics must be re-taught and adapted to the system.

Preconditions and procedure for teaching the wheel electronics units:

- Vehicle is stationary for at least 5 minutes.
- Select the type of tires installed (type and size) in the TPM menu in the instrument cluster. The message "No monitoring. System is learning from 15 mph (25 km/h)" then appears in the multi-function display.
- Drive at a speed of more than 15 mph (25 km/h) - ideally without stopping - until the tire pressure values are displayed (learning time: less than 2 minutes).

The system learns the wheel electronics only while driving. Intermediate stops and deviations from the described teaching procedure can result in a much longer learning time.

Teaching can be performed during the test drive or later while the customer is driving. Please inform your customer about this if necessary.

- 2 Restore customer settings if necessary.
- 3 Enter the campaign in the Guarantee and Maintenance booklet.

Warranty processing



Information

The specified working times were determined specifically for carrying out this campaign and include all necessary preliminary and subsequent work.

The working time may differ from the working time published in the Labor Operation List in the PCSS.

Scope 1:

Re-programming instrument cluster

Labor time:

Re-programming instrument cluster

Labor time: **45 TU**

Includes:

- Connecting and disconnecting battery charger
- Connecting and disconnecting PIWIS Tester
- Check customer settings and restore if necessary
- Reading out and erasing fault memories

⇒ **Damage code WNE2 066 000 1**

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2022 Porsche Cars North America, Inc.